

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016905/AKA3Q2

Date: 24/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMJ5096J

Insured Vehicle No : SKJ211A

Date of Loss: 22/09/2019

Nature of Claim: TP

Claim No: 1149766775SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ5096J**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B25502850

Reg. Date: 08/03/2019 (Man. Year: 2018)

Chassis No: MRHFC5650JT002435

Colour: Blue

Odometer: 10279 km

Engine Capacity: 1597 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size:

215/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side:

Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,619.36	2,697.92	1,921.44	41.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	830.00	2,520.00	75.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,969.36	3,527.92	4,441.44	55.73
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	7,969.36	2,800.00	5,169.36	64.87
+ GST 7.00/7.00% (S\$)	557.86	196.00	361.86	64.87
Nett Amount (S\$)	8,527.22	2,996.00	5,531.22	64.87
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,403.45		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 24/09/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	663.20 FL	*663.20 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	131.80 FL	*33.00 FL
3	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	360.00 FL	*- FL
4	1		*FRONT BUMPER FOGLAMP COVER RH	Deformed	98.20 FL	*98.20 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	166.20 FL	*- FL
6	1		*FRONT GRILLE BASE	Cracked	320.00 FL	*320.00 FL
7	1		*FRONT GRILLE LOGO	Necessary	80.00 FL	*50.00 FL
8	1		*FRONT GRILLE LOGO CHROME	Cracked	190.00 FL	*190.00 FL
9	1		*HID HEADLAMP RH	Cracked	1,250.30 FL	*808.00 FL
10	1		*HEADLAMP TOP GARNISH CHROME	Not Necessary	145.60 FL	*- FL
11	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	65.90 FL	*- FL
12	1		*FRONT FENDER RH	Dented	530.00 FL	*530.00 FL
13	1		*FRONT FENDER INNER COWLING RH	Torn	120.00 FL	*120.00 FL
14	1		*FRONT FENDER SIGNAL LAMP RH	Cracked	90.00 FL	*90.00 FL
15	1		*FRONT WASHER TANK	Deformed	190.00 FL	*190.00 FL
16	1		*FRONT AIR BAG SENSOR	Cracked	230.00 FL	*230.00 FL
17	1		*FRONT DOOR RH	Not Necessary	980.50 FL	*- FL
18	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
19	1		*SET HEADLAMP CLIPS	Not Necessary	20.00 FS	*- FS
20	1		*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
21	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	20.00 FS	*20.00 FS
22	1		*SET SUPPORT PANEL TOP COVER CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,741.70	3,362.40
- List Item Discount on L Items 20.00/20.00% (\$)	1,122.34	664.48
Total Parts (\$)	4,619.36	2,697.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,500.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,500.00	400.00
3	TO CONDUCT WIRING CHECK	New	100.00	30.00
4	TO REFOCUS HEADLAMP BEAM	New	250.00	0.00
Gross Labour Cost (\$\$)			3,350.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >