

Assignee: KennethREF: 08/CTE19016906/Kgd3<sup>172</sup>

Special instruction:

## ASSIGNMENT (Office)

From (Person): chang Bangen of CTIDate/Time: 24/9/2019 @ 4:03 pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKK 26864 Insured: SLE 4567Lat Workshop m/s Heng Yap seng Tel: 9183 3008of 160 Sin Ming Drive #08-13Policy No: MPCSN30568419022 Claim No: SNM190204477002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 21/9/19  
(Client's Record)CA / REV / REP. / REV 24 HRS up?

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12:01pm @ 25/9/19 Person Contacted: Beng Vehicle IN/OUT

| Date/Time       | Action/Instruction                                                   |
|-----------------|----------------------------------------------------------------------|
|                 | <u>Estimate ✓</u>                                                    |
|                 | <u>SKK 26864-X</u>                                                   |
|                 | <u>SLE 4567L-CTE19016901/Kybz</u>                                    |
| <u>06/11/19</u> | <u>checked with Beng, he has send final bill to Kenneth's email.</u> |
|                 | <u>Fin 11 Lyn 84200 email &amp; confirmed (Red 1518935.70, 79%,)</u> |

ASS. REC. BY:

REF: C12 /

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 + 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKK 20804 Yr Regn: 08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Toy Estima c.c. 2302

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 20765 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ACR 50 7133226

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 7 mm Rear: 7 mm

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 21/9/19 D.O.I. 25/9/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to  
Est not ready

RECEIVED 08 NOV 2019

Date/Time, File Pass to?

☐ : Prel. Report

11/05/11 turn in

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trlp: 1

Survey Fee:

Transportation: S + RS. SI

Fees

Others

TOTAL

220

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

MER-TP  
4200

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 24 September 2019 4:03 PM  
**To:** Shirley  
**Cc:** assignments  
**Subject:** RE: Your Ref: SLE 4567 L Our Ref: TKS/H434-ACC-42549.19/sl (SKK 2686 U)

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Shirley [mailto:shirley.loh@ksteoptr.com]  
**Sent:** Tuesday, September 24, 2019 3:25 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** FW: Your Ref: SLE 4567 L Our Ref: TKS/H434-ACC-42549.19/sl (SKK 2686 U)

Dear Boon Sen,

We refer to your letter dated 24/9/19.

Our client has agree to the usage of Kenneth Kong from LKK as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Kenneth Kong from LKK to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards  
Shirley  
Teo Keng Siang LLC

Tel: 6333 4222 ext 59

---

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]  
**Sent:** Tuesday, September 24, 2019 3:00 PM  
**To:** Shirley <[shirley.loh@ksteoptr.com](mailto:shirley.loh@ksteoptr.com)>  
**Subject:** RE: Your Ref: SLE 4567 L Our Ref: TKS/H434-ACC-42549.19/sl (SKK 2686 U)

Without prejudice

Dear Sir,  
LKK  
STA  
LBS

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Shirley [<mailto:shirley.loh@ksteoptr.com>]  
**Sent:** Monday, September 23, 2019 4:31 PM  
**To:** Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Catherine Thia <[catherine.thia@sg.cntaiping.com](mailto:catherine.thia@sg.cntaiping.com)>  
**Subject:** RE: Your Ref: SLE 4567 L Our Ref: TKS/H434-ACC-42549.19/sl (SKK 2686 U)

Dear Sirs,

We refer to the above matter.

We attached herewith our letter dated 23/9/19.

Please let us have your surveyor list soon.

Thank you.

Regards  
Shirley  
Teo Keng Siang LLC  
Tel: 6333 4222 ext 59

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

# HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Vehicle No : SKK2686U  
Vehicle Model : Toyota Estima

*Not Authorized*  
*11 Sep @ 4200h*  
*Returning After Repair*

## Estimate Repair Cost

| No. | Qty   | Parts List Items                |         |                    |              |
|-----|-------|---------------------------------|---------|--------------------|--------------|
| 1   | 1     | Rear bumper                     | 822.00  | By \$              | 1,488.60 ✓   |
| 2   | 2     | Rear bumper reflectors          |         | NILUM \$           | 180.60 ✓     |
| 3   | 2     | Rear bumper side retainers      |         | NISDIT \$          | 107.20 ✓     |
| 4   | 2     | Rear bumper side brackets       |         | \$ Sm              | 144.80 X     |
| 5   | 2     | Rear bumper tow hook cover      |         | \$ Sm              | 71.20 X      |
| 6   | 1     | Rear bumper sponge              |         | \$ CM              | 69.60 ✓      |
| 7   | 1     | Rear bumper lower skirt         |         | NJP \$             | 1,150.00 X   |
| 8   | 1 set | Rear bumper clips               |         | \$ M               | 40.00 ✓      |
| 9   | 1     | Tailgate                        | 1593.00 | By \$              | 1,886.40 ✓   |
| 10  | 1     | Tailgate windscreen moulding    |         | \$ M               | 89.00 ✓      |
| 11  | 1     | Tailgate centre emblem          |         | \$ M               | 62.00 ✓      |
| 12  | 1     | Tailgate outer moulding         |         | \$ Sm              | 286.20 X     |
| 13  | 2     | Tailgate number plate lamp      |         | \$ Sm              | 71.20 X      |
| 14  | 1     | Tailgate lock                   |         | \$ M               | 398.40 ✓     |
| 15  | 1     | Tailgate lock cover             |         | \$ Sm              | 23.50 X      |
| 16  | 1     | Tailgate catch                  |         | \$ M               | 52.60 X      |
| 17  | 2     | Tailgate hinges                 |         | \$ M               | 111.80 X     |
| 18  | 2     | Tailgate absorbers              |         | \$ Sm              | 530.40 X     |
| 19  | 2     | Tailgate stopper                |         | \$ Sm              | 25.40 X      |
| 20  | 1     | Tailgate inner trim             |         | \$ M               | 586.60 X     |
| 21  | 1     | Tailgate handle                 |         | \$ Sm              | 112.40 X     |
| 22  | 1     | Tailgate keyless sensor         |         | \$ M               | 282.70 ✓     |
| 23  | 1     | Tailgate weatherstrip           | 148.05  | 148.05 M D 10.1 \$ | 296.10 50% ✓ |
| 24  | 1     | Tailgate centre lamp            |         | \$ M               | 297.30 X     |
| 25  | 1     | Rear end panel                  |         | \$ M               | 685.50 ✓     |
| 26  | 1     | Rear end panel top gamish       |         | M 10.1 \$          | 193.60 ✓     |
| 27  | 1     | Rear end panel lower gamish     |         | \$ Sm              | 152.90 X     |
| 28  | 1     | Rear spare tyre compartment     |         | \$ Sm              | 974.40 X     |
| 29  | 1     | Rear spare tyre top cover       |         | \$ Sm              | 1,243.80 X   |
| 30  | 1     | Rear floor panel trim           |         | \$ Sm              | 556.10 X     |
| 31  | 1     | Rear exhaust silencer           |         | \$ M               | 865.30 X     |
| 32  | 2     | Rear exhaust silencer mountings |         | \$ Sm              | 49.60 X      |
|     |       |                                 |         | \$                 | 13,085.20    |

## Parts Special Nett Items

|    |   |                   |             |          |               |
|----|---|-------------------|-------------|----------|---------------|
| 33 | 1 | Rear number plate |             | \$ Sm    | 60.00 X       |
| 34 | 1 | Reverse sensor    |             | Short \$ | 800.00 2000 ✓ |
|    |   |                   | Total       | \$       | 920.00        |
|    |   |                   | Total Parts | \$       | 14,005.20     |

Labour

|   |                                                                                                                                |                         |     |
|---|--------------------------------------------------------------------------------------------------------------------------------|-------------------------|-----|
| 1 | Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts. | \$ 2,800.00             | 700 |
| 2 | To putty and respray painting on affected areas.                                                                               | \$ 2,500.00             | 660 |
| 3 | To remove, replace rear tailgate fittings to facilitate repair.                                                                | \$ 250.00               | 80  |
| 4 | To remove, replace rear windscreen glass.                                                                                      | \$ 200.00               | 120 |
| 5 | To remove, replace reverse sensor.                                                                                             | \$ 200.00               | 50  |
| 6 | To remove, replace rear exhaust silencer.                                                                                      | \$ <del>na</del> 100.00 | X   |
| 7 | To check wiring and lightings.                                                                                                 | \$ 80.00                | 20  |

Total Labour \$ 6,130.00

Total Parts and Labour \$ 20,135.20

20,075.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19016906/KQD3N2

Date: 14/11/2019

## REFERENCE

|                              |                                               |                             |                   |                                  |
|------------------------------|-----------------------------------------------|-----------------------------|-------------------|----------------------------------|
| <b>Handling Insurer:</b>     | China Taiping Insurance (Singapore) Pte. Ltd. | <b>Policy No:</b>           | DMPCSN30568419022 |                                  |
| <b>Claimant Vehicle No :</b> | SKK2686U                                      | <b>Insured Vehicle No :</b> | SLE4567L          |                                  |
| <b>Date of Loss:</b>         | 21/09/2019                                    | <b>Nature of Claim:</b>     | TP                | <b>Claim No:</b> SNM19D204477C02 |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                                    |                              |                    |              |
|------------------------------------|------------------------------|--------------------|--------------|
| <b>Reg No:</b>                     | SKK2686U                     | <b>Engine No:</b>  | 2AZ4A49985   |
| <b>Make &amp; Model:</b>           | TOYOTA ESTIMA, 2.4 (A)       | <b>Chassis No:</b> | ACR507133226 |
| <b>Reg. Date:</b>                  | 22/08/2017 (Man. Year: 2016) | <b>Odometer:</b>   | 26765 km     |
| <b>Colour:</b>                     | Metallic Black               |                    |              |
| <b>Engine Capacity:</b>            | 2362 cc                      |                    |              |
| <b>Market Value/New Car Price:</b> | N/A                          |                    |              |
| <b>Sum Insured (S\$):</b>          | Market Value/New Car Price   |                    |              |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                                 |                                |     |                                 |     |
|---------------------------------|--------------------------------|-----|---------------------------------|-----|
| <b>General Condition:</b>       | <b>Steering (Serviceable):</b> | Yes | <b>Footbrake (Serviceable):</b> | Yes |
| <b>Handbrake (Serviceable):</b> | <b>Engine Modification:</b>    | No  | <b>Pre-accident Condition:</b>  |     |

## CONDITION OF TYRES

|                          |               |                         |               |
|--------------------------|---------------|-------------------------|---------------|
| <b>Front Tyre Size:</b>  | 235/50R18     | <b>Rear Tyre Size:</b>  | 235/50R18     |
| <b>Front Left Side:</b>  | Michelin 7 mm | <b>Rear Left Side:</b>  | Michelin 7 mm |
| <b>Front Right Side:</b> | Michelin 7 mm | <b>Rear Right Side:</b> | Michelin 7 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                          | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 13,945.20        | 3,632.82        | 10,312.38        | 73.95        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 6,130.00         | 1,630.00        | 4,500.00         | 73.41        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>20,075.20</b> | <b>5,262.82</b> | <b>14,812.38</b> | <b>73.78</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>4,200.00</b> |                  |              |
| <b>Nett Amount (S\$)</b>                 | <b>20,075.20</b> | <b>4,200.00</b> | <b>15,875.20</b> | <b>79.08</b> |

## INSPECTION

|                            |            |                      |                                |
|----------------------------|------------|----------------------|--------------------------------|
| <b>Date of Assignment:</b> | 27/09/2019 | <b>Inspected At:</b> | Heng Yap Seng Auto Services    |
| <b>Date Inspected:</b>     | 25/09/2019 |                      | 160 Sin Ming Auto City, #08-13 |
|                            |            |                      | Singapore 575722               |

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 14 Nov 2019)                                                                                                                                |
| <b>Parts:</b> M1-MPV                                         | TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                      |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SKK2686U) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *                                                                                                      |

## Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition           | Repairer's | Amount       |
|-----|-----|----------|----------------------------------|---------------------|------------|--------------|
| 1   | 1   |          | *REAR BUMPER                     | Bent                | 1,488.60 F | *822.00 FL   |
| 2   | 1   |          | *REAR BUMPER REFLECTORS          | N/s Cracked         | 180.60 F   | *90.30 FL    |
| 3   | 1   |          | *REAR BUMPER SIDE RETAINERS      | N/s Distorted       | 107.20 F   | *53.60 FL    |
| 4   | 2   |          | *REAR BUMPER SIDE BRACKETS       | Serviceable         | 144.80 F   | *-FL         |
| 5   | 2   |          | *REAR BUMPER TOW HOOK COVER      | Serviceable         | 71.20 F    | *-FL         |
| 6   | 1   |          | *REAR BUMPER SPONGE              | Cracked             | 69.60 F    | *69.60 FL    |
| 7   | 1   |          | *REAR BUMPER LOWER SKIRT         | No such part        | 1,150.00 F | *-FL         |
| 8   | 1   |          | *SET REAR BUMPER CLIPS           | Necessary           | 40.00 F    | *40.00 FL    |
| 9   | 1   |          | *TAILGATE                        | Bent                | 1,886.40 F | *1,593.00 FL |
| 10  | 1   |          | *TAILGATE WINDSCREEN MOULDING    | Necessary           | 89.00 F    | *89.00 FL    |
| 11  | 1   |          | *TAILGATE CENTRE EMBLEM          | Necessary           | 62.00 F    | *62.00 FL    |
| 12  | 1   |          | *TAILGATE OUTER MOULDING         | Serviceable         | 286.20 F   | *-FL         |
| 13  | 2   |          | *TAILGATE NUMBER PLATE LAMP      | Serviceable         | 71.20 F    | *-FL         |
| 14  | 1   |          | *TAILGATE LOCK                   | Dented              | 398.40 F   | *398.40 FL   |
| 15  | 1   |          | *TAILGATE LOCK COVER             | Serviceable         | 23.50 F    | *-FL         |
| 16  | 1   |          | *TAILGATE CATCH                  | Repair              | 52.60 F    | *-FL         |
| 17  | 2   |          | *TAILGATE HINGES                 | Repair              | 111.80 F   | *-FL         |
| 18  | 2   |          | *TAILGATE ABSORBERS              | Serviceable         | 530.40 F   | *-FL         |
| 19  | 2   |          | *TAILGATE STOPPER                | Serviceable         | 25.40 F    | *-FL         |
| 20  | 1   |          | *TAILGATE INNER TRIM             | Serviceable         | 586.60 F   | *-FL         |
| 21  | 1   |          | *TAILGATE HANDLE                 | Serviceable         | 112.40 F   | *-FL         |
| 22  | 1   |          | *TAILGATE KEYLESS SENSOR         | Dented              | 282.70 F   | *282.70 FL   |
| 23  | 1   |          | *TAILGATE CENTRE LAMP            | Serviceable         | 297.30 F   | *-FL         |
| 24  | 1   |          | *REAR END PANEL                  | Bent                | 685.50 F   | *685.50 FL   |
| 25  | 1   |          | *REAR END PANEL TOP GARNISH      | Mtg Distorted       | 193.60 F   | *193.60 FL   |
| 26  | 1   |          | *REAR END PANEL LOWER GARNISH    | Serviceable         | 152.90 F   | *-FL         |
| 27  | 1   |          | *REAR SPARE TYRE COMPARTMENT     | Serviceable         | 974.40 F   | *-FL         |
| 28  | 1   |          | *REAR SPARE TYRE TOP COVER       | Serviceable         | 1,243.80 F | *-FL         |
| 29  | 1   |          | *REAR FLOOR PANEL TRIM           | Serviceable         | 556.10 F   | *-FL         |
| 30  | 1   |          | *REAR EXHAUST SILENCER           | Repair              | 865.30 F   | *-FL         |
| 31  | 2   |          | *REAR EXHAUST SILENCER MOUNTINGS | Serviceable         | 49.60 F    | *-FL         |
| 32  | 1   |          | *TAILGATE WEATHERSTRIP (50%)     | Dented/Distorted    | 296.10 FS  | *148.05 FS   |
| 33  | 1   |          | *REAR NUMBER PLATE               | Serviceable         | 60.00 FS   | *-FS         |
| 34  | 1   |          | *REVERSE SENSOR                  | Shorted (1 Pc only) | 800.00 FS  | *200.00 FS   |

(4 Pcs)

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>13,945.20</b> | <b>4,727.75</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b> | <b>0.00</b>      | <b>1,094.93</b> |
| <b>Total Parts (\$\$)</b>                                 | <b>13,945.20</b> | <b>3,632.82</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                                                                             | Lab.Type | Repairer's      | Amount          |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                                                                                                         |          |                 |                 |
| 1                        | LABOUR CHARGE TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS | New      | 2,800.00        | 700.00          |
| 2                        | TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS                                                                         | New      | 2,500.00        | 660.00          |
| 3                        | TO REMOVE,REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR                                                           | New      | 250.00          | 80.00           |
| 4                        | TO REMOVE,REPLACE REAR WINDSCREEN GLASS                                                                                 | New      | 200.00          | 120.00          |
| 5                        | TO REMOVE,REPLACE REVERSE SENSOR                                                                                        | New      | 200.00          | 50.00           |
| 6                        | TO REMOVE,REPLACE REAR EXHAUST SILENCER                                                                                 | New      | 100.00          | 0.00            |
| 7                        | TO CHECK WIRING AND LIGHTINGS                                                                                           | New      | 80.00           | 20.00           |
| Gross Labour Cost (\$\$) |                                                                                                                         |          | <b>6,130.00</b> | <b>1,630.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >