Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19016910/KBA3Q2

**Date:** 15/03/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant GBJ3531M Insured Vehicle No: SKR4499T

Date of Loss: 15/09/2019 Nature of Claim: TP Claim No: 0110946115SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBJ3531M

Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25047507B

Reg. Date: 26/03/2019 (Man. Year: 2019) Chassis No: JN1MC2E26Z0031065

Colour: White Odometer: 18199 km

Engine Capacity: 2488 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195R15X8 Rear Tyre Size: 195R15X8
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,625.80	3,625.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,820.00	390.00	17.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,835.80	5,445.80	390.00	6.68
+ GST 7.00/7.00% (S\$)	408.51	381.21	27.30	6.68
Nett Amount (S\$)	6,244.31	5,827.01	417.30	6.68
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
_				

+ Doc/Search Fee (S\$) 8.00

Nett Liability (S\$) 6,555.01

Global Sum Settlement (S\$) 6,500.00

**INSPECTION** 

Date of Assignment: 24/09/2019

Date Inspected: 02/10/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Bent	600.50 FN	*600.50 FN	
2	1		*REAR BUMPER CENTRE STEP PANEL	Bent	169.00 FN	*169.00 FN	
3	6		*REAR BUMPER CLIP	Necessary	26.40 FN	*26.40 FN	
4	1		*REAR TAILGATE	Bent	1,742.00 FN	*1,742.00 FN	
5	1		*TAILGATE INNER LOCK	Dented	261.00 FN	*261.00 FN	
6	1		*TAILGATE INNER LOCK OUTER COVER	Cracked	32.50 FN	*32.50 FN	
7	1		*TAILGATE INNER RUBBER	Cut	127.50 FN	*127.50 FN	
8	1		*TAILGATE LOGO	Necessary	59.70 FN	*59.70 FN	
9	1		*TAILGATE EMBLEM NV350	Necessary	101.30 FN	*101.30 FN	
10	1		*REAR END PANEL (INNER)	Bent	411.80 FN	*411.80 FN	
11	1		*REAR END PANEL INNER TOP MOULDING	Dented	65.30 FN	*65.30 FN	
12	1		*REAR END PANEL (OUTER)	Bent	138.50 FS	*138.50 FS	
13	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS	
14	1		*STICKER 70KM/HR	Necessary	10.00 FS	*10.00 FS	
15	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS	
F=Franchise part. S=SpcNett. N=NettItemDisc.							
				Sub Total (S\$)	3,985.50	3,985.50	
			- Nett Item Discount on N Items	10.00/10.00% (S\$) <sub>_</sub>	359.70	359.70	
				Total Parts (S\$)	3,625.80	3,625.80	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	<u>Labour Items</u>						
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00			
2	REMOVE & REFIX REAR BUMPER ,TAILGATE & ATTACHMENTS ,TAILLAMPS ,TO CUT ,WELD & RENEW REAR END PANEL (INNER & OUTER) ,KNOCKING & REPAIR REAR FLOORBOARD & REALIGN THE SAME	New	1,000.00	800.00			
3	PUTTY & RESPRAY REAR BUMPER ,TAILGATE REAR END PANEL (INNER & OUTER) ,REAR FLOORBOARD & ALL AFFECTED AREAS	New	800.00	700.00			
4	TO REWIRE ADVERTISEMENT	New	200.00	140.00			
5	RUSTPROOFING	New	90.00	60.00			
	Gross Labour Cost (S\$)		2,210.00	1,820.00			
	Report was unsubmitted duri	ng this print-out.					

< END OF ESTIMATES >