

Version:

INS. CASE OWNER:

CC3/EQ11901

6919, Epb39

LOR:

IDAC:

Surveyor:

STEVE

DOI:

ASSIGNMENT

NE/ALN

Date / Time:

NE/ALN

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 9499K

Claim No.:

minimumber

Name of Insured:

LHENG Pury Kurner

Policy No.:

Umpptu-000694

Insured Tel No.:

HP:

Make / Model:

TOYOTA

Excess Sec II :S\$

D.O.A.:

22/9/19

Place of Accident:

UE TMS PIF

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHO6005G



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHO6005G-1

SLK 9499K-1

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

445.12

(4 days)

28/11/28

Loss of Use (LOU):

S\$

-

(5 - x - days)

Loss of Income (LOI):

S\$

20.00

(50 x 4 days)

LOR only

LOU only

LOI only

LOI only

LOI only

LOI only

LOI only

[Tick only one]

GIA/LTA Search:

S\$

7.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

242.12

Global Sum S\$:

200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

200.00

Name 1:

SMRT Taxi Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

SLK
6/11
PIC

ASS. REC. BY: Steve.

REF:

EG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3.

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 6005 G

Yr Regn: 28/Jun/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c 1795

Colour

Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading

547700

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36U705768281

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R 15

R: 195/65 R 15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/09/2019

D.O.I.

24/09/2019

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

US \$ 1350. CRed \$ 3282.89/71%.

TP
09/19/2081
SLK 9499K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Emp. Sign / U/C:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wheel and (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI19016919/Epb3

Date: 25.09.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD6005G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.09.2019 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,271.36
Revised Estimate Amount	: S\$	1,439.70
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

STEVE CHEN
Licensed Appraiser

Section A - Accident Details

Registration Number	SHD6005G
Case Reference Number	TAX09/19/2051
Registration Date	28/6/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	PHA CHOON SENG
Type of Accident	Head to Rear
Accident Date and Time	22/9/2019 1:45 PM
Accident Reported Date and Time	23/9/2019 11:06 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	22/9/2019 3:28 PM
Replacement Vehicle issued?	No
Job Card Number	24103484
Special instruction to ARC, if any	TOWED \$ 40 / REAR PORTION
Prepared Date and Time	23/9/2019 8:29 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$2,553.89	\$527.76
Total Other Cost	\$836.00	\$120.00
TOTAL COST	\$4,832.89	\$1,347.76
Lump Sum Total	\$4,650.00	\$1,350.00 (L/S)
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / EQ
ARC / Surveyor Sign Off Date	24/09/2019 4:51 PM	24/09/2019 1:45 PM
Signature		
Remarks	Lump sum Repair, Take after spray.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0404	Invoice Number	
Quotation Date	22.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$300.00
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$58.00	\$40.00
Total Other Costs	\$638.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		89997-30070	ANTENNA ELECTRICAL LOWER REAR SENSOR REVERSE	0.00	\$157.40	0.00	\$0.00	Replace	Check X
				1.00	\$180.00	0.00	\$180.00	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X

	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
	76068-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
	76067-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	X
Total				\$4,046.10		\$659.70			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

659.70

-20%

527.76

+ 300.00

+ 520.00

1347.76

4s \$1350/-

Case Details

Case Reference Number : TAX/09/19/2081
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6005G

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8605-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
Accident Date and Time : 22/08/2019 05:45 AM
Vehicle Age(In Months) : 39

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
SOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	* / DO
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	* / Nec.
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	* / Nec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	* X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	* X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	* / short
One Time Key In	Main			BUMPER SIDE RETAINER RVLH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	* X SVC

Total Spare Part Cost 3,192.36

Surveyor Total 858.70

Lump Sum Discount (%) 25.00

Lump Sum Disa (%) 20

Final Spare Part Cost 2,553.89

Final Sur Total 827.76

SMART Recommendation											Surveyor Approval		
SOI Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER SEAL, RR LH	1	66.00	66.00	25.00	49.50	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	115.10	115.10	25.00	86.33	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP REAR	1	229.90	229.90	25.00	171.98	Replace	0	0	Not Give * X SVC
One Time Key In	Main			UNDER COVER SUB- ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give * X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.93	Replace	0	0	Not Give * X SVC
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.93	Replace	1	0	Repair * X R

Total Spare Part Cost	3,192.36	✓	Surveyor Total	655.70
Lump Sum Discount (%)	25.00		Lump Sum Dis (%)	20
Final Spare Part Cost	2,353.89		Final Sur Total	527.78

1641/5 3192.36

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	300	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	175.00	300	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	175.00	200	
Total:			930.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	/ Nec
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ Nec
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec
5	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ Nec
6	Main	TO WASH AND VACUUM	80.00	0	
7	Main	TOWING CHARGE	58.00	8	40 / NR
Total:			538.00	80.80	120

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,553.89	527.76
Total Labour Cost	507.00	300.00
Total Spray Painting	958.00	400.00
Other	538.00	80.00
Overall Total	4,556.89	1,307.76
Lump Sum Repair Option	-	-
Lump Sum Total	4,556.89	1,307.76
Surveyor Approved Amount		1,300.00

No of Repair Days*

Remarks

Surveyor Name

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3

Lump sum Repair, Take after spray.

STEVE CHEN

Save

Clear

Survey Date

24/09/2019

Repair day - 3 day

steve
24/9/2019

Lump Sum Repair, after spray

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6005G
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR1682850
Chassis No.:	JTDKN36U705768261
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	28 Jun 2016
First Registration Date:	28 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2024
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$22,104.00
Total Rebate Amount:	\$25,854.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Sep 2019

OK

Case Details

Case Reference Number : TAX/09/19/2081
Type of Repair : Accident Repair
Vehicle Registration Number : SHD6005G

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8605-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
Accident Date and Time : 22/09/2019 05:45 AM
Vehicle Age(In Months) : 39

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	• / DO
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	• / Nec.
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	• / Nec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	• X
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	• X
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	• / short
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	• X SVC

Total Spare Part Cost 3,192.36

Surveyor Total 659.70

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,553.89

Final Sur Total 527.76

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair	* R
Total Spare Part Cost									3,192.36	Surveyor Total			659.70	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									2,553.89	Final Sur Total			527.75	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	300	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	/ Nec
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ Nec
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec
5	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ Nec
6	Main	TO WASH AND VACUUM	80.00	0	
7	Main	TOWING CHARGE	56.00	0	
Total:			836.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,553.89	527.76
Total Labour Cost	507.00	300.00
Total Spray Painting	938.00	400.00
Other	836.00	80.00
Overall Total	4,632.89	1,307.76
Lump Sum Repair Option		
Lump Sum Total	4,650.00	1,300.00
Surveyor Approved Amount		1,300.00

No. of Repair Days*

Remarks

Surveyor Name

Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2

Lump sum Repair, Take after spray.

STEVE CHEN



Save Clear

Survey Date

24/09/2019

Repair day - 3 day

steve
24/9/2019

Lump Sum Repair, after spray

Hsiao Tong (LKKAUTO)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Friday, 1 November 2019 2:31 PM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Accident on 22/9/2019 involving SHD 6005G & SLK 9499K (EQ's insured) Our Ref: TAX/09/19/2081/lg //LKK REF: CC3/EQ19016919/Epb3

Dear Hsiao Tong,

We agreed to accept your global offer of \$2,000/-. Please let us have EQ's cheque for the said sum payable to **SMRT TAXIS PTE LTD**. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: 01/11/2019 08:02
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Subject: RE: LOD Re: Accident on 22/9/2019 involving SHD 6005G & SLK 9499K (EQ's insured) Our Ref: TAX/09/19/2081/lg //LKK REF: CC3/EQ19016919/Epb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$2,000.00(all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Su Li (LKK Auto) <suli@lkkauto.com>

Sent: Wednesday, 30 October 2019 2:08 PM

To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: FW: LOD Re: Accident on 22/9/2019 involving SHD 6005G & SLK 9499K (EQ's insured) Our Ref: TAX/09/19/2081/lg

Without Prejudice

Dear Sir / Madam,

Thank you for your email.

Please be informed that this matter is now handled by my colleague, Ms Hsiao Tong.

Hi Hsiao Tong,

FYNA, our ref CC3/EQ19016919/Epb3

Thank you.

Best Regards,

Su Li | Admin Support

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 (Ext:119) Email: SuLi@lkkauto.com | Fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) [<mailto:LeeGek@smrt.com.sg>]

Sent: Wednesday, 30 October 2019 2:06 PM

To: CS A Team; Admin A

Subject: LOD Re: Accident on 22/9/2019 involving SHD 6005G & SLK 9499K (EQ's insured) Our Ref: TAX/09/19/2081/lg

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$1350.00
Loss of Rental	\$556.40 (5 days x \$111.28)

Loss of Income	\$300.00 (5 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$2213.40

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) Police/GIA reports
- 4) Accident vehicle laid-up report
- 5) LTA search

Please be informed that our relief driver Mr Pua Choon Seng (NRIC No. Sxxxx462C) is claiming his injury and loss of income (based on his medical leave) through his own lawyer. We are claiming the loss of income (based on downtime) on behalf of our hirer Mr Snd Kay Hock (NRIC No. Sxxxx904Z).

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLK 9499K (Insd Veh)	Your Ref. No. : DM19HO02642-JG
	SHD 6005G (TP Veh)	Our Ref. No. : CC3/EQ19016919/Epb3q2
Date of Accident	22/9/2019	

Liability	100%	
Final Repair Cost	: \$ 1,350.00	
Loss of Income	: \$ 200.00	4 days
Rental (If any)	: \$ 445.12	4 days
Others:	: \$ 7.00	
	: \$	
	2,002.12	
Final Settlement Sum	: \$ 2,000.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	SMRT TAXIS PTE LTD	: \$ 2,000.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ19016919/Epb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-11-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 9499K	Veh. Inspected	SHD 6005G
Policy No.	DMPPHQ19-000694	Coverage (\$)	0.00
Claim No.	DM19HO02642-JG	Excess (\$)	0.00
Assign From		Assign Date	24/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U705768261	Colour	MAROON
Odometer	547700	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	22/09/2019	Inspection Date	24/09/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6005G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	REVERSE SENSOR (SN)	SHORTED	180.00	180.00
1	TAILGATE DOOR WEATHERSTRIP	SERVICEABLE	353.40	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY ,RR BUMPER RH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY ,RR BUMPER LH	SERVICEABLE	139.60	-
1	ANTENNA ,ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER SEAL ,RR LH	SERVICEABLE	88.90	-
1	BUMPER SEAL ,RR RH	SERVICEABLE	65.70	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	UNDER COVER SUB-ASSY,RR FLOOR	SERVICEABLE	514.50	-
1	UNDER COVER RR SHIELD	SERVICEABLE	63.90	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
			4,125.00	659.70
LABOUR				
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF TAILGATE ASY .		507.00	300.00
	SPRAY PAINT.		936.00	400.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-

Report Ref No. CC3/EQ19016919/Epb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGE.		56.00	40.00
			2,079.00	820.00
	GRAND TOTAL		6,204.00	1,479.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CC3/EQI19016919/Epb3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.