

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License

80490192H

DICKSON LIM TING CHENG

Exp Date: 23 Feb 1964
Issue Date: 23 Jul 2015

002464262C

010

DRIVER LICENSE TO BE USED FOR THE PURPOSE OF DRIVING A MOTOR VEHICLE

THIS IS A FULLY VALID DRIVER LICENSE FOR THE PURPOSE OF DRIVING A MOTOR VEHICLE

NP 228A



Insurance policy

Police Report



**SINGAPORE
POLICE FORCE**



1/20181229/0005

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470001

Report No: 1/20181229/0005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
20/12/2018 12:25

Video Report No:
1/20181228/0124

Station Duty No:

Informant's Particulars

Name of Informant: DICKSON LIM TING CHENG			Address: APT BLK 553 WOODLANDS DRIVE 24 #12-04 SINGAPORE 730553	
ID Type / ID No: NRIC NO / S9490192H			Contact No: Home/Office: 61180464	
Nationality: SINGAPORE CITIZEN			Email: dicksonlimtingcheng@gmail.com	
Sex: Male	Age: 24	Date of Birth: 23/02/1994	Type of Informant: Driver	
Race: Chinese			Language: English	
Occupation: Student			Institution / School Name: Date of Expiry:	
			Driving License Information: Class: 3	

General Information of the Accident

Type of Accident: Location: CENTRAL EXPRESSWAY	Injury: Attended by Police	Drink Drive: No	Date/Time of Accident: 20/12/2018 17:55	Type of Location: Straight Road
Weather: Clear	Road Surface: Dry	Road Speed Limit: 40 Km/h	Traffic Volume: Moderate	
Traffic Flow: One Way	Traffic Control: Not Controlled	Anyone conveyed by ambulance: Yes		
Type of Collision: Between Moving Vehicles - Head To Rear				

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM8663Y	Car	HONDA	JAZZ	Blue	Totally Damaged	2
SKM2112Z	Car	BMW	640i	Black	Damaged Seriously	1
SKQ5488U	Car	HYUNDAI	AVANTE	Grey	Damaged Seriously	1
SI 842B	Car	MINI	COOPER	Red	Damaged No Damage	1

Police Report



SINGAPORE
POLICE FORCE



12/01/18/25/2005

Police Station: 10 Canton
Traffic Police
10 Ulu Areal 4 SINGAPORE 400000
Tel No: 65470000

Report No: 12/01/18/25/2005

CONTINUATION OF REPORT

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMD30225	Car	TOYOTA	GLHR	Grey	Slightly Damaged	2
SME 1910L	Car	HYUNDAI	ELANTRA	Grey	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Driver

Name	DICKSON LIM TING CHENG	ID No.	S9490192H
Related Vehicle	SJM8663Y (Car)	Contact No.	81180464
Hospital/Clinic	CENTRAL 24 HR CLINIC (WOODLANDS)	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/12/2018	Date Discharge	28/12/2018
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Passenger

Name	ROSLIN	ID No.	NIL
Related Vehicle	SJM8663Y (Car)	Contact No.	98241051
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Driver

Name	RICK NG	ID No.	S71145225E
Related Vehicle	SKM2112Z (Car)	Contact No.	88382112
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Report



**SINGAPORE
POLICE FORCE**



150101225/005

Police Station Of Origin
Traffic Police
10 Ulu Avenue SINGAPORE 408865
Tel No: 65470000

Page 5
Report No: 150101225/005

CONTINUATION OF REPORT

Driver Name		JOSEPH CHO		ID No	S7630683305
Related Vehicle		SKQ2549RU (Car)		Contact No	9021564
Hospital/Clinic		NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment		NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL		Degree of Injury	NIL
Driver Name		JENSEN LIM		ID No	S7636548H
Related Vehicle		SI B42R (Car)		Contact No	9734384F
Hospital/Clinic		NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment		NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL		Degree of Injury	NIL
Driver Name		PAOLO		ID No	39475144
Related Vehicle		SMD30225 (Car)		Contact No	90920777
Hospital/Clinic		NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment		NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL		Degree of Injury	NIL
Driver Name		CHUA KAI PENG		ID No	S18619621
Related Vehicle		SME1910E (Car)		Contact No	93364341
Hospital/Clinic		NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment		NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL		Degree of Injury	NIL

Police Report



SINGAPORE
POLICE FORCE



12/01/12 29/005

Police Station Of Charge:

Traffic Police

101 Bras Basah Road SINGAPORE 400081

Ref No: 65470000

4 of 5

Report No: 12/01/12 29/005

CONTINUATION OF REPORT

Brief Details:

The accident occurred whilst I was traveling along CTE towards AY1 before Bukit Timah exit. I was driving a Grab Heli cab with one female Indian passenger of unknown age (whom was the only victim conveyed by ambulance to the hospital - she was suffering from a nosebleed immediately after the accident, she was in the rear seat without her seat belt on at the time of collision. My car was the 4 out of 6 car from the front. On the actual day, I believed I reported that I did indeed collide with the vehicle in front of me. I wish to emphasize that the severity of the hit should be taken into account, it was minimal (I believe the damage would have been almost insignificant but for the serious impact that happened right after that pushed my vehicle forward). The incident happened rather quickly and I believe that my version can be corroborated with my passenger (on the slight collision I had, and the following serious impact). The photo evidence should also reflect similarly, and if we contra the impact of collision from my front and back, and the collision of the vehicle I hit with the vehicle in front, it becomes clear that the damage from the collision should be mostly attributed to the fifth and last vehicle from the accident.

When I was driving, the vehicle in front of me came to a sudden abrupt stop, of which I reacted immediately by hitting my brakes hard. However, the road was slightly downward sloping at that point in time which meant that I could not completely stop in time which resulted in my slight collision, it was a momentary sigh of relief for both me and my passenger. Almost immediately, I felt a heavy impact from the back which threw both myself and my passenger forward, and before we could recover in time, another heavy impact that jolted both of us. Two distinct impact could be felt by my vehicle and I believe that such can be corroborated by the vehicles in front.

Hope that the investigation would show that but for the serious fifth and sixth collision (of which the impact can be evidenced by the back of my vehicle that was obliterated) and the relatively minor collisions from the first four vehicles, the accident would have been minor and insignificant, not anywhere near the severity that finally ensued.

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin
Traffic Police
10 Ulu Avenue 3 SINGAPORE 408865
Tel No. 65476000



20181224/005

Page 5

Doc No: 246 (1-20181224-005)

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report
Not applicable

Signature Of Interpreter
Not applicable

Officer In Charge Of Case
TP / TPHQ /
SHAHRUL NIZAM BIN SAMARRI
Contact No. 65476904

Authentication Stamp
N/A

Signature Of Informant

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time
23/12/2018 12:25

Classification Of Case

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CS18023333/ECD3S2
Date: 09/01/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC18A00017901
Claimant Vehicle No :	SME1910L	Insured Vehicle No :	SJM8663Y
Date of Loss:	28/12/2018	Nature of Claim:	TP
			Claim No: DMPC1800481H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1910L	Engine No:	G4FGJU250219
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU740285
Reg. Date:	21/09/2018 (Man. Year: 2018)	Odometer:	7861 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	31/12/2018		
Date Inspected:	02/01/2019	Inspected At:	Em Solution Pte Ltd 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2019)
Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: LKK Auto Consultants Pte Ltd/SME1910L/09/01/2019 09:27
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/SME1910L/09/01/2019 09:27. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SME1910L/09/01/2019 09:27. Not valid without Reference section.
--

< END OF ESTIMATES >

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Chua Kah Peng
c/o 160 Sin Ming Drive
#03-18/19 Sin Ming Autocity
Singapore 575722

Date : 12/02/2019

Reference No : CAS/19-02/011

General Information

Registration No. : SME 1910L
Accident Date : 28/12/2018

Particulars of Damaged Vehicle

Colour	: Grey	Make & Model	: Hyundai Elantra AD 1.6
Engine Capacity	: 1591 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 7860	Engine No.	: G4FGJU250219
Chassis No.	: KMHD841CMJU740285	Steering	: In Order
Registration Date	: 21/09/2018	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195/65R15	NEXEN	90%
L/H Front Tyre	195/65R15	NEXEN	90%
R/H Rear Tyre	195/65R15	NEXEN	90%
L/H Rear Tyre	195/65R15	NEXEN	90%

Inspection

Repairer : EM Solution Pte Ltd
160 Sin Ming Drive #03-18/19 Sin Ming Autocity, Singapore 575722

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$26,659.76
Revised Amount : \$19,300.00
Less Excess : -
Nett Total : \$19,300.00

Remarks

- (A) Survey was done on 31/12/2018
- (B) Re-survey was done on 03/01/2019
- (C) Re-survey after repair was done on 11/01/2019
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Boot lid	Dented/Buckled	1,582.10	1,582.10 /
2	1pc	Boot emblem 'H'	Necessary	32.60	32.60 /
3	1pc	Boot emblem 'Elantra'	Necessary	36.50	36.50 /
4	1pc	Boot emblem 'S'	Necessary	28.80	28.80 /
5	2pcs	Boot lamp @ \$297.80	Scratched/Cracked	595.60	595.60 /
6	2pcs	Boot licence lamp @ \$42.20	Cracked	84.40	84.40 X SK
7	1pc	Boot opening switch	Damaged	126.20	126.20 X SK
8	1pc	Boot reverse camera	Damaged	462.10	462.10 X SK
9	1pc	Boot inner lock	Bent	185.30	185.30 /
10	1pc	Boot lock striker	Bent	41.50	41.50 X SK
11	1pc	Boot lock cable	Serviceable	68.20	-
12	1pc	Boot inner trim <i>No Damaged</i>	Deformed	196.20	196.20 X Δ
13	1pc	Boot weatherstrip	Distorted	115.20	115.20 /
14	1pc	Boot hinge @ \$106.50	Bent	213.00	Δ 213.00 X R
15	2pcs	Boot stopper @ \$24.20	Necessary	48.40	48.40 X SK
16	2pcs	Rear fender inner shield @ \$69.00	Serviceable	138.00	-
17	2pcs	Rear fender inner trim @ \$280.50	Deformed	561.00	561.00 X SK
18	2pcs	Rear fender air vent @ \$68.60	Serviceable	137.20	-
19	2pcs	Rear taillamp @ \$384.50	Cracked/Broken	769.00	769.00 /
20	2pcs	Rear taillamp panel @ \$164.20	Dented	328.40	328.40 X SK
21	1pc	Rear bumper	Broken	520.60	520.60 /
22	1pc	Rear bumper diffuser	Broken	279.00	279.00 /
23	2pcs	Rear bumper reflector @ \$68.20	Cracked/Broken	136.40	136.40 /
24	1pc	Rear bumper inner sponge	Broken	120.60	120.60 /
25	1pc	Rear bumper reinforcement	Broken	341.50	341.50 /
26	2pcs	Rear bumper lower support bracket @ \$91.25	Twisted	182.50	182.50 /
27	2pcs	Rear bumper side retainer @ \$41.50	Broken	83.00	83.00 /
28	1pc	Rear bumper under cover RH	Deformed	52.60	52.60 X SK
29	1pc	Rear bumper under cover LH	Torn	81.40	81.40 /
30	2pcs	Rear bumper bracket @ \$79.40	Bent	158.80	158.80 /
31	1pc	Rear bumper exhaust heat protector	Warped	69.80	69.80 /
32	1pc	Rear end panel	Dented	451.60	451.60 /
33	1pc	Rear end panel inner garnish	Deformed	189.60	189.60 /

Constant Appraiser Services

Vehicle No : SME 1910L

Our ref : CAS/19-02/011

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>					
34	1pc	Rear floor board	Bent	380.60	380.60 ✓ 280
35	1pc	Rear floor panel	Dented/Buckled	803.90	803.90 ✓ 730
36	1pc	Rear spare wheel retainer lock	Broken	46.20	46.20 ✓
37	1pc	Rear antenna assembly smartkey	Broken	182.20	182.20 ✓
38	1pc	Rear exhaust silencer	Dented/Bent	681.60	681.60 X Svc
39	2pcs	Rear exhaust mounting @ \$28.50	Distorted	57.00	57.00 X Svc
40	1pc	Rear exhaust insulator	Warped	134.00	134.00 ✓
41	1pc	Front bonnet	Dented/Buckled	1,526.00	1,526.00 ✓ 1184
42	4pcs	Front bonnet stopper @ \$22.75	Necessary	91.00	91.00 X Svc
43	1pc	Front bonnet lock	Bent	129.00	129.00 ✓
44	1pc	Front bonnet lock cable	Serviceable	62.60	-
45	2pcs	Front bonnet hinge @ \$49.10	Bent	98.20	98.20 ✓
46	1pc	Front grille assy	Broken	460.20	460.20 ✓
47	1pc	Front grille emblem logo	Broken	34.10	34.10 ✓
48	2pcs	Front headlamp @ \$1,198.80	Broken	2,397.60	2,397.60 ✓
49	2pcs	Front headlamp lower bracket @ \$47.00	Broken	94.00	94.00 X Svc
50	1pc	Front bumper	Broken	520.60	520.60 ✓
51	1pc	Front bumper lower lid	Deformed	102.60	102.60 X Svc
52	2pcs	Front bumper fog lamp @ \$265.00	Mounting Bent	530.00	530.00 X Svc
53	2pcs	Front bumper fog lamp cover @ \$118.00	Mounting Deformed	236.00	236.00 X Svc
54	1pc	Front bumper inner sponge	Broken	129.00	129.00 ✓
55	1pc	Front bumper reinforcement	Broken	695.00	695.00 ✓
56	1pc	Front bumper undercover	Serviceable	86.20	-
57	2pcs	Front bumper retainer @ \$38.60	Broken	77.20	77.20 ✓
58	1pc	Front bumper tow hook cover	Serviceable	21.00	-
59	1pc	Front bumper lower support beam	Twisted	117.00	117.00 X Svc
60	2pcs	Front bumper day light @ \$175.00	Mounting Broken	350.00	350.00 X Svc
61	2pcs	Front fender @ \$699.00	Repair	1,398.00	-
62	2pcs	Front chassis frame bracket @ \$77.50	Bent	155.00	155.00 X Svc
63	1pc	Front support panel	Broken	949.00	949.00 ✓
64	1pc	Front support panel top cover	Broken	67.50	67.50 ✓
65	1pc	Front support panel side garnish RH	Deformed	47.00	47.00 X Svc
66	1pc	Front support panel side garnish LH	Deformed	47.00	47.00 X Svc
67	1pc	Air cleaner intake duct	Serviceable	119.20	-

Constant Appraiser Services

Vehicle No : SME 1910L

Our ref : CAS/19-02/011

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>					
68	1pc	Air con condenser	Punctured/Bent	745.00	745.00 ✓
69	1pc	Radiator assy	Bent/Twisted	681.90	681.90 ✓
70	1pc	Radiator electric fan assy	Jammed	559.00	559.00 X SVC
71	1pc	Radiator spare tank	Deformed	81.60	81.60 X SVC
72	1pc	Front no plate holder	Deformed	39.60	39.60 X SVC
				23,349.70	21,319.30
Less 20%				(4,669.94)	(4,263.86)
Sub total				18,679.76	17,055.44
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Front bumper clip	Necessary	52.00	52.00 30/ ✓
2	1set	Front bumper rivet set	Necessary	74.00	74.00 X SVC
3	1pc	Front no plate	Dented	55.00	45.00 35/ ✓
4	1set	Rear bumper clip	Necessary	50.00	50.00 30/ ✓
5	1set	Rear bumper rivet set	Necessary	65.00	65.00 X SVC
6	2sets	Rear fender inner trim clip @ \$34.00	Necessary	68.00	68.00 X SVC
7	2sets	Rear fender inner shield clip @ \$26.00	Necessary	52.00	52.00 X SVC
8	1set	Rear bootlid inner trim clip	Necessary	34.00	34.00 20/ ✓
9	1set	Rear bumper under cover clip RH	Necessary	18.00	18.00 X SVC
10	1set	Rear bumper under cover clip LH	Necessary	22.00	22.00 10/ ✓
11	1set	Rear floor panel sound proofing	Necessary	250.00	220.00 180/ ✓
12	1bot	Air con oil	Necessary	65.00	65.00 20/ ✓
13	1bot	Radiator coolant	Necessary	45.00	45.00 20/ ✓
14	1pc	Rear bootlid top spoiler	Twisted/Bent	550.00	550.00 X SVC
15	1set	Reverse sensor	Broken	250.00	220.00 200/ ✓
Sub total				20,329.76	18,635.44
<u>LABOUR & MISC. CHARGES</u>					
1		To tow accident vehicle to workshop		100.00	80.00 ✓
2		To remove, refix rear interior upholstery to assist repair		120.00	80.00 60/ ✓
3		To remove, refix reverse sensor & camera		80.00	60.00 30/ ✓
4		To remove, refix A/C condenser & refill gas		150.00	120.00 ✓
5		To checkup front / rear electrical wiring & test for any leakage		80.00	60.00 30/ ✓

Constant Appraiser Services

Vehicle No : SME 1910L

Our ref : CAS/19-02/011


S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES (CONT'D)</u>			
6		To remove, refix rear exhaust system		100.00	80.00 60/
7		To respray undercoating		300.00	200.00 50/
8		To respray painting & etc		2,400.00	2,200.00 2000/
9		Panel beating, remove & replacing above parts	4439	3,000.00	2,600.00 2000/
		Grand total		26,659.76	24,115.44
Recommended cost of lump sum repair (To its pre-accident condition)					19,300.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$19,300.00 on a contractual basis. Under normal circumstances, the repair period would be about 11 (Eleven) working days.

Yours faithfully,
Constant Appraiser Services



Lip Yung Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

P- 17,727.84

SM - 545

L - 4439

17,732.84

L/S - 14,162.27

= 14,150

10 repair days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CS3/ICS18023333/Etd3s2-1		
10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Date : 27-09-2019		
		Code : ICS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 8663Y	Veh. Inspected	SME 1910L	
Policy No.	MPC18A00017901	Coverage (\$)	0.00	
Claim No.	DMPC1800481H/JG	Excess (\$)	0.00	
Assign From	ELIZABETH CHEW	Assign Date	25/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHD841CMJU740285	Colour	SILVER	
Odometer	7861	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	6 mm	
L/H Front Tyre	195/65 R15	NEXEN	6 mm	
R/H Rear Tyre	195/65 R15	NEXEN	6 mm	
L/H Rear Tyre	195/65 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2018	Inspection Date	02/01/2019	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1910L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED / BUCKLED	1,582.10	1,582.10
1	BOOT EMBLEM 'H'	NECESSARY	32.60	32.60
1	BOOT EMBLEM 'ELANTRA'	NECESSARY	36.50	36.50
1	BOOT EMBLEM 'S'	NECESSARY	28.80	28.80
2	BOOT LAMP @ \$297.80	SCRATCHED / CRACKED	595.60	595.60
2	BOOT LICENCE LAMP @ \$42.20	SERVICEABLE	84.40	-
1	BOOT OPENING SWITCH	SERVICEABLE	126.20	-
1	BOOT REVERSE CAMERA	SERVICEABLE	462.10	-
1	BOOT INNER LOCK	BENT	185.30	185.30
1	BOOT LOCK STRIKER	SERVICEABLE	41.50	-
1	BOOT LOCK CABLE	SERVICEABLE	68.20	-
1	BOOT INNER TRIM	NO DAMAGED	196.20	-
1	BOOT WEATHERSTRIP	DISTORTED	115.20	115.20
2	BOOT HINGE @ \$106.50	TO REPAIR SEE LABOUR	213.00	-
2	BOOT STOPPER @ \$24.20	SERVICEABLE	48.40	-
2	REAR FENDER INNER SHIELD @ \$69.00	SERVICEABLE	138.00	-
2	REAR FENDER INNER TRIM @ \$280.50	SERVICEABLE	561.00	-
2	REAR FENDER AIR VENT @ \$68.60	SERVICEABLE	137.20	-
2	REAR TAILLAMP @ \$384.50	CRACKED / BROKEN	769.00	769.00
2	REAR TAILLAMP PANEL @ \$164.20	SERVICEABLE	328.40	-
1	REAR BUMPER	BROKEN	520.60	520.60
1	REAR BUMPER DIFFUSER	BROKEN	279.00	279.00
2	REAR BUMPER REFLECTOR @ \$68.20	CRACKED / BROKEN	136.40	136.40
1	REAR BUMPER INNER SPONGE	BROKEN	120.60	120.60
1	REAR BUMPER REINFORCEMENT	BROKEN	341.50	341.50
2	REAR BUMPER LOWER SUPPORT BRACKET @ \$91.25	TWISTED	182.50	182.50
2	REAR BUMPER SIDE RETAINER @ \$41.50	BROKEN	83.00	83.00

Report Ref No. CS3/ICS18023333/Etd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER UNDER COVER RH	SERVICEABLE	52.60	-
1	REAR BUMPER UNDER COVER LH	TORN	81.40	81.40
2	REAR BUMPER BRACKET @ \$79.40	BENT	158.80	158.80
1	REAR BUMPER EXHAUST HEAT PROTECTOR	WARPED	69.80	69.80
1	REAR END PANEL	DENTED	451.60	451.60
1	REAR END PANEL INNER GARNISH	DEFORMED	189.60	189.60
1	REAR FLOOR BOARD	BENT	380.60	280.00
1	REAR FLOOR PANEL	DENTED / BUCKLED	803.90	730.00
1	REAR SPARE WHEEL RETAINER LOCK	BROKEN	46.20	46.20
1	REAR ANTENNA ASSEMBLY SMARTKEY	BROKEN	182.20	182.20
1	REAR EXHAUST SILENCER	SERVICEABLE	681.60	-
2	REAR EXHAUST MOUNTING @ \$28.50	SERVICEABLE	57.00	-
1	REAR EXHAUST INSULATOR	WARPED	134.00	134.00
1	FRONT BONNET	DENTED / BUCKLED	1,526.00	1,184.00
4	FRONT BONNET STOPPER @ \$22.75	SERVICEABLE	91.00	-
1	FRONT BONNET LOCK	BENT	129.00	129.00
1	FRONT BONNET LOCK CABLE	SERVICEABLE	62.60	-
2	FRONT BONNET HINGE @ \$49.10	BENT	98.20	98.20
1	FRONT GRILLE ASSY	BROKEN	460.20	460.20
1	FRONT GRILLE EMBLEM LOGO	BROKEN	34.10	34.10
2	FRONT HEADLAMP @ \$1198.80	BROKEN	2,397.60	2,397.60
2	FRONT HEADLAMP LOWER BRACKET @ \$47.00	SERVICEABLE	94.00	-
1	FRONT BUMPER	BROKEN	520.60	520.60
1	FRONT BUMPER LOWER LID	SERVICEABLE	102.60	-
2	FRONT BUMPER FOG LAMP @ \$265.00	SERVICEABLE	530.00	-
2	FRONT BUMPER FOG LAMP COVER @ \$118.00	SERVICEABLE	236.00	-
1	FRONT BUMPER INNER SPONGE	BROKEN	129.00	129.00
1	FRONT BUMPER REINFORCEMENT	BROKEN	695.00	695.00
1	FRONT BUMPER UNDERCOVER	SERVICEABLE	86.20	-
2	FRONT BUMPER RETAINER @ \$38.60	BROKEN	77.20	77.20
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	21.00	-
1	FRONT BUMPER LOWER SUPPORT BEAM	SERVICEABLE	117.00	-

Report Ref No. CS3/ICS18023333/Etd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER DAY LIGHT @ \$175.00	SERVICEABLE	350.00	-
2	FRONT FENDER @ \$699.00	TO REPAIR SEE LABOUR	1,398.00	-
2	FRONT CHASSIS FRAME BRACKET @\$77.50	SERVICEABLE	155.00	-
1	FRONT SUPPORT PANEL	BROKEN	949.00	949.00
1	FRONT SUPPORT PANEL TOP COVER	BROKEN	67.50	67.50
1	FRONT SUPPORT PANEL SIDE GARNISH RH	SERVICEABLE	47.00	-
1	FRONT SUPPORT PANEL SIDE GARNISH LH	SERVICEABLE	47.00	-
1	AIR CLEANER INTAKE DUCT	SERVICEABLE	119.20	-
1	AIR CON CONDENSER	PUNCTURE / BENT	745.00	745.00
1	RADIATOR ASSY	BENT / TWISTED	681.90	681.90
1	RADIATOR ELECTRIC FAN ASSY	SERVICEABLE	559.00	-
1	RADIATOR SPARE TANK	SERVICEABLE	81.60	-
1	FRONT NO PLATE HOLDER	NOT NECESSARY	39.60	-
	LESS 20% DISCOUNT		-4,669.94	-3,100.12
			18,679.76	12,400.48
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	52.00	30.00
1	SET FRONT BUMPER RIVET (SN)	SERVICEABLE	74.00	-
1	FRONT NO PLATE (SN)	DENTED	55.00	35.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER RIVET (SN)	SERVICEABLE	65.00	-
2	SETS REAR FENDER INNER TRIM CLIP @ \$34.00 (SN)	SERVICEABLE	68.00	-
2	SETS REAR FENDER INNER SHIELD CLIP @ \$26.00 (SN)	SERVICEABLE	52.00	-
1	SET REAR BOOTLID INNER TRIM CLIP (SN)	NECESSARY	34.00	20.00
1	SET REAR BUMPER UNDER COVER CLIP RH (SN)	SERVICEABLE	18.00	-
1	SET REAR BUMPER UNDER COVER CLIP LH (SN)	NECESSARY	22.00	10.00
1	SET FLOOR PANEL SOUND PROOFING (SN)	NECESSARY	250.00	180.00
1	BOT AIR CON OIL (SN)	NECESSARY	65.00	20.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	45.00	20.00
1	REAR BOOTLID TOP SPOILER (SN)	SERVICEABLE	550.00	-
1	SET REVERSE SENSOR (SN)	BROKEN	250.00	200.00
			1,650.00	545.00

Report Ref No. CS3/ICS18023333/Etd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO TOW ACCIDENT VEHICLE TO WORKSHOP.		100.00	80.00
	TO REMOVE, REFIX REAR INTERIOR UPHOLSTERY TO ASSIST REPAIR.		120.00	60.00
	TO REMOVE, REFIX REVERSE SENSOR & CAMERA.		80.00	30.00
	TO REMOVE, REFIX A/C CONDENSER & REFILL GAS.		150.00	120.00
	TO CHECK FRONT / REAR ELECTRICAL WIRING & TEST FOR ANY LEAKAGE.		80.00	30.00
	TO REMOVE, REFIX EXHAUSTS SYSTEM.		100.00	60.00
	TO RESPRAY UNDERCOATING.		300.00	50.00
	TO RESPRAY PAINTING & ETC.		2,400.00	2,000.00
	PANEL BEATING, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF BOOT HINGE AND FRONT FENDER.		3,000.00	2,000.00
			6,330.00	4,430.00
	GRAND TOTAL		26,659.76	17,375.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,900.00

Report Ref No. CS3/ICS18023333/Etd3s2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.