Surveyor	
From (Person	Jan Tay Hui Ping of CT2 Date/Time: 72.9.19 11.449.m
Estimated Con	Bill to:
To Inspect Ve	STTP RESTOR RESTEVATING INVINVICS Shicle No: S1 ( 433 B Insured: P ( 5858p)
of 350 V	1911
Policy No: D	MB 1543067 871 9000 Claim No: SWM 190 204528102
Sum Insured:	
Make of Veh: (Client's Record	THE A STATE OF THE
CA / REV	REP. / REV 24 HRS  1.9.19 1.34 p.m Person Contacted: Mars 121 Vehicle INCOUT
Date/Time	Action/Instruction ( / ) Estimate
	SL( 433B - MA / CTT 19016878/ Y D.OA - 24/09/2019
	PC 5358 D - NEA / CT/ MUSTE/ Y DOA - 26/00/2019

man

Ext. PR Seen. Consistent? 'Yes or No  Ext. Papers: Gays. Rest. Yes or No  D.O.A. D.I.L. 30/09/19.  D.O.A. D.I.L. 30/09/19.  Survey held at Cycle and Carriege  Descriptions Fit (@D) OIS I NIS I LIC I Rooftep of  Valide: IN I OUT	(71				
30-9. 219  SLC 433B  Type (CT) IN Cycle   Bus   Vari   Lorry   Taxi   Prime Mover    Truck   Trailer or  SLC 433B  SLC 433B  SLC 433B  SLC 433B  SLC 433B  Truck   Trailer or  Truck   Trailer or  SLC 433B  Truck   Trailer or  Truck   Trailer or  SLC 433B  SLC 43B  SLC	can try ask adman first. U.S.	SIGNMENT			
Truck   Trailer or  SIC 433 B  Male:   Mi T Outlandor   CC 2360  Male:   M	30-9. 219	196.01	SLC 433B	201	6 April
House the series SC 433B  Vicinity Continue  Vicini	440	Type (MICID)	M.Cycle / Bus   Van / I	Lorry / Taxi / Prime Mo	ver.
Under Continued SLC 433B  Water Click & Corringe  NO 33b us road 3  Sp. Reading  T4220  Titledoc Instruct Std INTINA  Sp. Reading  Town I Fair I Poor I Burnt  Steering Inografi Jummed I Leaked I Burnt or  Brake: Inglief Jummed I Leaked I Burnt or  Modi Nil Skimil Std Arkin or  The Star E 22 \$ 5 \$ R J S  RE	O (TP )VS   TP RES   OD RES   EVA   MV   MV	Truck /	Trailer or		
Cobus Gray , AC Insured Istal NI INA  NO 330 ulp road 3  Engile  Engile  Chica  Engile  Chica  Tributor Istal NI INA  Engile  Chica  Tributor Istal NI INA  Engile  Engile  Engile  Engile  Engile  Engile  Engile  Tributor Istal NI INA  Engile		Make:	Mit outle	nder co	2360
Sp. Reading 742 0 TRadio: Instruct of Std INTINA  Tradio: Sp. Reading 742 0 TRadio: Instruct of Std INTINA  English  Chic Type 1 To Type 1 The Tradio: Instruct of Std INTINA  English  Chic Type 1 The Tradio: Instruct of Std INTINA  English  Chic Chic Type 1 The Tradio: Instruct of Std Intina  English  English  English  English  English  English  English  English  Intina  English  English  Intina  English	The state of the s	Colour			Std / NI / NA
Engile  Check  Simple For Fourth  Excess  Exce				T/Radio: Insured I	Std / NI / NA
The state of the s					
Seen Conf. Source   Pair   Poor   Burnt			JMYX TGF	3WGJ000 477	
Steering Ingrar   Jammed   Leaked   Burnt or		Gen. Cond 6	ood / Fair / Poor / Bur	nt	
Enter Show!    Consistence   C					
Modi NII (SRIIII) STD ARIIII or  Tyre Size F: 225/55 R 18.  Frieldy Condition  Friendly Condition  The Size F: 225/55 R 18.  BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  Final ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL ExnovA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / FIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / FIR / SUM/ I  TOYO / GOOD  FINAL EXNOVA / GY / FS / LIZA / MIG / OHTSU / GY / G		_			
Tyre Size: F: 225/55 R I 8.  R: 325/53 R I 8.  R					
R: 325/55 R18.  Remark: The year had commenced its repair at the time of inspection.  But or Market Views  CAC Accisent Prof.  Consistent? Yes or No  Survey hald at Cycle and Carriage  Descriptions  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  R: 325/55 R18.  BS / DUN / EX NOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM/ /  TOYO / YOKO or  France Consistent? Yes or No  Result of Market Views  CAC / PREV / PREP / 24 HRS  William / Person Contacted!  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  RECEIVED 0.2 Frame / Survey Fee  Result of Repair:  RECEIVED 0.2 Frame / Survey Fee  Result of Repair:  Result of Repair:  Result of Result	7. Operation 1.				
BS J DUN J EX NOVA J GY I FS I LIZA I MIC I OHTSU I PIR I SUMI I  TOYO I YOR ON  THE BEAR  RESAL DO ITM RESAL DO ITM  RESA	Esta/Castillas	The same			
TOYD / YCRO or  Front Consistent? Yes or No  CAC Accident Front Consistent? Yes or No  Each PRESENT Consistent? Yes or No  Each PRESENT Consistent? Yes or No  CAT PREVIOUS  THE USE OF THE CONSISTENT OF THE CONSISTENT OF THE USE OF THE CONSISTENT OF THE USE OF THE		BEIDINIE			SUMIT
Description of the Property of			75		
DAC Accident Floors  Consistent? Yes of No  DAL PR Seen  Consistent? Yes of No  DAL PR Seen  Gays Fless Yes of No  Survey held at  Cycle and Conferge  Descriptions  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  Affected by the UIC / Chassis frame / Body Structure affected due to collisis  Affected by the UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  Affected by the UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Struc	and and their all Visco			Dave	
DOA  DOA  DITE 30/09/19  DESCRIPTION  DOA  DITE 30/09/19  DOA  DITE 30/09/19  DESCRIPTION  DESCRIPTION  DOA  DITE 30/09/19  DESCRIPTION  DE			do	/	mm
Survey field at Cycle and Carriered  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis  The UIC / Chassis frame / Body Structure affected due to collisis	WEST CHARGE WITH SHALL	10.0000		V-	2 1101
Survey held at Cycle and Carriage  CA / REV / REP   14 HRS			90		
Descriptions of the controlled			· (	301	
Ferson Contacted  Ferson Contacted  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis  The UIC / Chassis frame / Body Structure effected due to collisis					U
The UIC / Chassis frame / Body Structure affected due to collision  TP China  TP China  Olizing Color Advan Gaband PP \$ 1,119.00 @ 5 days  with Mars Lu. 1997  RECEIVED 8 2 8 40 2010  Prell Report  Type Prell Report  Add Fig. Site Heap 18  Interview 18  Interview 18			spes PH I Ceap I O	S I NIS I UIO I ROUII	ep. 0.
TP Chinn  TP Chinn  Olizing Colombination  With Mars Lv. 199  RECEIVED 0 2 0 2 0 10  RECEIVED 0 2 0 10  Type I Final Report  Add Fig. Site hap 18  I thereby It has 199  Resonable III	Person Contacted		/ Chassis frame / Bo	dy Structure affected	due to collision
TP Chian  with Mass Lv. WA  RECEIVED 0 2 000 2010  Prell Report  Type I Final Report  Add For: Site hap is 1 100 100 100 100 100 100 100 100 100	Sate / Time 1 4:00m / Instruction		7.5-1111-515-313111-1-1-3-3		
RECEIVED 0 2 500 2010  Prell Report Days Of Repair:  Final Report Resurvey No. of Trip: Street Fee Temperate  Add Fee: Site has 18 19 19 19 19 19 19 19 19 19 19 19 19 19			(*:		
RECEIVED 0 2 500 2010  Prell Report Days Of Repair:  Final Report Resurvey No. of Trip: Street Fee Temperate  Add Fee: Site has 18 19 19 19 19 19 19 19 19 19 19 19 19 19				8	
RECEIVED 0 2 500 2010  Prell Report Days Of Repair:  Final Report Resurvey No. of Trip: Street Fee Temperate  Add Fee: Site has 18 19 19 19 19 19 19 19 19 19 19 19 19 19	00/12/19 Continued Adian Godin	and PP	\$ 7,119.00	@ 50	lays
Prell. Report  Final Report  Resurvey No. of Trip:  Add Fee: Site hap 18  Whiteview 18  Final Report  Add Fee: Site hap 18	with mas le-				
Prell. Report  Final Report  Resurvey No. of Trip:  Add Fee: Site hap 18  Whiteview 18  Final Report  Add Fee: Site hap 18					
Prell. Report  Final Report  Resurvey No. of Trip:  Add Fee: Site hap 18  Whiteview 18  Final Report  Add Fee: Site hap 18	RE	CEIVED	2 2018		
Add Fee: Site hap 19 1.44 30 1					
Add Fee: Site hap 19 1.40 1.00 1.00 1.00 1.00 1.00 1.00 1.00	3.5				
Add Fee: Site hap 19 19 19 19 19 19 19 19 19 19 19 19 19	: Prell. Report	Days Of Re	palr:		3.115
Add Fee: Site hap 19	Typica : Final Report	Resurvey N	o of Trip:	Survey Fee	
Misryley IX No.				Territoria	
Teaching (I	Add F	1000		_ + = _ x	
		linter.	view IF	Pine.	
\$ 1/19 00 8/8		fest		1000	
	\$ 1,119.00 P/P	100			220

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authred	Status		
Main	26 Sep 2019 Main		26 Sep 2019 11:44 Assign				New Assign Cancel Cas	And the second	
	Main	Re	ference	Clair	n Details	Docume	ents	Show All	
CLAIM S	UBFOLDER DET	TAILS				[Cre	eated by insu	rer]	
Insured: Main Clair	nant		AVEL PTE LTD,	Co. Reg. No.: 2 7532666A	01427374E				
Vehicle Reg. No.:		SLC43	338	Dat	Date of Loss:		24/09/2019 07:00 - [40 Months and 26   Reg Date (Man Yr)]		
Claim Typ	e:	TP / S	NM19D204528	CO2 Poli	Policy/Cover Note No.: D		MB1SN30678719000		
Vehicle Re	g. No. (Insured)	PC585	C5858D		Policy No. (Claimant):		5108611379		
				T Marie	rss	5\$0.00			
Repairer:			e & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3, 408650 Ubi - Tel: 67461000 na Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Irene Tay Hul						
Handling !	Insurer:		Faiping Insuranc 638986192]	e (Singapore)	Pte. Ltd. (HQ) - T	el: 6389 6111	[Handled by Ir	ene Tay Hui	
Claimant's	Insurer:		Income Insuranc					_	
Adjuster:					Tel: 6256-3561	Final Rpt due	07/10/2019	]	
Driver/Cu	stodian (Insured)	: LIU SH	ENGSHI (44 / Male	) , NRIC: G5	40886T Email:				
ASSOCIA	ATED MAIL REC	EIVED				View A	II Comp	ose Case Mail	
There are	no mail for this o	case.							
E									
	OCIATED TASK	cs			View All   Sear	ch Tasks   Ch	eate New Task	Complete	
	LET LATER TOWN		enum Subtact	Handler					
Due Da	LET LATER TOWN	Type Task 0	iroup Subject	Handler	Assigned By	Completed Or		d	

# Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto)

Sent:

Monday, 2 December 2019 3:29 pm

To:

Mars Ler

Cc:

Chris Bulaclac; Renemer Bagang; SUR

Subject:

RE: OUR REF: SNM19D204528-PC5858D-THP & YOUR REF: SLC433B - TO CONDUCT

PRS -SLC433B -Accident On 24/09/2019

Finalization & Before Paint

Dear Mars.

Confirmed final fig \$ 7,119.00 @ 5 days of repairs.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards.

Shirley Hiew | Case Handler

## LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mars Ler <mars.ler@ccfulco.com.sg> Sent: Friday, 29 November 2019 8:18 am

To: SUR <sur@lkkauto.com>

Ce: Chris Bulaclac <chris.bulaclac@ccfulco.com.sg>; Renemer Bagang <renemer.bagang@ccfulco.com.sg>;

Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: OUR REF: SNM19D204528-PC5858D-THP & YOUR REF: SLC433B - TO CONDUCT PRS -

SLC433B -Accident On 24/09/2019 Finalization & Before Paint

Dear Shirley,

Good morning, may we know do you facing any problem finalize on this case? Any enquiry please do not hesitate contact me, otherwise please kindly assist finalize.

Thank you,

Best regards

Mars Ler Senior Advisor - Motor Claims Cycle & Carriage Fulco Motor Dealer Pte Ltd 330 Ubi Road 3 Singapore 408650 D/D 65949163 H/P 91792566

### SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	24/09/2019 14:26
Date Of Accident	24/09/2019 07:10
Exact Location Of Accident	BUANGKOK GREEN TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE
D. C.	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLC433B
Insured/Policyholder	
Name Of Registered Owner	TAN PUAN YNG
NRIC No	S7532666A
Email Address	TANPUANY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97739662
Alternative Phone No	OTHERS-97739662
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	OUTLANDER-2.4 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	AND DESCRIPTION OF THE PROPERTY AND CONTRACTOR OF THE PROPERTY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108611379
Cover Note Number	DRIVO PREMIUM
Driver	
Name of Driver	TAN PUAN YNG
NRIC No	S7532666A
Date Of Birth	29/10/1975
Occupation	INDOOR
Date Of Driving Pass	27/08/2002
Driving Experience	17 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97739662
Fax Number	
Contact Number	OTHERS-97739662

TANPUANY@HOTMAIL.COM

Address

91A GERALD DRIVE

Postcode

797749

144 141 141

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

•

Insurance Company of Driver's Own Vehicle

.

#### General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: PASSENGER

GENDER:

FEMALE

Passenger 2

NAME:

: PASSENGER

GENDER:

: FEMALE

### Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

## Circumstances of Accident

I STOPPED AT THE TRAFFIC JUNCTION WHEN VEHICLE B HIT INTO THE REAR PORTION OF MY VEHICLE.

## Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

PC5858D

Vehicle Make/Model/Colour

Details Of Properties

FRONT PORTION

Vehicle Category

BUS

Name of Driver

LIU SHENGSHI

NRIC/Passport Number

G5140886T

Contact Number

97977963

Address

Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

NELS Income Money Service Control

Support Not MY DATE A

SIC 433B

Report Date: 54 9 2019 South Time: 2-28 PM agrorting Figur. TP Fine Fine:

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wiful mismoresentation or withholding of material facts may allow insurance companies to restudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of colley liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the sentre and to copies of the report being made available accessed.
- B. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, some and consent that
  - (a) My insurer: into workshop and the General Insurance Association of Singapore ("GIA") may like demnited to cortect, use, doclose and/or process my personal data/personal information set out at this florm! and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurers such drawn insured vehicle(s) involved in this accident tall insurers') who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers" the Insurers' lawyers/law firms, the Monetany Authority of Singapore and any relevant government agency/authority (such as the police), for the purposets) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
  - In investigating the accident and or my claims:
  - (iii) carrying out antifor dearing with my instructions or responding to any enguries by me.
  - (iii) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) comprising with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes".
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms, may are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information mayican be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawvershaw firms), which may be sited outside of Simpacone, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (a) the information so collected under (d) above may be shared / disclosed.
- (ii) to all insurers and/or any other third parties that aspec in evaluating, investigating, controlling or managing flaud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or

I'll for compluing with requirements under any regulations, law or court orders.

V

24/9/2010 14 26

24/9/2019 14:25

Policyheider's Signature Date & Time Driver's Signature (If shiver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: Etic Woo Jun Kiet NRIC/ Fin No: 5982753

## Sketch Plan Pg. 2

7				
	BUANG	KOK GREEN TRAFFIC	BJUNCTION	
Vehicle A: SEC4338	Vehicle B. PC5658D			
ESCRIBE CIRCUMSTANCES	OF THE ACCIDENT			

We declare the foregoing particulars are true in every respect

249/2019 14:25

24/4/2019 14:25

Reporting Centre Personnel's Signature Name: End Woo Jun Kost NRIC: Fin No: 9992753

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:



# Certificate of Insurance

Certificate Number: 5108611379	Cover : drive PREMIUM				
Index mark and Registration Number of Vehicle	SLC433B				
Chassis Number	: JMYXTGF3WGI000477				
Name of Policyholder	: TAN PUAN YNG (ZENG FANYING)				
3. Effective Date of Insurance	: 29 Apr 2019				
Expiry Date of Insurance	: 28 Apr 2020				
the Motor Vehicle or has been so permitted and	accordance with the licensing or other laws or regulations to drivid is not disqualified by order of a Court of Law or by reason of any				
enactment or regulation in that behalf from driv 5. Limitations as to Use#					
	and in connection with the Policyholder's business or profession.				
This Policy does not cover  (a) Use for hire or reward.					
(b) Use for racing, pace-making, reliability trial or s; (c) Use for the carriage of goods (other than sampled) Use for any purpose in connection with the Mot # Limitations rendered inoperative by Section 8 of Act (Chapter 189) and Section 95 of the Road Tribeadings.	es) in connection with any trade or business.				
EXCESS (SECTION 1)	: \$\$600				
EXCESS (SECTION 2)	: N/A				
WINDSCREEN EXCESS	: S\$100				
ADDITIONAL EXCESS	: N/A				
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF				
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES				
NSURE WITH COE	: YES				
NCD PROTECTION	: YES				
TRANSPORT ALLOWANCE	: YES				
EXCESS WAIVER	: NO				
PRIMARY DRIVER	: TAN PUAN YNG				
NAMED DRIVER (1)	: LIM PAULINE				
NAMED DRIVER (2)	: N/A				
HIRE PURCHASE COMPANY	: N/A				
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE ATTIME OF LOSS				
/We hereby Certify that the Policy to which this Certific Vehicles (Third Party Risks and Compensation) Act (Charles) Agency : GOHTECK KHYE (00000581375) Date of Issue : 11 Apr 2019 11:54 hrs	rate relates is issued in accordance with the provisions of the Mopter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)  For NTUC INCOME INSURANCE CO-OPERATIVE LIMITE				



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD. EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

# **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
CUITAL TAIDING INCUDANCE (CINCADODE)	Cust No/Name	/Mr Tan Puan Yng (zeng Fanying)		
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00	Reg No/Reg Date	SLC433B*1F / 29/04/2016		
Springleaf Tower	Date In/Mileage	25/09/2019/ 0		
Singapore 079909	Chassis No	JMYXTGF3WGJ000477		
Attn: Claims Dept.	Engine No	4B12RK1608		
Contact No 63896111	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)		
	Colour/Trim	C00 / BK		

Acco	unt No	Terms	Date/Time Printed	d CSE	Operator		WIP No		
F0000		Credit	25/09/2019/ 17:		218 / MarsLer		33282		
	A I I	CONTRACTOR OF THE PARTY.	Description of G	The state of the s	s —	Qty	Unit Price	Disc%	Amount
S M	IPNT8808	38			LKK Auto Cons	ultants hence n	otify	7	250.00
D	IAGNOSTI	IC / SCAN	NNING		the Repairer of	the tollowines	111.00	1 1	1.000
SM	IPNT8808	38			<ul> <li>To resurvey before</li> </ul>	BIGGER STORY DISINGS	a a	1 1	280.00
R	EVERSE S	SENSOR SE	ET Fond		<ul> <li>To display damage</li> </ul>	or group terminal the	luryey	1 1	TITLE VANCOUS
S M	IPNTB808	38	All (XX)		Parts prices are si	Alect to confirmus	R.	1 1	300.00
T	O REPLAC	CE TAILGA	ATE GLASS		Third party survey	at on a Wishout Pr	RIVERS basis	1 1	
	IPNTB808				No illegat modificat	pavite) iz spoked		1 1	100.00
S	EALANT K	KIT ON TA	AILGATE GLASS	me plee.	Supplementary iter     is subject to final a	mis) must be return	myed and	1 1	Verno
	IPNT8808					MANAGEM (COLD STEEL)	inoli Company		X \$ 220.00
			COOL SOLAR FILM (	ON TAILGATE G	LAS\$ Acknowledged by Re	tpairer			1. annun
	IPNT8808			э п	Signature:	П			× 350.00
R	EVERSE (	CAMARE LI	ENS	10057	TOHY:	01770	7		2 please
	IPNT8808					7111 (1		1	3~ 608.00
Т	O TRANSF	FER TAIL	GATE COMPONENT &	MECHANISM PA	RTS	166	2		2 3000/0
	IIPNT8808		CHEVER THE THE TANK OF THE	v viievevvvvv	NAME OF TAXABLE PARTY.				300600.00
			-INSTALL TRIMMING						
			REAR ACCIDENT AF	FFECTED AREAS	y)				200 3600.0
	IIPNT8808	A - A - A - A - A - A - A - A - A - A -	CONTRACTOR OF THE PARTY OF THE	a tarboard but the COT became and					1200 3000.0
			ATE PANEL, REAR BU	UMPER, ETC					
			EAR END PANEL						
			M,ALIGN ON REAR A	ACCIDENT AFFE	CTED AREAS				100300.0
	MIPNT8808								-300.0
			KIT ON NEW PANEL	L				840	(260,00.00
	MIPNT9808	77.77.7						240	2,000.00
		INTING O	N REAR ACCIDENT	AFFECTED AREA	S				nec 50.00
	UNDRY								114 50.00
	& C LO	GO							50.00
	UNDRY								nec 50.00
11.5	MIVEC EM		CACE D	R BUMPER W/FL	ald	1.00	873.00	0.00	-873.0
	J6410024		FACE, KI	R BUMPER W/FL	940	10.00	2.00	<ul> <li>VENTREVE</li> </ul>	→ 20.0
	JMU4880		CLIP,RR		~	10.00	2.00		-20.0
PJ	JMR2003		CLIP,RR	BRACKET, RR		1.00	12.00		- 12.0
16 3	J6410D3	30	LH SIDE	DRACKET . KK	Mer	1.00	10.00	4.00	

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info				
CHINA TAIPING INSURANCE (SINGAPORE)	Cust No/Name	/Mr Tan Puan Yng (zeng Fanying)			
3 Anson Road #16-00	Reg No/Reg Date	SLC433B*1F / 29/04/2016			
Springleaf Tower	Date In/Mileage	25/09/2019/ 0			
Singapore 079909	Chassis No	JMYXTGF3WGJ000477			
Attn: Claims Dept.	Engine No	4B12RK1608			
Contact No 63896111	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)			
	Colour/Trim	C00 / BK			

Account	No Terms	Date/Time Printed	CSE	Operator		WIP No	0 1	
F0000018	Credit	25/09/2019/ 17:18	DS	218 / MarsLer		33282		
	HIT II	Description of Good	s / Service	es	Qty	Unit Price	Disc%	Amount
M JJ64	0D337	RH SIDE BRAG	CKET, RR	Alla	1.00	12.00	0.00	- 12.00
	5A061	EXTENSION. 1	RR BUMPER	seld	1.00	232.00	0.00	232.00
	0B896	RH REINFORCE	EMENT.RR	DIM Pro	1.00	79.00	0.00	X a 79.00
	0B895	LH REINFORCE	EMENT.RR	THENE	1.00	79.00	0.00	¥ ? 79.00
	7A967	DANEL DD EN	n Re	ž	1.00	246.00	0.00	X + 246.00
	78115	ANTENNA, KE	YLESS OP	that New	1.00	96.00	0.00	× 96.00
	7A176	BUZZER, KEY	LESS OPER	Not Nec .	1.00	91.00	0.00	₹ 91.00
	7A317	LH MOULDING			1.00	106.00	0.00	- 106.00
	7A318	RH MOULDING			1.00	106.00	0.00	- 106.00
	18675	TAILGATE PA		Derte	1.00	984.00	0.00	984.00
	8A135	LATCH. TAIL		DAY W	□1.00	475.00	0.00	+ 475.00
	3A149	MOTOR POWER	TANGAT	THY CO	E 3.00	1966.00	0.00	+ 1966.00
	5A067	WEATHERSTRI	P. TATLE	1449012	1.00	213.00	0.00	+ 213.00
	5A015	MARK, THREE	M (AIC	44110	1 1.00	60.00	0.00	+ 60.00
	7A265YB	GARNISH, TAI			1.00	494.00	0.00	+ 494.00
	5A306	GLASS, TAILG			1.00	751.00	0.00	751.00
	5A316	UPR DAM, TAI			1.00	13.00	0.00	13.00
	5A315	SIDE DAM, TA		Nec	2.00	27.00	0.00	54.00
	5A317	LWR DAM, TAI			1.00	41.00	0.00	41.00
	62285	STOPPER, TAI	LGATE WI	N Me	2.00	3.00	0.00	- 6.00
	14447	FASTENER, WI	NDSHIELD	plan	4.00	6.00	0.00	24.00
	6A153	LH REFLECTO			1.00	100.00	0.00	+ 100.00
	7A138	RH REFLECTO			1.00	95.00	0.00	+ 95.00
	08174	RR RH LAMP		M 2	1.00	600.00	0.00	× 600.00
	OB173	RR LH LAMP		M Trans	1.00	600.00	0.00	+ 600.00
	1A179				1.00	506.00	0.00	₹ 506.00
	1A180	LH TAILLAMP RH TAILLAMP	ASSY J	u	1.00	506.00	0.00	₹ 506.00
	5A401	MARK, OUTLAN			1.00	95.00	0.00	95.00
Z NOTE				<u> </u>			- 1	
ACCI	ENT ON 24/	09/2019 ALONG BUANGKO	K GREEN	TRAFFIC JUNCTION				
		THIRD PARTY						
	RED REPLACE							
	PC5858D	TP INS : CHINA TAI	PING					
21(12)	72 6 2	Maria Savaran Internet		61 . 1 3	Parts			9,555.0
Confir	& accepted	by	1	Adrian Ling	Labour			0.0
					Standard M	lenu		0.0
			1,	17 30 05 17	Specialist			8,700.0
					Others (Lub			0.0
				05000	Sundry			100.0
					Total (w/o	2222		18,355.0

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
CUINA TAIDING INCUDANCE (CINCADODE)	Cust No/Name	/Mr Tan Puan Yng (zeng Fanying)		
CHINA TAIPING INSURANCE (SINGAPORE)  3 Anson Road #16-00	Reg No/Reg Date	SLC433B*1F / 29/04/2016		
Springleaf Tower	Date In/Mileage	14/10/2019/ 74920		
Singapore 079909	Chassis No	JMYXTGF3WGJ000477		
Attn: Claims Dept.	Engine No	4B12RK1608		
Contact No 63896111	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)		
	Colour/Trim	C00 / BK		

Acc	ount No	Terms	Date/Time Pi	rinted	CSE	Operator	1000	WIP No	200	Street Street
F000	00018	Credit	21/10/2019/	20:19	DS	218 / MarsLer		33282		
100	port in	THE REAL PROPERTY.	Description		/ Services	DESCRIPTION AND	Qty	Unit Price	Disc%	Amount
SI	MIPNT880	88								250.00
	DIAGNOST MIPNTEBO	IC / SCAI	NNING							280.00
		SENSOR SE	ET							
	MIPHT880		*. f. ;							300.00
	The second second		ATE GLASS							100.00
	MIPNT880									100.00
		A de la company	AILGATE GLAS	5						300.00
	MIPNT880		GATE COMPONE	NT & MECH	ANTEM DAD	27				
					The second secon		-			300.00
3	TO REMOV	E AND RE	-INSTALL TRI	MING, AND	CAPERTING	TOTAL VENAY CO	2450	2		
	ACCESS R	EPAIR ON	REAR ACCIDE	NT AFFECT	ED AREAS	110012		7]		
							2166	7		1200.00
	TO REPLA	CE TAILG	ATE PANEL, RE	AR BUMPER	,ETC	De Veeve			- 1	
			M, ALIGN ON R	EAR ACCIO	ENT AFFEC	TED AREAS			- 1	100.00
	MIPNT880		MAT ON MEU	DANCI						100100
	MIPNT980		KIT ON NEW	PANEL					- 1	840.00
			N REAR ACCID	ENT AFFE	TED AREAS				- 1	
	SUNDRY	INITING O	W KEAR ACCID	Citi Miles	TEO MIENO					50.00
	C & C LC	GO							- 1	
	SUNDRY								- 1	50.00
	MIVEC EN	BLEM			0.000 (17.000)		2 22			873.00
	JJ641002	100	FAC	E, RR BU	MPER W/FL		1.00	873.00	0.00	20.00
	JJMU4880	7.75		P.RR BUM			10.00	2.00	0.00	20.00
	JJMR2003			P.RR BUM			1.00	12.00	0.00	12.00
	JJ6410D3			SIDE BRA			1.00	12.00	(	12.00
/570	JJ6410D3	The state of the s		SIDE BRA			1.00	232.00	N 1985 1985 1	232.00
X	JJ6415A				RR BUMPER		1.00	106.00	2000	106.00
X	JJ7407A3				, RR BUMP		1.00	106.00	0.00	106.00
X	JJ7407A				, RR BUMP			984.00		984.00
X	JJ5801B	575	TAI	LGATE PA	NEL ASSY		1.00	954.00	0.00	204.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info			
CHINA TATRING INCUDANCE (CINCARODE)	Cust No/Name	/Mr Tan Puan Yng (zeng Fanying)		
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00	Reg No/Reg Date	SLC4338*1F / 29/04/2016		
Springleaf Tower	Date In/Mileage	14/10/2019/ 74920		
Singapore 079909	Chassis No	JMYXTGF3WGJ000477		
Attn: Claims Dept.	Engine No	4B12RK160B		
Contact No 63896111	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (G43)		
	Colour/Trim	C00 / BK		

Account No	Terms	Date/Time Printed	CSE	Operator	ne sodo	WIP No	Diam'r.	STATE OF THE PARTY OF
F0000018	Credit	21/10/2019/ 20:19	DS	218 / MarsLer		33282		
- 45-23	-	Description of Good	ds / Services	STATE OF STREET	Qty	Unit Price	Disc%	Amount
OWNER CI	315 317 285 447 401 T ON 24/0	GLASS, TAILE  UPR DAM, TAI  SIDE DAM, TAI  SIDE DAM, TAI  STOPPER, TAI  FASTENER, W  MARK, OUTLAI  9/2019 ALONG BUANGKO	SATE WINDO ILGATE AILGATE IL GATE ILGATE WIN INDSHIELD DK GREEN TRA	AFFIC JUNCTION	1.00 1.00 2.00 1.00 2.00 4.00 1.00	751.00 13.00 27.00 41.00 3.00 6.00 95.00	0.00 0.00 0.00 0.00 0.00	751.00 13.00 54.00 41.00 6.00 24.00 95.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the rumoval of the windscreen.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19016966/ASF3N2

Date:

03/12/2019

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMB1SN30678719000

Claimant Vehicle No:

SLC433B

Insured Vehicle No:

PC5858D

Date of Loss:

24/09/2019

Nature of Claim:

TP

Claim No:

SNM19D204528C02

JMYXTGF3WGJ000477

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLC433B

Make & Model:

MITSUBISHI OUTLANDER, 2.4 CVT (A)

Engine No: Chassis No: 4B12RK1608

Reg. Date: Colour:

29/04/2016 (Man. Year: 2016)

Grey

Engine Capacity: Market Value/New Car 2360 cc

Price: Sum Insured (S\$):

Market Value/New Car Price

Odometer: 74230 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/55R18

Rear Tyre Size:

225/55R18

Front Left Side:

Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 9,935.00 0.00	Adjuster's 3,729.00 0.00	6,206.00 0.00	Diff % 62.47
Labour Paintwork Labour	8,420.00 0.00	3,390.00	5,030.00 0.00	59.74
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,355.00	7,119.00	11,236.00	61.21
+ GST 7.00/7.00% (S\$)	1,284.85	498.33	786.52	61.21
Nett Amount (S\$)	19,639.85	7,617.33	12,022.52	61.21

INSPECTION

Date of Assignment:

26/09/2019

Date Inspected:

30/09/2019 Inspected At:

Cycle & Carriage Fulco Motor Dealer

Pte Ltd (HQ) 330 Ubi Road 3 Singapore 408650

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Dec 2019)
Parts: M1-SUV MITSUBISHI OUTLANDER 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLC433B)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Recommended	Parts
-------------	-------

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR BUMPER W/FL	Deformed	873.00 FS	*873.00 FS
2	10		*CLIP,RR BUMPER	Necessary	20.00 FS	*20.00 FS
3	10		*CLIP,RR BUMPER	Necessary	20.00 FS	*20.00 FS
4	1		*LH SIDE BRACKET,RR	Necessary	12.00 FS	*12.00 FS
5	1		*RH SIDE BRACKET,RR	Necessary	12.00 FS	*12.00 FS
6	1		*EXTENSION,RR BUMPER	Deformed	232.00 FS	*232.00 FS
7	1		*RH REINFORCEMENT,RR	Not Necessary	79.00 FS	*-FS
8	1		*LH REINFORCEMENT,RR	Not Necessary	79.00 FS	*-FS
9	1		*PANEL,RR END	Repair	246.00 FS	*-FS
10	1		*ANTENNA, KEYLESS OPE	Not Necessary	96.00 FS	*-FS
11	1		*BUZZER,KEYLESS OPER	Not Necessary	91.00 FS	*-FS
12	1		*LH MOULDING,RR BUMP	Necessary	106.00 FS	*106.00 FS
13	1		*RH MOULDING,RR BUMP	Necessary	106.00 FS	*106.00 FS
14	1		*TAILGATE PANEL ASSY	Dented	984.00 FS	*984.00 FS
15	1		*LATCH,TAILGATE	Not Necessary	475.00 FS	*-FS
16	1		*MOTOR, POWER TAILGATE	Not Necessary	1,966.00 FS	*-FS
17	1		*WEATHERSTRIP,TAILGA	Not Necessary	213.00 FS	*-FS
18	1		*MARK,THREE-DIA	Not Necessary	60.00 FS	*-FS
19	1		*GARNISH,TAILGATE	Not Necessary	494.00 FS	*-FS
20	1		*GLASS,TAILGATE WINDO	Necessary	751.00 FS	*751.00 FS
21	1		*UPR DAM, TAILGATE	Necessary	13.00 FS	*13.00 FS
22	2		*SIDE DAM, TAILGATE	Necessary	54.00 FS	*54.00 FS
23	1		*LWR DAM, TAIL GATE	Necessary	41.00 FS	*41.00 FS
24	2		*STOPPER, TAILGATE WIN	Necessary	6.00 FS	*6.00 FS
25	4		*FASTENER, WINDSHIELD	Necessary	24.00 FS	*24.00 FS
26	1		*LH REFLECTOR,TAIL L	Not Necessary	100.00 FS	*-FS
27	1		*RH REFLECTOR, TAIL L	Not Necessary	95.00 FS	*-FS
28	1		*RR RH LAMP ASSY,COM	Not Necessary	600.00FS	*-FS
29	1		*RR LH LAMP ASSY,COM	Not Necessary	600.00FS	*-FS
30	1		*LH TAILLAMP ASSY	Not Necessary	506.00FS	*-FS
31	1		*RH TAILLAMP ASSY	Not Necessary	506.00 FS	*-FS
32	1		*MARK,OUTLANDER	Necessary	95.00 FS	*95.00 FS
33	1		*SET REVERSE SENSOR	Damaged	280.00FS	*280.00 FS
34	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
35	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
F=Fra	inchise p	art. S=SpcNe	ett.			
				Total Parts (S\$)	9,935.00	3,729.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

			The State of the S	10.00	Programme in the
Par	mn	mar	non	10	bour
1764		116-21	1116-211		1111111

Particulars	Lab.Type	Repairer's	Amount
our Items			
DIAGNOSTIC/SCANNING	New	250.00	250.00
TO REPLACE TAILGATE GLASS	New	300.00	300.00
SEALANT KIT ON TAILGATE GLASS	New	100.00	100.00
TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS	New	220.00	0.00
REVERSE CAMERA LENS	New	350.00	0.00
TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS	New	600.00	300.00
TO REMOVE AND RE-INSTALL TRIMMING AND CARPETING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	600.00	300.00
TO REPLACE TAILGATE PANEL, REAR BUMPER, ETC- CUT & RE-WELD REAR END PANEL, STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	3,600.00	1,200.00
TO APPLY SEALANT KIT ON NEW PANEL	New	300.00	100.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,100.00	840.00
Gross Labou	r Cost (S\$)	8,420.00	3,390.00
	DIAGNOSTIC/SCANNING TO REPLACE TAILGATE GLASS SEALANT KIT ON TAILGATE GLASS TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS REVERSE CAMERA LENS TO TRANSFER TAILGATE COMPONENT & MECHANISM PARTS TO REMOVE AND RE-INSTALL TRIMMING AND CARPETING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS TO REPLACE TAILGATE PANEL, REAR BUMPER, ETC-CUT & RE-WELD REAR END PANEL, STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS TO APPLY SEALANT KIT ON NEW PANEL SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	DIAGNOSTIC/SCANNING New TO REPLACE TAILGATE GLASS New SEALANT KIT ON TAILGATE GLASS New TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE New GLASS REVERSE CAMERA LENS New TO TRANSFER TAILGATE COMPONENT & MECHANISM New PARTS TO REMOVE AND RE-INSTALL TRIMMING AND CARPETING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS TO REPLACE TAILGATE PANEL, REAR BUMPER, ETC- CUT & RE-WELD REAR END PANEL, STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS TO APPLY SEALANT KIT ON NEW PANEL SPRAY PAINTING ON REAR ACCIDENT AFFECTED New	DIAGNOSTIC/SCANNING New 250.00 TO REPLACE TAILGATE GLASS New 300.00 SEALANT KIT ON TAILGATE GLASS New 100.00 TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE New 220.00 GLASS REVERSE CAMERA LENS New 350.00 TO TRANSFER TAILGATE COMPONENT & MECHANISM New 600.00 PARTS TO REMOVE AND RE-INSTALL TRIMMING AND CARPETING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS TO REPLACE TAILGATE PANEL, REAR BUMPER, ETC-CUT & RE-WELD REAR END PANEL, STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS TO APPLY SEALANT KIT ON NEW PANEL New 300.00 SPRAY PAINTING ON REAR ACCIDENT AFFECTED New 2,100.00 AREAS

< END OF ESTIMATES >