

Case Details

Case Reference Number : TAX/09/19/2090
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4173Y

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8635-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : QBE Insurance (International) Ltd
Accident Date and Time : 19/09/2019 08:55 AM
Vehicle Age(In Months) : 70

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ OR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	✓ DO
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	✗ NN
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	✓ BR
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ NEC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	✓ CRN
Total Spare Part Cost									24,276.03	Surveyor Total		9,165.18		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									19,420.82	Final Sur Total		7,332.14		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	✓ CRM
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	✓ CH
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ OR
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ OR
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.4	2	40.30	80.60	25.00	60.45	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	✓ DO
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	✓ NPC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ NPC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ NPC
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ NPC
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace	✓ NPC
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	1	818.18	Replace	✓ DR
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace	✓ DR
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	✓ APC
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	265.05	Replace	✓ CRU
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace	✓ DR
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Not Give	X NN
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Not Give	X N/A
One Time Key In	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Not Give	X N/A
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	/ APC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ APC
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	/ APC
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ APC
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	715.28	Replace	/ DR
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ APC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ APC
One Time Key In	Main			ROOF PANEL	1	1,102.80	1,102.80	25.00	827.10	Replace	0	0	Not Give	X N/A
One Time Key In	Main			MLDG DRIP RH, ROOF	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	X N/A
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace	/ DR
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	1	90.82	Replace	✓ CR4
One Time Key In	Main			REINFORCEMENT, RR	1	34.60	34.60	25.00	25.95	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ N/A
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	1	0	Repair	X R
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X N/A
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	1	509.70	Replace	✓ CR4
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	1	284.40	Replace	✓ CR4
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	1	97.95	Replace	✓ CR4
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CAP SUB-ASSY, WHEEL	4	174.10	696.40	25.00	522.30	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									24,276.03	Surveyor Total		9,165.18		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									19,420.82	Final Sur Total		7,332.14		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	1	230.25	Replace	/ CR
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	261.70	261.70	25.00	196.27	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	10.00	1,512.81	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	X N/A
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	1	23.02	Replace	/ OR
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.02	Replace	/ OR
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	1	83.18	Replace	/ ON Taillamp pa
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	/ ON
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ NPC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ NPC
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	✓ CR4
One Time Key In	Main			REINFORCEMENT, BACK	1	89.50	89.50	25.00	67.13	Replace	0	0	Check	✗ X NAI
One Time Key In	Main			REINFORCEMENT, BELT	1	103.20	103.20	25.00	77.40	Replace	0	0	Check	✗ X NAI
One Time Key In	Main			REINFORCEMENT, ROOF	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			REINFORCE, ROOF SIDE	1	91.90	91.90	25.00	68.93	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			PANEL, ROOF SIDE,	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			EXTENSION, QUARTER	1	55.70	55.70	25.00	41.78	Replace	1	41.78	Replace	✓ NPC
One Time Key In	Main			EXTENSION, QUARTER	1	83.50	83.50	25.00	62.63	Replace	1	62.63	Replace	✓ NPC
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	1	52.80	Replace	✓ BR
One Time Key In	Main			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			PANEL, ROOF SIDE OUTER RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			RAIL, ROOF SIDE	1	273.60	273.60	25.00	205.20	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	1	634.88	Replace	✓ NPC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ NPC
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	X R
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	1,690.00	1,200	
Total:			1,690.00	1,200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	50	
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	100	
5	Main	TO RESPRAY TAIL GATE	378.00	200	
6	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	
7	Main	TO RESPRAY REAR SPOILER	180.00	80	
8	Main	TO RESPRAY REAR MEMBER,RH	180.00	0	
Total:			4,590.00	1,260.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
11	Main	TO RESPRAY BATTERY PANEL	180.00	0	
12	Main	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
13	Main	TO RESPRAY ROOF TOP PANEL	378.00	0	
14	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	50	Taillamp panel RH
15	Main	TO RESPRAY REAR FENDER RH	378.00	200	
16	Main	RESPRAY WHEEL CAP	720.00	0	
17	Main	TO RESPRAY RH REAR DOOR	378.00	200	
Total:			4,590.00	1,260.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	AK
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	AK
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	AK
5	Main	TO REMOVE / REFIT SEAT	120.00	30	AK
6	Main	TO ALIGN CHASSIS	350.00	0	
7	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
8	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	600.00	600.00	AK
9	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	20	AK
10	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	AK
11	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	AK
12	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	AK
Total:			3,036.00	1,040.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
13	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	AK
14	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100	AK
15	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	50	AK
16	Main	TO REMOVE AND REFIT WIRE HARDESS	300.00	20	AK
17	Main	TO REPLACE SUNDRY PARTS	100.00	30	AK
18	Main	TO WASH AND VACUUM	60.00	0	
Total:			3,036.00	1,040.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	19,420.82	7,332.14
Total Labour Cost	1,690.00	1,200.00
Total Spray Painting	4,590.00	1,260.00
Other	3,036.00	1,040.00
Overall Total	28,736.82	10,832.14
Lump Sum Repair Option	☒	☒
Lump Sum Total	28,750.00	10,850.00
Surveyor Approved Amount		10,850.00
No of Repair Days*	14	10
Remarks		L/S repair, take after spray. Request Purchase Value
Surveyor Name		STEVE CHEN
Signature		
Survey Date	25/09/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHC4173Y
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5904796
Chassis No.:	JTDKN36U605708262
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	29 Nov 2013
First Registration Date:	29 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2021
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$63,297.00
COE Rebate Amount:	\$17,208.00
Total Rebate Amount:	\$23,065.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Sep 2019

$$\$122,499.75 \div 96 \text{ month} = \$1275.94$$

$$\$1275.94 \times 26 \text{ month} = \$33,174.57$$

$$\$33,174.57 + \$5857 = \$39,031.57$$

$$\$39,931.57 - \$23,965.00 = \$15,966.57 \text{ (repair limit)}$$

Steve Chen (LKK Auto)

From: Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops) <samkwok@smrt.com.sg>
Sent: Wednesday, September 25, 2019 5:44 PM
To: Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis)
Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis); Gerald Tan Chwee Hock (Auto Svcs/ARC/ARC/Buses); Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis); Lynn Gan Peh Ling (TPHS/Ops&Maint/FOps/Ops); Wong Kok Wah (Auto Svcs/Claims & IA/Claims & IA); Damian Chan Wee Siong (TPHS/Ops&Maint/FOps); Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: TP Surveyor request purchase value for this vehicle taxi SHC 4173Y

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Tuck Foo,

The purchase value for SHC4173Y will be **\$122,490.75**

Thank you.

Best regards,
Sam Kwok
DID : 68662752

From: Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis)
Sent: 25 September 2019 15:55
To: Sam Kwok Kok Meng (TPHS/Ops&Maint/FOps/Ops) <samkwok@smrt.com.sg>
Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis) <kimming.chin@smrt.com.sg>; Gerald Tan Chwee Hock (Auto Svcs/ARC/ARC/Buses) <tanchweehock@smrt.com.sg>; Peh Eng Hock (Auto Svcs/ARC/ARC/Taxis) <PehEngHock@smrt.com.sg>; Lynn Gan Peh Ling (TPHS/Ops&Maint/FOps/Ops) <LynnGanPehLingYanPeiling@smrt.com.sg>; Wong Kok Wah (Auto Svcs/Claims & IA/Claims & IA) <WongKokWah@smrt.com.sg>; Damian Chan Wee Siong (TPHS/Ops&Maint/FOps) <DamianChan@smrt.com.sg>; Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis) <ANGBANGKIEN@smrtlan.com.sg>
Subject: TP Surveyor request purchase value for this vehicle taxi SHC 4173Y

Hi Sam ,

Please provide the purchase value as requested by the TP surveyor.

TP surveyor need this purchase value to calculate net book value to determine repair limit for this vehicle taxi.

Thanks ,
Tuck Foo

Shu Pei (LKKAUTO)

From: Janice Goh Siew Geok <janice.goh@qbe.com>
Sent: Monday, 30 September 2019 10:19 AM
To: Shu Pei (LKKAUTO)
Cc: Admin A; Asher Sng (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving YP8159T (OI : QBE - TBA) AND SHC4173Y (TP : LKK REF - CC3/QBE19016977/Eeb3) on 19.09.2019
Attachments: YP8159T.pdf

Hi Shu Pei

Thank you for your email.

As requested, please refer to the attachment.

Thank you.

Janice Goh

Executive, Claims

Claims | Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6477 1243

Website LinkedIn Twitter



From: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Sent: Thursday, 26 September 2019 5:04 PM
To: Jenny Toh <jenny.toh@qbe.com>; Janice Goh Siew Geok <janice.goh@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: Direct Settlement - Accident Involving YP8159T (OI : QBE - TBA) AND SHC4173Y (TP : LKK REF - CC3/QBE19016977/Eeb3) on 19.09.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 4173Y at M/s SMRT Automotive Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE19016977/Eea3s2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 05-03-2020		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 8159T	Veh. Inspected	SHC 4173Y	
Policy No.	V0023776	Coverage (\$)	0.00	
Claim No.	VC013018	Excess (\$)	0.00	
Assign From		Assign Date	25/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U605708262	Colour	MAROON	
Odometer	713022	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	5 mm	
L/H Front Tyre	195/65 R15	FALKEN	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/09/2019	Inspection Date	25/09/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4173Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (DISC 25%)	BROKEN	458.60	343.95
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	BUMPER LIP COVER RR/RH (DISC 25%)	CRUSHED	118.10	88.58
1	BUMPER LIP REAR (DISC 25%)	CRUSHED	228.90	171.68
1	BUMPER SEAL, RR RH (DISC 25%)	CUT	65.70	49.28
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	BROKEN	94.80	71.10
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	DAM, BACK DOOR GLASS (DISC 25%)	NECESSARY	27.30	20.48
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER (DISC 25%)	NECESSARY	29.40	22.05
1	DAM, BACK DOOR GLASS ADHESIVE, NO.2 (DISC 25%)	NECESSARY	17.40	13.05
1	MOULDING, BACK WINDOW, LOWER NO.2 (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING, BACK WINDOW, OUTSIDE LH NO.2 (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING, BACK WINDOW OUTSIDE RH NO.2 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR GLASS (DISC 25%)	BROKEN	1,090.90	818.18
1	TAILGATE LOWER WINDOW GLASS (DISC 25%)	BROKEN	721.30	540.98
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	CRUSHED	353.40	265.05
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	BROKEN	504.90	378.68
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.23
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.93
1	SPOILER REAR (DISC 25%)	BROKEN	953.70	715.28
1	END PANEL (DISC 25%)	DENTED	602.10	451.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	CRUSHED	121.10	90.83
1	BOX, RR FLOOR, BOARD (DISC 25%)	CRUSHED	679.60	509.70

Report Ref No. CC3/QBE19016977/Eea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOARD ASSY, RR RH (DISC 25%)	CRUSHED	379.20	284.40
1	SPACER, RR FLOOR (DISC 25%)	CRUSHED	130.60	97.95
1	PANEL ASSY, DECK RH (DISC 25%)	CRUSHED	307.00	230.25
1	TAIL LAMP BRACKET, RH (DISC 25%)	BROKEN	30.70	23.03
1	TROUGH, BACK DOOR (DISC 25%)	DENTED	110.90	83.18
1	FENDER RR/RH (DISC 25%)	DENTED	766.80	575.10
1	FENDER LINER RR/RH (DISC 25%)	CRUSHED	141.30	105.98
1	EXTENSION, QUARTER (DISC 25%)	NECESSARY	55.70	41.78
1	EXTENSION, QUARTER (DISC 25%)	NECESSARY	83.50	62.63
1	DUCT ASSY, QUARTER (DISC 25%)	BROKEN	70.40	52.80
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.88
1	TAILGATE DOOR HINGE LH/RH (DISC 25%) (ADDITIONAL)	DENTED	58.30	43.73
1	TAILGATE DOOR HINGE LH/RH (DISC 25%) (ADDITIONAL)	DENTED	58.30	43.73
1	TAILGATE, BOARD ASSY (DISC 25%) (ADDITIONAL)	CRUSHED	246.90	185.18
1	BOX, DECK FLOOR, RR (DISC 25%) (ADDITIONAL)	BROKEN	649.70	487.28
1	BOARD, RR FLOOR (DISC 25%) (ADDITIONAL)	BROKEN	392.30	294.23
1	GARNISH ASSY, ROOF RH (DISC 25%) (ADDITIONAL)	CRUSHED	256.40	192.30
1	TAIL LAMP RH (DISC 10%)	BROKEN	557.80	502.02
1	BATTERY (DISC 10%) (ADDITIONAL)	CRUSHED	278.00	250.20
1	BATTERY ASSY, HV (DISC 10%) (ADDITIONAL)	BROKEN / DENTED	5,544.40	4,989.96
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @ \$37.00 (SN)	NECESSARY	111.00	111.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	ANTENNA ELECTRICAL, LOWER REAR	NOT NECESSARY	157.40	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-

Report Ref No. CC3/QBE19016977/Eea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	UNDER COVER SUBASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	EXHAUST HEAT SHIELD, REAR	NOT NECESSARY	107.40	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	656.20	-
2	SUPPORT EXHAUST PIPE, NO.4 @ \$40.30	NOT NECESSARY	80.60	-
2	SUPPORT, EXHAUST REAR @ \$33.60	NOT NECESSARY	67.20	-
2	TAILGATE DOOR HINGE LH/RH @ \$58.30	NOT NECESSARY	116.60	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE DOOR STAY LH	NOT NECESSARY	241.50	-
1	TAILGATE DOOR STAY RH	NOT NECESSARY	241.50	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	-
1	TAILGATE TRIM, LH	NOT NECESSARY	85.90	-
1	TAILGATE TRIM, LOWER	NOT NECESSARY	180.70	-
1	TAILGATE BOARD ASSY	NOT NECESSARY	246.90	-
1	WIRE, BACK DOOR, NO.1	NOT NECESSARY	582.40	-
1	ARM, RR WIPER	NOT NECESSARY	84.70	-
1	BLADE ASSY, REAR WIPER	NOT NECESSARY	55.00	-
1	3RD BRAKE LAMP	NOT NECESSARY	231.30	-
1	ROOF PANEL	NOT NECESSARY	1,102.80	-
1	MLDG DRIP RH, ROOF	NOT NECESSARY	78.80	-
1	END PANEL COVER, DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	REINFORCEMENT, RR	NOT NECESSARY	34.60	-
1	MEMBER SUB-ASSY, RR RH	NOT NECESSARY	174.10	-
1	FLOOR PANEL RR/RH	NOT NECESSARY	209.90	-
1	BOX, DECK FLOOR, RR	NOT NECESSARY	649.70	-
1	BOARD, RR FLOOR	NOT NECESSARY	392.30	-
1	COVER ASSY, TONNEAU	NOT NECESSARY	602.10	-
1	CUSHION, SPARE WHEEL	NOT NECESSARY	230.80	-
1	PROTECTOR, SPARE	NOT NECESSARY	143.70	-
1	CARRIER, SPARE	NOT NECESSARY	19.70	-
4	CAP SUB-ASSY, WHEEL @ \$174.10	NOT NECESSARY	696.40	-
1	BREAKDOWN SIGN	NOT NECESSARY	35.00	-

Report Ref No. CC3/QBE19016977/Eea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GARNISH SIDE UPPER, LHR	NOT NECESSARY	261.70	-
1	BATTERY	NOT NECESSARY	278.00	-
1	BATTERY CLAMP	NOT NECESSARY	16.10	-
1	BATTERY TRAY	NOT NECESSARY	42.80	-
1	WIRE, FRAME	NOT NECESSARY	1,680.90	-
1	WIRE, ENGINE, NO.3	NOT NECESSARY	74.00	-
1	WIRE, FLOOR	NOT NECESSARY	1,675.00	-
1	WIRE, FLOOR, NO.2	NOT NECESSARY	1,305.40	-
1	PANEL SUB-ASSY, QTR	NOT NECESSARY	326.70	-
1	PANEL SUB-ASSY, QTR	NOT NECESSARY	588.40	-
1	REINFORCEMENT, BACK	NOT NECESSARY	89.50	-
1	REINFORCEMENT, BELT	NOT NECESSARY	103.20	-
1	REINFORCEMENT, ROOF	NOT NECESSARY	60.30	-
1	REINFORCE, ROOF SIDE	NOT NECESSARY	91.90	-
1	PANEL, ROOF SIDE,	NOT NECESSARY	134.80	-
1	PANEL, ROOF SIDE INNER FRONT RH	NOT NECESSARY	134.80	-
1	PANEL, ROOF SIDE OUTER RH	NOT NECESSARY	134.80	-
1	RAIL, ROOF SIDE	NOT NECESSARY	273.60	-
1	DOOR LOCK RR/RH	NOT NECESSARY	709.30	-
1	CHECK ASSY, RR DOOR,	NOT NECESSARY	150.30	-
1	TYRE	NOT NECESSARY	126.74	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	667.70	-
1	DOOR RR/RH	TO REPAIR SEE LABOUR	954.50	-
1	SOLAR FILM (SN)	NECESSARY	600.00	600.00
			38,908.64	16,147.19
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL AND DOOR RR/RH.		1,690.00	1,480.00
	SPRAY PAINT.		4,590.00	1,560.00
	TOWING CHARGE.		126.00	90.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00

Report Ref No. CC3/QBE19016977/Eea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE / REFIT SEAT.		120.00	30.00
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	TO REMOVE & REFIT EXHUAUST.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO INSPECT RR LIGHTING, MECHANISM & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	20.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	20.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	100.00
	TO REMOVE & REFIT REAR QUARTER GLASS RH.		120.00	50.00
	TO REMOVE AND REFIT WIRE HARDESS.		300.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	LABOUR TO REMOVE & REFIX HV BATTERY. (ADDITIONAL)		350.00	150.00
			9,066.00	3,720.00
GRAND TOTAL			47,974.64	19,867.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CC3/QBE19016977/Eea3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.