

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19016982/KKA3Q2

**Date:** 04/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SMG2869G **Insured Vehicle No :** SMF3028R

**Date of Loss:** 18/09/2019 **Nature of Claim:** TP **Claim No:** 2791351085SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMG2869G</b>		
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Engine No:	HIDDEN
Reg. Date:	01/12/2018 (Man. Year: 2018)	Chassis No:	ZVW400029112
Colour:	Metallic Silver	Odometer:	69791 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Neuton 9 mm	Rear Left Side:	Neuton 9 mm
Front Right Side:	Neuton 9 mm	Rear Right Side:	Neuton 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	787.62	0.00	787.62	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	200.00	2,390.00	92.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,377.62</b>	<b>200.00</b>	<b>3,177.62</b>	<b>94.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	236.43	14.00	222.43	94.08
<b>Nett Amount (S\$)</b>	<b>3,614.05</b>	<b>214.00</b>	<b>3,400.05</b>	<b>94.08</b>
<b>+ Car Rental (1.0 x S\$88.00/day) (S\$)</b>		88.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>309.45</b>		

### INSPECTION

Date of Assignment: 01/10/2019

Date Inspected: 01/10/2019 Inspected At:

385 SIN MING DRIVE  
Repairer: Esteem Performance Pte Ltd  
(HQ)

Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Serviceable	200.00 FS	* - FS
2	1		*REAR BUMPER	Repair	499.60 FL	* - FL
3	1		*REAR BUMPER CLIP	Not Necessary	38.90 FL	* - FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	62.70 FL	* - FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	62.70 FL	* - FL
6	1		*REAR BUMPER REFLECTOR LH	Serviceable	59.80 FL	* - FL
7	1		*REAR BUMPER REFLECTOR RH	Serviceable	59.80 FL	* - FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>983.50</b>	<b>0.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	195.88	0.00
<b>Total Parts (\$\$)</b>	<b>787.62</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAIL DOOR ,END PANEL)	New	1,000.00	0.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAIL DOOR ,END PANEL)	New	1,000.00	200.00
3	TO CHECK WIRING	New	50.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	0.00
5	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
6	TO TUFF COAT	New	150.00	0.00
7	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,590.00</b>	<b>200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >