

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG19016993/ASF3E2

**Date:** 26/11/2020

### REFERENCE

Insured/Claimant:	CLIVE GORDON SCOTT	Policy No:	1800096299
Date of Loss:	07/07/2019	Nature of Claim:	OD
		Claim No:	7938849935SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>S9105CD</b>		
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Engine No:	CDN282963
Reg. Date:	31/08/2012 (Man. Year: 2012)	Chassis No:	WAUZZZ8RXCA126012
Colour:	Black	Odometer:	92783 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$20,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,052.00	6,014.32	4,037.68	40.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,752.00	3,852.00	2,900.00	42.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,804.00</b>	<b>9,866.32</b>	<b>6,937.68</b>	<b>41.29</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>15,804.00</b>	<b>8,866.32</b>	<b>6,937.68</b>	<b>43.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,106.28</b>	<b>620.64</b>	<b>485.64</b>	<b>43.90</b>
<b>Nett Amount (S\$)</b>	<b>16,910.28</b>	<b>9,486.96</b>	<b>7,423.32</b>	<b>43.90</b>

### INSPECTION

Date of Assignment:	26/09/2019	
Date Inspected:	26/09/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,432.00 FS	*1,945.60 FS
2	1		*FRONT BUMPER SPOILER	Not Necessary	249.00 FS	*- FS
3	1		*FRONT BUMPER SIDE RETAINER-LH	Not Necessary	569.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE DRILLE-LH	Not Necessary	123.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION	Damaged	34.00 FS	*27.12 FS
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	598.00 FS	*- FS
7	1		*FOAM FILLER PIECE	Not Necessary	103.00 FS	*- FS
8	1		*FRONT BUMPER SENSOR	Not Necessary	231.00 FS	*- FS
9	1		*FRONT BUMPER SENSOR SEAL RING	Not Necessary	20.00 FS	*- FS
10	4		*FRONT FENDER-LH	Dented	913.00 FS	*730.00 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	61.00 FS	*- FS
12	1		*SEALING FRAME-LH	Not Necessary	59.00 FS	*- FS
13	1		*FRONT FENDER BRACKET-LH	Not Necessary	49.00 FS	*- FS
14	1		*FRONT FENDER BRACKET-CENTER	Not Necessary	45.00 FS	*- FS
15	6		*POP ROVERT	Not Necessary	108.00 FS	*- FS
16	1		*FRONT FENDER BRACE-LH	Bent	79.00 FS	*62.64 FS
17	1		*WHEEL HOUSING LINER	Torn	246.00 FS	*196.40 FS
18	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	94.00 FS	*74.96 FS
19	1		*WHEEL SPOILER	Not Necessary	60.00 FS	*- FS
20	1		*HEADLIGHT MOUNTING	Not Necessary	107.00 FS	*- FS
21	1		*RETAINING PLATE	Not Necessary	66.00 FS	*- FS
22	1		*HEADLIGHT GAS DISCHARGE	Cut	2,432.00 FS	*2,119.20 FS
23	1		*HALOGEN FOG LAMP	Not Necessary	203.00 FS	*- FS
24	1		*HEADLIGHT LIFT CYLINDER	Not Necessary	227.00 FS	*- FS
25	1		*ALUMINIUM RIM	Cut	844.00 FS	*844.00 FS
26	1		*RUBBER VALVE	Not Necessary	75.00 FS	*- FS
27	1		*SUNDRIES	Necessary	25.00 FS	*14.40 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**    **10,052.00**    **6,014.32**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER,FRONT BUMPER SPOILER AND LHS FRONT FENDER	New	3,000.00	1,650.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>6,752.00</b>	<b>3,852.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >