Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017001/EPA3Q2

Date: 12/01/2021

REFERENCE

MCOM0015 Handling Insurer: India International Insurance Pte Ltd Policy No: Claimant SG5788R

Insured Vehicle No: SHA2983A Vehicle No:

Date of Loss: Nature of Claim: ΤP 23/09/2019 Claim No: MCT19090563

DESCRIPTION & IDENTIFICATION OF VEHICLE

SG5788R Reg No:

Make & Model: MAN A95, 10.5 D (A) Engine No: 50343980824398 Reg. Date: 19/08/2016 (Man. Year: 2016) Chassis No: WMAA95ZZ3G7003343 Odometer: 249654 km

Colour: Multi-colour **Engine Capacity:** 10518 cc

Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 Front Left Side: Rear Left Side: Firenza 5 mm Firenza 5 mm Front Right Side: Rear Right Side: Firenza 5 mm Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		974.70	0.00	974.70	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,241.00	884.00	357.00	28.77
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	2,215.70	884.00	1,331.70	60.10

+ Loss of Use (3.0 x S\$325.00/day) (S\$) 975.00 1,859.00 **(S\$)**

929.50 **Liable Amount (50.00%) (S\$)**

INSPECTION

Date of Assignment: 26/09/2019

Date Inspected: 26/09/2019 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Jul 2020)

Parts: N/A MAN A95 10.5 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SG5788R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*COVER ,HEADLAMP ,FRT LH ,FOR MAN A22 BUS	Repair	974.70 F	*- F		
F=Fra	inchise	part.		Total Parts (S\$)	974.70	0.00		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00		
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	446.00	354.00		
	Gross Labour Cost (S\$)		1,241.00	884.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >