Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017003/KPA3Q2

Date: 20/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant Insured Vehicle No: SHD4884Z SKG1798H

Vehicle No:

Date of Loss: 24/09/2019 Nature of Claim: ΤP Claim No: MCT19090605

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKG1798H Reg No:

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: 1AZE169018

Reg. Date: 17/06/2010 (Man. Year: 2010) Chassis No: MR053BK4107056820

Colour: Metallic Green Odometer: 132575 km

Engine Capacity: 1998 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm Front Right Side: Rear Right Side: Michelin 9 mm Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,180.90	1,101.89	79.01	6.69
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	900.00	650.00	250.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,091.90	1,762.89	329.01	15.73
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,091.90	1,400.00	691.90	33.08
+ GST 7.00/7.00% (S\$)	146.43	98.00	48.43	33.07
Nett Amount (S\$)	2,238.33	1,498.00	740.33	33.08
+ Med	+ Medical Costs (S\$)			
+ Car Rental (3.0 x S\$150.00/day + 7	+ Car Rental (3.0 x S\$150.00/day + 7.00% GST) (S\$)			
No	ett Liability (S\$)	2,021.50		

INSPECTION

Date of Assignment: 26/09/2019 Present Location: City Auto Pte Ltd (HQ) City Auto Pte Ltd (HQ) Date Inspected: 27/09/2019 Inspected At:

160 Sin Ming Drive #05-01,, Sin Ming

AutoCity,

Singapore 575722

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)	
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Print Code: (Unsubmitted, no print-code for SKG1798H)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bumper	Buckled	475.90 FL	*475.90 FL
2	1		*Front bumper LH retainer	Distorted	58.33 FL	*58.33 FL
3	1		*Front bumper LH chrome	Serviceable	105.34 FL	*- FL
4	1		*LH Headlamp	Mtg Cracked	898.71 FL	*898.71 FL
5	1		*Emblem - VVT-i	Necessary	36.25 FL	*36.25 FL
F=Fra	anchise	part. L=ListIter	nDisc.			
				Sub Total (S\$)	1,574.53	1,469.19
	- List Item Discount on L Items 25.00/25.00% (S\$)		393.63	367.30		
				Total Parts (S\$)	1,180.90	1,101.89
			Report was unsubmitted	during this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	OD/TP Case (Insurer) (NECESSARY)	_	11.00	11.00
			Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	* To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	400.00	250.00
2	* Spray painting on affected and replace parts	New	500.00	400.00
	Gross Labour	Cost (S\$)	900.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >