

ASS. REC. BY:

REF:

CS/TP19017044/Asd3M2

Adrian

ASSIGNMENT

Front:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJF 4713A

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Vehicle: IN / OUT

Person Contacted:

Veh No: GBE 46734

Yr Regn: 2015, Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c 2982

Colour: Red A/C: Insured / Std / Nil / NA

Sp. Reading: 193547 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: JTFHT02P700184385

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: 195 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firemax

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 25/09/19

Survey held at Vision

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Direct Asia (Independent)

GBE 46734 - NA / AIG 19016796/13

SJF 4713A - NA / AIG 19016796/13

POA: 23/9/2019

BON: 23/9/2019

MV: 46K.

PV: 21.7K

Nett: 24.3K.

26/11/19 Adrian Confirmed L/S \$ 10,200/- @ 9 days with Bacc
(\$11,150.25 Red - 52%)

Resurvey No. of Trip - 2

Date/Time File Pass to?

Date/Time File Return to?

1) Typist

2)

3)

4)

5)

6)

Prel. Report

Final Report L/S \$ 10,200/-

Part Prices Check:

IN

OUT

Survey Fee:

Date: 11/15: 165

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1701/65

50

50+50

90

80

655

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/09/2019 10:20
Date Of Accident	23/09/2019 15:15
Exact Location Of Accident	SLIP RD OF EXIT 6(CTE CITY)ENTERING BUKIT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE4673G
Insured/Policyholder	
Name Of Registered Owner	SAKUNTHALA'S HOLDINGS PTE LTD
Co Reg No	200103245E
Email Address	SAKUNTHALACATERING@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62936649

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100443245-03
Cover Note Number	

Driver

Name of Driver	KANNAN PRABAKARAN
Passport No/FIN	G2687897M
Date Of Birth	05/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	07/12/2017
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93738342
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	151 DUNLOP STREET
Postcode	209466
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - AUTHORISED DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF4713A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGT5863E
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.




Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Report Centre Personnel's Signature
Name
NRIC No. & No.

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23.09.19 at about 15:15 hours along Slip Road of Exit 6 (CTE City) entering Bukit Timah Road. I was travelling straight on lane 2, when I was approaching the zebra crossing and there were pedestrians crossing hence I slowed down and stopped. Suddenly I heard a loud bang from behind. When I alighted I realised it was vehicle (B) collided onto rear portion of my vehicle (A). It was a chain collision of total 3 vehicles involved.

Vehicle (A): GBE 4673G

Vehicle (B): SJF 4713A

Vehicle (C): SGT 5863E

DECLARATION

I/We do hereby declare that the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NAC ID No.

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 24.09.19

TO : DIRECT ASIA MOTOR CLAIMS DEPTS

VEHICLE NO : GBE4673G

MODEL : TOYOTA HIACE

DATE OF ACCIDENT : 23.09.19

TIME OF ACCIDENT : 15:15HRS

ITFHT02P700184595

Shirley

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE Dented	1	\$ 2,067.00	\$ 2,067.00
2	TAILGATE STOPPER new	2	\$ 19.00	\$ 38.00
3	TAILGATE DAMPER New	2	\$ 58.00	\$ 116.00
4	TAILGATE CORNER GARNISH Missing	2	\$ 18.00	\$ 36.00
5	TAILGATE OUTER MOULDING new	1	\$ 324.00	\$ 324.00
6	TAILGATE LOGO new	1	\$ 80.00	\$ 80.00
7	TAILGATE LOCK MOTOR Dmgd	1	\$ 545.00	\$ 545.00
8	TAILGATE WEATHERSTRIP Lt	1	\$ 410.00	\$ 410.00
9	TAILGATE INNER LOCK Dmgd	1	\$ 285.00	\$ 285.00
10	TAILGATE LOWER LOCK Best	1	\$ 45.00	\$ 45.00
11	TAIL LAMP cracked	2	\$ 380.00	\$ 760.00
12	TAILLAMP LOWER GARNISH Dented RH	2	\$ 298.00	\$ 596.00
13	TAILLAMP LOWER GARNISH RETAINER new	2	\$ 65.00	\$ 130.00
14	REAR BUMPER Distorted	1	\$ 479.00	\$ 479.00
15	REAR BUMPER SIDE RETAINER new	2	\$ 55.00	\$ 110.00
16	REAR END PANEL (EXTEND) Dented	1	\$ 295.00	\$ 295.00
17	REAR END PANEL (INNER) Dented	1	\$ 871.00	\$ 871.00
18	REAR END PANEL (OUTER) Dented	1	\$ 597.00	\$ 597.00
19	REAR FLOOR PANEL Repair	1	\$ 1,960.00	\$ 1,960.00
20	REAR SPARE TYRE HOLDER BRACKET Best	1	\$ 380.00	\$ 380.00
21	REAR SPARE TYRE HOLDER BOLT new	1	\$ 60.00	\$ 60.00
22	REAR EXHAUST PIPE 3rd Best	1	\$ 989.00	\$ 989.00
23	REAR EXHAUST PIPE MOUNTING new	2	\$ 47.00	\$ 94.00

8054

6040.50

TOTAL PRICE \$ 11,267.00
LESS 25% \$ 2,816.75
SUB TOTAL PRICE \$ 8,450.25

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE Best	1	\$ 50.00	\$ 50.00

30

TO : DIRECT ASIA MOTOR CLAIMS DEPTS
 VEHICLE NO : GBE4673G
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 23.09.19
 TIME OF ACCIDENT : 15:15HRS

2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	TAIL LAMP CLIP (SET) <i>per</i>	1	\$ 40.00	\$ 40.00	20
4	TAILLAMP LOWER GARNISH CLIP (SET) <i>per</i>	1	\$ 60.00	\$ 60.00	20
5	TAILGATE SEALANT <i>per</i>	1	\$ 150.00	\$ 150.00	+
6	TAILGATE CORNER GARNISH CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00	20
7	TAILGATE OUTER MOULDING CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00	+
8	TAILGATE STICKER '70KM/H' <i>New</i>	1	\$ 40.00	\$ 40.00	15
9	TAILGATE COMPANY STICKER (SET) <i>New</i>	1	\$ 1,500.00	\$ 1,500.00	800
10	TAILGATE INNER TRIM (STANDARD STEEL) <i>Bed</i>	1	\$ 550.00	\$ 550.00	350
11	TAILGATE INNER TRIM CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00	30
12	TAILGATE WINDSCREEN SEALANT <i>3 per</i>	1	\$ 80.00	\$ 80.00	40
13	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	40
14	REAR END PANEL (OUTER) SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	60
15	REAR END PANEL (INNER) SEALANT <i>Not per</i>	1	\$ 150.00	\$ 150.00	X
16	REAR END PANEL (OUTER) SEALANT <i>per</i>	1	\$ 150.00	\$ 150.00	+
17	REAR FLOOR PANEL SEALANT <i>per</i>	1	\$ 350.00	\$ 350.00	+
18	REAR FLOOR TOP COVER (STANDARD STEEL) <i>Bed</i>	1	\$ 3,800.00	\$ 3,800.00	2500
19	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200
20	REVERSE CAMERA <i>Not New</i>	1	\$ 450.00	\$ 450.00	X

HISS

TOTAL \$ 8,030.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,800.00	1200
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1000
3	WIRING, BULB CHECKING	\$ 180.00	30
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	✓
5	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
7	REAR CHASSIS ALIGHMENT	\$ 250.00	+

TO : **DIRECT ASIA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBE4673G**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 23.09.19
 TIME OF ACCIDENT : 15:15HRS

8	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50
9	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 80.00	50
10	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

4870

2610

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,480.25
 TOTAL LABOUR COST : \$ 4,870.00
 TOTAL REPAIR COST : \$ 21,350.25

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY

HP : 9856 4815

Adrian Lim
 L/S 25/09/19.

09 Days.

total 12805.50
 L/S 10.21C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
VISION AUTOWORK PTE LTD			Ref : CS/TP19017044/Asd3n2	
8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKITSINGAPORE 415875			Date : 26-11-2019	
ON BEHALF OF SAKUNTHALA'S HOLDINGS PTE LTD			Code : TP491	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		GBE 4673G
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		25/09/2019
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTFHT02P700184395	Colour	RED	
Odometer	193547	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	FIREMAX	6 mm	
L/H Front Tyre	195 R15C	FIREMAX	6 mm	
R/H Rear Tyre	195 R15C	FIREMAX	6 mm	
L/H Rear Tyre	195 R15C	FIREMAX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		23/09/2019	Inspection Date	
Survey held at		VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4673G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	DENTED	2,067.00	2,067.00
2	TAILGATE STOPPER @\$19.00	NOT NECESSARY	38.00	-
2	TAILGATE DAMPER @\$58.00	NOT NECESSARY	116.00	-
2	TAILGATE CORNER GARNISH @\$18.00	MISSING	36.00	36.00
1	TAILGATE OUTER MOULDING	NOT NECESSARY	324.00	-
1	TAILGATE LOGO	NECESSARY	80.00	80.00
1	TAILGATE LOCK MOTOR	DAMAGED	545.00	545.00
1	TAILGATE WEATHERSTRIP	CUT	410.00	410.00
1	TAILGATE INNER LOCK	DAMAGED	285.00	285.00
1	TAILGATE LOWER LOCK	BENT	45.00	45.00
2	TAIL LAMP @\$380.00	CRACKED	760.00	760.00
2	TAILLAMP LOWER GARNISH @\$298.00	O/S DEFORMED	596.00	105.00
2	TAILLAMP LOWER GARNISH RETAINER @\$65.00	NOT NECESSARY	130.00	-
1	REAR BUMPER	DISTORTED	479.00	479.00
2	REAR BUMPER SIDE RETAINER @\$55.00	NECESSARY	110.00	110.00
1	REAR END PANEL (EXTEND)	DENTED	295.00	295.00
1	REAR END PANEL (INNER)	DENTED	871.00	871.00
1	REAR END PANEL (OUTER)	DENTED	597.00	597.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,960.00	-
1	REAR SPARE TYRE HOLDER BRACKET	BENT	380.00	380.00
1	REAR SPARE TYRE HOLDER BOLT	NOT NECESSARY	60.00	-
1	REAR EXHAUST PIPE	BENT	989.00	989.00
2	REAR EXHAUST PIPE MOUNTING @\$47.00	NOT NECESSARY	94.00	-
	LESS 25% DISCOUNT		-2,816.75	-2,013.50
			8,450.25	6,040.50
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	BENT	50.00	30.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	40.00	20.00
1	SET TAILLAMP LOWER GARNISH CLIP (SN)	NECESSARY	60.00	20.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET TAILGATE CORNER GARNISH CLIP (SN)	NECESSARY	50.00	20.00
1	SET TAILGATE OUTER MOULDING CLIP (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/TP19017044/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE STICKER "70KM/H" (SN)	NECESSARY	40.00	15.00
1	SET TAILGATE COMPANY STICKER (SN)	NECESSARY	1,500.00	800.00
1	TAILGATE INNER TRIM (STANDARD STEEL)(SN)	BENT	550.00	350.00
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	50.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	40.00
1	REAR END PANEL (OUTER) SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR END PANEL (INNER) SEALANT (SN)	NOT NECESSARY	150.00	-
1	REAR END PANEL (OUTER) SEALANT (SN)	NOT NECESSARY	150.00	-
1	REAR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	350.00	-
1	REAR FLOOR TOP COVER (STANDARD STEEL)(SN)	BENT	3,800.00	2,500.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
			8,030.00	4,155.00
	LABOUR			
	PANEL BEATING AND REPLACE PARTS,INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,800.00	1,200.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	1,000.00
	WIRING,BULB CHECKING.		180.00	30.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	REMOVE AND REFIX REAR EXHAUST PIPE.		180.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR.		80.00	50.00
	REMOVE AND REFIX REAR REVERSE CAMERA.		80.00	50.00
	REMOVE AND REFIX REAR WINDSCREEN.		120.00	120.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
	-		-	-
	-		-	-
	-		-	-
			4,870.00	2,610.00
	GRAND TOTAL		21,350.25	12,805.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,200.00

Report Ref No. CS/TP19017044/Asd3n2



Report Ref No. CS/TP19017044/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.