

	Repair Estimates	Finalized SMC 18	941 H
Parts	(a) Cost / List Price Items	\$7497.06	4,213.06
	Plus/Less 25%	\$.674.>7	1,053.27
	Total of Cost / List	\$1877.79	3,159.80
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$ 240	295.00
Total P	arts Cost	\$717.79	3,454.80
Labour		\$ 1400	3,230.00
l'otal		\$3517.79	6,684.80

Not Nothark

Name of Survey	or	:		Kenneth	,	
Company		:		IKK		
Survey conducte	d on	:	2	7/8/19 at		
	f this vehicle is author	rized :	/ is not authorized until furth  OG  Required / Not Required	er notice. day(s)		
(d) Excess		:\$_				
(e) Signature of	surveyor	:		Le	Date:	27/9119



Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

**Spare Parts** 

Vehicle No. : Make & Model :

Chassis No

SMC 1941 H

TOYOTA PRIUS ALPHA ZVW400029582 Submit By

Year Manufacture

**JENNY** 

2018

Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price		Price	Disposition by Surveyor
1	Rear windscreen moulding	M	1	\$70.20	7	/	-
2	Rear windscreen sealant	M	1	\$50.00	1	Ś.N	4012
3	Reverse sensor	Shan	1	\$200.00	~	ร์.ท	i
4	Rear number plate	92	~ 1	\$45.00		S.N	×
5	Rear bumper	Bu	2 1	\$459.20	7	-	
6	Rear bumper clip	M	n 1	\$38.90	4	/	-
7	Rear bumper side retainer LH	PL	_ 1	\$121.70			×
8	Rear bumper side retainer RH	n.	d 1	\$121.70	4	/	~
9	Rear bumper reflector LH	SL	1	\$58.70			X
10	Rear bumper reflector RH	C	<b>27</b> 1	\$58.70	4	•	-
11	Tail door	12	7 1	\$1,022.50	1		-
12	Tail door lock		R 1	\$391.60			×
13	Tail door plate garnish	Sa	1	\$498.30			X
14	Tail door emblem	Su	_ 1	\$67.10			X
15	Wording "PRIUSCX"	n	1	\$72.66	4	_	
16	Boot weatherstrip	Su	. 1	\$342.70	1		X
17	Tail lamp RH	Mon	1	\$653.20	1	/	2/
18	Tail lamp clip	m	10	\$42.10			买
19	Tail end panel garnish	Sm	1	\$154.60			X
20	Tail end panel garnish	Sin	1	\$39.20			X
21					1		
22							
23							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N

CN: 240

7497.06



Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

Vehicle No.	:	SMC 1941 H	Submit By	:	Carmen Lim	
Make & Model	:	TOYOTA PRIUS ALPHA	Year of Manufacture:		2018	

Labour Description	Esimated Price	Adjusted Price
TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL,		
SPARE TYRE WELL PANEL)	\$1,200.00	5001
TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL,	\$1,200.00	6001
SPARE TYRE WELL PANEL)		
To check wiring	\$50.00	201
To remove & refit reverse sensor	\$120.00	501
To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	7
to assist work load.		
To remove & refit rear windscreen.	\$120.00	
To tuff coat.	\$150.00	301
To transfer boot mechanism to new boot	\$120.00	601
To conduct water leakage tests to ensure proper air and	\$120.00	201
sealing		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)  TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)  To check wiring  To remove & refit reverse sensor  To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.  To remove & refit rear windscreen.  To tuff coat.  To transfer boot mechanism to new boot  To conduct water leakage tests to ensure proper air and	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)  TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)  To check wiring  \$50.00  To remove & refit reverse sensor  \$120.00  To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.  To remove & refit rear windscreen.  \$150.00  To tuff coat.  \$150.00  To transfer boot mechanism to new boot  To conduct water leakage tests to ensure proper air and

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.