

Person

REF A19

17081 M(10)

2803

ASSIGNMENT

From: _____ Date: 1.10.2019
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SGM 8016B
at Workshop m/s Volkswagen
of 247 Alexandra Road
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: 12.00 p.m. owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS mp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGM 8016B Yr Regn: 2018 / JUN
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: VOLKSWAGEN PASSAT 1.8PS c.c. 1798
Colour: GREY A/C: Insured / Std / NI / NA
Sp. Reading: 29965 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WUV 2223C2JE220868
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / STD A/Rim or
Tyre Size: F: 215/55R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 27/09/19 D.O.I. 01/10/19
Survey held at VOLKSWAGEN
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/8 Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos: _____

Others: _____

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invt (\$ _____)

☐ : Wheel end (\$ _____)