

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbro@yahoo.com

Invoice/Ref No: SMG4818R190925

Estimate**Customer**Name: EQ Insurance Company LimitedDate: 28-09-19Address Motor Claims DepartmentVehicle No: SMG48185 Maxwell Road #17-00Model/Make: MercedesTower Block MND Complex Singapore 069110

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bonnet <i>DD/BUC</i>	\$ 2,505.42	
2	Bonnet Logo <i>nu</i>	\$ 108.50	
3	Bonnet Hinges 02 pcs (@ \$5166.00) <i>n1</i>	\$ 332.00	X
4	Bonnet Lock Centre Level <i>su</i>	\$ 125.00	X
5	Bumper <i>D.S</i>	\$ 1,465.00	
6	Bumper Side Retainer 02 pcs (@ \$565.00) <i>n1</i>	\$ 130.00	X
7	Bumper Sponge <i>Torn</i>	\$ 162.90	
8	Bumper Reinforcement <i>Bent</i>	\$ 685.32	
9	Bumper PDC Sensor <i>Shocked</i>	\$ 232.33	
10	Bumper Centre Grille <i>n1</i>	\$ 218.20	X
11	Grille <i>ma</i>	\$ 895.00	
12	Grille Logo <i>one</i>	\$ 112.00	
13	Grille Chrome Moulding <i>ena</i>	\$ 288.20	
14	Bumper Top Inner Rubber <i>Torn</i>	\$ 115.00	
15	Support Panel <i>DD/Bent</i>	\$ 904.30	
16	Head Lamp Assys 02 pcs (@ \$3,687.25) <i>MS holder</i>	\$ 7,374.50	1PC
17	Licence Plate Garnish <i>Torn</i>	\$ 68.50	
18	Head Lamp Bracket <i>Self/ty</i>	\$ 255.00	
19	View Camera <i>Shocked</i>	\$ 680.00	
20	Centre Retainer <i>twi</i>	\$ 148.50	
21	Aircon Condenser <i>n1</i>	\$ 1,213.15	X
22	Support Panel Centre Garnish <i>Torn</i>	\$ 266.20	
23	Licence Plate With Holder <i>Torn 194 (102)</i>	\$ 50.00	405.2
	To check all wiring & electrical component for proper function	\$ 50.00	20
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	30
	To reprogramme & Reset System	\$ 150.00	80
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 120.00	119 X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	500
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	550

Total Parts & Labour of estimate for damaged vehicle

\$ 20,305.03

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

Not Authorized

9/12 12541.48

30/9/19

4 dy.

P-12579.43

10%

P-11321.48

L-1220.00

12541.48