

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19017149/T1GA3Q2

Date: 03/11/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00003036-02

Claimant
Vehicle No : SGS6230E **Insured Vehicle No :** SGT7492D

Date of Loss: 25/09/2019 Nature of Claim: TP Claim No: 1201900028820

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS6230E		
Make & Model:	TOYOTA CAMRY, 2.4 ABS AIRBAG (A)	Engine No:	2AZE022989
Reg. Date:	20/03/2007 (Man. Year: 2007)	Chassis No:	MR053BK4007008268
Colour:	Silver	Odometer:	207562 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,564.90	1,013.00	3,551.90	77.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	480.00	2,330.00	82.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,374.90	1,493.00	5,881.90	79.76
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	7,374.90	1,200.00	6,174.90	83.73
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,527.45		
Global Sum Settlement (S\$)		1,500.00		

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 30/09/2019 Inspected At:

Ama Autocare Pte Ltd (HQ)
42 Toh Guan Road East, #01-79
Singapore 608583

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2020)
Parts:	143	TOYOTA CAMRY 2.4 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGS6230E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Not Necessary	1,149.00 FL	*- FL
2	2		*REAR BOOTLID HINGE	Not Necessary	214.00 FL	*- FL
3	1		*REAR BUMPER	Deformed	1,035.00 FL	*946.00 FL
4	1		*SET REAR BUMPER SIDE RETAINER	N/S Deformed/O/S Not Necessary	196.00 FL	*98.00 FL
5	1		*REAR BUMPER SPONGE	Not Necessary	461.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	738.20 FL	*- FL
7	2		*REAR BUMPER BRACKETS	Not Necessary	342.00 FL	*- FL
8	1		*REAR END PANEL	Not Necessary	982.00 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Not Necessary	216.00 FL	*- FL
10	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
11	1		*SET REAR END PANEL INNER GARNISH CLIPS	Not Necessary	70.00 FS	*- FS
12	1		*SET REVERSE SENSOR	Not Working	220.00 FS	*200.00 FS
13	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
14	1		*REAR NUMBER PLATE	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,898.20	1,274.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,333.30	261.00
Total Parts (\$\$)	4,564.90	1,013.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,200.00	200.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PATTS REPLACED	New	1,000.00	250.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUCTIONS	New	160.00	0.00
4	TO REMOVE AND REFIX /REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPONENT	New	180.00	0.00
5	TO REMOVE AND REPLACE REVERSE SENSORS	New	150.00	30.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (\$\$)			2,810.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >