

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: Dmpcsn3080171800
Repairer Reference: SMG 3159R(Bmw320i)
Date calculated: 21/10/2019 12:48 PM

Full Report
Registration: SMG3159R
Printed: 21/10/2019 4:15 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	Dmpcsn3080171800	Date of Incident:	20/09/19
Estimated Repair Time:	7	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	3 SERIES E90/91
Sub Model:	320 I
Model Sheet Number:	01 12 01
Registration:	SMG3159R
VIN number:	WBAVA76010NK18547
Odometer:	120840

Model Specs

4-DOOR	TWO COAT METALLIC	PREPARE OFF VEHICLE
--------	-------------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 12 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK	2.0	7.00
51 42 503	R + R L/R DOOR TRIM	6.0	21.00
51 48 570)	R + R L/R DOOR INSULATION	3.0	10.50
51 22 590)	R + R LEFT REAR DOOR LOCK	2.0	7.00
51 12 656	R + R REAR BUMPER	11.0	38.50
	INCLUDES: R + R TAILLAMPS		
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)	1.0	3.50
41 62 510	R + R TAILGATE	7.0	24.50
41 62 501	REPLACE TAILGATE (WITH TAILGATE REMOVED)	9.0	31.50
51 43 751	R + R L/R C-PILLAR TRIM	1.0	3.50
51 43 751	R + R R/R C-PILLAR TRIM	1.0	3.50
51 31 731)	RENEW REAR SCREEN	21.0	73.50
2353	ROOF PANEL REPAIR	25.0*	87.50
2711	REAR PANEL REPAIR	30.0*	105.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		9.90	119.0
Total of Labour			416.50

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR BUMPER NEW PART PAINT K1G/P	29.0	
	ROOF W/OUT ROOF FRAM REPAIR PAINTING >50%	39.0	
	REAR PANEL REPAIR PAINTING >50%	15.0	
	BOOTLID/TAILGATE REPAIR PAINTING >50%	27.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1G/P	117.90
2353	ROOF W/OUT ROOF FRAM REPAIR PAINTING >50%	63.99
2711	REAR PANEL REPAIR PAINTING >50%	12.64
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	38.71

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		110.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	14.30	143.0
Total	12 WU/h	14.30	171.6

Material Cost - Paint

New Part Painting - Plastic K1G/PUR
 Repair Painting
 Material-constant Metal Preparation
 Material-constant Plastic
Total

Price SGD
117.90
115.34
28.60
12.70
274.54

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2018-09-10/12	Price SGD
1877	L/R DOOR LOCK	51 22 7 202 147			192.00
2583	REAR BUMPER COVER	51 12 7 141 053			656.00
2613	TOWING EYE COVER	51 12 7 187 542			16.00
2702	REAR NUMBER PLATE	KNPL6			35.00
2931	BOOTLID/TAILGATE	41 62 7 254 425			632.00
2976	LOCK	51 24 7 840 617			80.00
3011	REAR BADGE	51 14 8 219 237			55.00
3151	REAR SCREEN	51 31 7 138 639			480.00
3160	REAR SCREEN BOND KIT	83 19 2 289 285			131.55
3162	CLEANER R1	83 19 2 211 217			26.15
3171	UP/COVER REAR SCREEN	51 31 7 061 970			86.00
3172	LOWER R/SCREEN TRIM	51 31 7 138 664			86.00
f: OEM Parts					
n: Non-OEM Parts					
u: Used parts					
Savings					0.00
Subtotal					2,475.70
Fixed Sundry Parts Price					100.00
Total					2,575.70

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	2,475.70	
Total Parts	100.00	2,575.70
Labour Time Base 12 WU/h		
Total 119.0 WU X 42.00 SGD/h	416.50	
Total of Labour		416.50
Paint Work Time Base 10 WU/h		
Labour Cost 143.0 WU X 42.00 SGD/h	600.60	
Material Cost	274.54	
Total Paint Including Material		875.14
Repair Cost Excludes GST		3,867.34
GST (+7.0%)		270.71
Repair Cost Included GST		4,138.05

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Finalised

Insurer Reference: Dmpcsn3080171800
Repairer Reference: SMG 3159R(Bmw320i)
Date calculated: 21/10/2019 2:21 PM

Full Report
Registration: SMG3159R
Printed: 21/10/2019 2:22 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	Dmpcsn3080171800	Date of Incident:	20/09/19
Estimated Repair Time:	7	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	BMW
Model:	3 SERIES E90/91
Sub Model:	320 I
Model Sheet Number:	01 12 01
Registration:	SMG3159R
VIN number:	WBAVA76010NK18547
Odometer:	120840

Model Specs

4-DOOR	TWO COAT METALLIC	PREPARE OFF VEHICLE
--------	-------------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK			
51 42 503	R + R L/R DOOR TRIM		2.0	7.00
51 48 570)	R + R L/R DOOR INSULATION		6.0	21.00
51 22 590)	R + R LEFT REAR DOOR LOCK		3.0	10.50
51 12 656	R + R REAR BUMPER		2.0	7.00
	INCLUDES: R + R TAILLAMPS		11.0	38.50
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)		1.0	3.50
41 62 510	R + R TAILGATE		7.0	24.50
41 62 501	REPLACE TAILGATE (WITH TAILGATE REMOVED)		9.0	31.50
51 43 751	R + R L/R C-PILLAR TRIM		1.0	3.50
51 43 751	R + R R/R C-PILLAR TRIM		1.0	3.50
51 31 731)	RENEW REAR SCREEN		21.0	73.50
2353	ROOF PANEL REPAIR		25.0*	87.50
Labour Cost				
Panel / Mechanical Labour		Hrs	WU	
		7.40	89.0	311.50
Total of Labour				311.50

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1G/P		29.0	
	ROOF W/OUT ROOF FRAM REPAIR PAINTING >50%		39.0	
	REAR PANEL REPAIR PAINTING >50%		15.0	
	BOOTLID/TAILGATE REPAIR PAINTING >50%		27.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1G/P	117.90
2353	ROOF W/OUT ROOF FRAM REPAIR PAINTING >50%	63.99
2711	REAR PANEL REPAIR PAINTING >50%	12.64
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	38.71

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			110.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	14.30	143.0	600.60
Total	12 WU/h	14.30	171.6	600.60

Material Cost - Paint

New Part Painting - Plastic K1G/PUR
 Repair Painting
 Material-constant Metal Preparation
 Material-constant Plastic
Total

Price SGD
117.90
115.34
28.60
12.70
274.54

Spare Parts

				prices as at 2018-09-10/12
Code	Description	Part Number	Supplier	Price SGD
1877	L/R DOOR LOCK	51 22 7 202 147		192.00
2583	REAR BUMPER COVER	51 12 7 141 053		656.00
2613	TOWING EYE COVER	51 12 7 187 542		16.00
2702	REAR NUMBER PLATE	KNPL6		35.00
2931	BOOTLID/TAILGATE	41 62 7 254 425		632.00
2976	LOCK	51 24 7 840 617		80.00
3011	REAR BADGE	51 14 8 219 237		55.00
3151	REAR SCREEN	51 31 7 138 639		480.00
3160	REAR SCREEN BOND KIT	83 19 2 289 285		131.55
3162	CLEANER R1	83 19 2 211 217		26.15
3171	UP/COVER REAR SCREEN	51 31 7 061 970		86.00
3172	LOWER R/SCREEN TRIM	51 31 7 138 664		86.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,475.70
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			2,575.70

Final Calculation

	SGD	SGD
Parts	2,475.70	
Fixed Sundry Parts Price	100.00	
Total Parts		2,575.70
Labour Time Base 12 WU/h		
Total 89.0 WU X 42.00 SGD/h	311.50	
Total of Labour		311.50
Paint Work Time Base 10 WU/h		
Labour Cost 143.0 WU X 42.00 SGD/h	600.60	
Material Cost	274.54	
Total Paint Including Material		875.14
Repair Cost Excludes GST		3,762.34
GST (+7.0%)		263.36
Repair Cost Included GST		4,025.70

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 21 October 2019 4:22 PM
To: 'Jouis'; SUR
Subject: RE: SMG 3159R-DOA: 20/9/2019 (CHINA TAIPING OD)

Dear Jouis,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jouis <jouis@jinauto.com.sg>
Sent: Monday, 21 October 2019 4:11 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SMG 3159R-DOA: 20/9/2019 (CHINA TAIPING OD)

Dear Veron

Ok we settle at S\$3000.00 , please offer through Merimen

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, 21 October 2019 3:39 PM
To: Jouis <jouis@jinauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SMG 3159R-DOA: 20/9/2019 (CHINA TAIPING OD)

Dear Jouis,

Offer Lump Sum \$3000 @ 6 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 3 October 2019 10:19 AM

To: jous <jous@jinauto.com.sg>; SUR <sur@lkkauto.com>

Subject: SMG 3159R-DOA: 20/9/2019 (CHINA TAIPING OD)

Dear Jouis,

As instructed by our client , please proceed to repair the **insured vehicle SMG 3159R Not exceeding Lump Sum \$3000/-, (Excess \$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2019 Sendback Est	27 Sep 2019 14:21 \$55,682.84	30 Sep 2019 13:08 Edit Adj Rpt	\$3,000.00 Edit Estimates	\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GORDEN KOH TIEN CHYE, ID: S7215328F, Tel: +6588158824		
Vehicle Reg. No.:	SMG3159R	Date of Loss:	20/09/2019 21:00 - :59 [161 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D204501-SMG3159R-CML	Policy/Cover Note No.:	DMPCSN3080171800 (Comprehensive)
		Excess:	\$0.00
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/10/2019]		
Driver/Custodian:	GORDEN KOH TIEN CHYE (/ Male), NRIC: S7215328F, Tel: +6588158824 Email:		

ASSOCIATED MAIL RECEIVED

- CHINA_TAIPING (03/10/2019): Alert - Adj Mandate Approved (\$3000.00) - SMG3159R - Claim Handler: Elaine Cheo...

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Claim Documents

SMG3159R (SNM19D204501-SMG3159R-CML)
OD

Sep 20 2019 9:00PM
[GORDEN KOH TIEN CHYE]
Jin Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	27/09/19 14:21	Repairer Estimates			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/19 14:31	Adjuster Immediate Advice			

1

Load HTM

1

Load HTM

Photos/Images

3 per page

No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	30/09/19 11:15	Before Repair Photo			
2	30/09/19 11:15	Before Repair Photo			
3	30/09/19 11:15	Before Repair Photo			
4	30/09/19 11:15	Before Repair Photo			
5	30/09/19 11:15	Before Repair Photo			
6	30/09/19 11:15	Before Repair Photo			
7	30/09/19 11:15	Before Repair Photo			
8	30/09/19 11:15	Before Repair Photo			
9	30/09/19 11:15	Before Repair Photo			
10	30/09/19 11:15	Before Repair Photo			
11	30/09/19 11:15	Before Repair Photo			
12	30/09/19 11:15	Before Repair Photo			
13	30/09/19 11:15	Before Repair Photo			
14	30/09/19 11:15	Before Repair Photo			
15	30/09/19 11:15	Before Repair Photo			
16	15/10/19 14:16	After Repair Photo			
17	15/10/19 14:16	After Repair Photo			
18	15/10/19 14:16	After Repair Photo			
19	15/10/19 14:16	After Repair Photo			
20	15/10/19 14:16	After Repair Photo			
21	15/10/19 14:16	After Repair Photo			
22	15/10/19 14:16	After Repair Photo			
23	15/10/19 14:16	After Repair Photo			
24	15/10/19 14:16	After Repair Photo			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/19 09:41	General View			
2	02/10/19 09:41	General View			
3	02/10/19 09:41	General View			
4	02/10/19 09:41	General View			
5	02/10/19 09:41	General View			
6	02/10/19 09:41	General View			
7	02/10/19 09:41	General View			
8	02/10/19 09:41	General View			
9	02/10/19 09:41	General View			
10	02/10/19 09:41	General View			
11	02/10/19 09:41	General View			
12	02/10/19 09:41	General View			

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

1

Load JPG

Assessment Reports

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	1 per page	Thumbnail	Print
13	02/10/19 09:41	General View		Load JPG	☒
14	02/10/19 09:41	General View		Load JPG	☒
15	02/10/19 09:41	General View		Load JPG	☒
16	02/10/19 09:41	General View		Load JPG	☒
17	02/10/19 09:41	General View		Load JPG	☒
18	02/10/19 09:41	General View		Load JPG	☒
19	02/10/19 09:41	General View		Load JPG	☒
20	02/10/19 09:41	General View		Load JPG	☒
21	02/10/19 09:41	General View		Load JPG	☒
22	02/10/19 09:41	General View		Load JPG	☒
23	02/10/19 09:41	General View		Load JPG	☒
24	02/10/19 09:41	General View		Load JPG	☒
25	02/10/19 09:41	General View		Load JPG	☒
26	02/10/19 09:41	General View		Load JPG	☒
27	02/10/19 09:41	General View		Load JPG	☒
28	02/10/19 09:41	General View		Load JPG	☒
29	02/10/19 09:41	General View		Load JPG	☒
30	02/10/19 09:41	General View		Load JPG	☒
31	02/10/19 09:41	General View		Load JPG	☒
32	02/10/19 09:41	General View		Load JPG	☒
33	02/10/19 09:41	General View		Load JPG	☒
34	02/10/19 09:41	General View		Load JPG	☒
35	02/10/19 09:41	General View		Load JPG	☒
36	02/10/19 09:41	General View		Load JPG	☒
37	02/10/19 09:41	General View		Load JPG	☒
38	02/10/19 09:41	General View		Load JPG	☒
39	02/10/19 09:41	General View		Load JPG	☒
40	02/10/19 09:41	General View		Load JPG	☒
41	02/10/19 09:41	Odometer Reading		Load JPG	☒
42	02/10/19 09:41	Chassis Number		Load JPG	☒
43	15/10/19 12:32	Dismantled Parts		Load JPG	☒
44	15/10/19 12:32	Dismantled Parts		Load JPG	☒
45	15/10/19 12:32	Dismantled Parts		Load JPG	☒
46	15/10/19 12:32	Dismantled Parts		Load JPG	☒
47	15/10/19 12:32	Dismantled Parts		Load JPG	☒
48	15/10/19 12:32	Dismantled Parts		Load JPG	☒
49	15/10/19 12:32	Dismantled Parts		Load JPG	☒
50	15/10/19 12:32	Dismantled Parts		Load JPG	☒
51	15/10/19 12:32	Dismantled Parts		Load JPG	☒
52	15/10/19 12:32	Dismantled Parts		Load JPG	☒
53	15/10/19 12:32	Dismantled Parts		Load JPG	☒
54	15/10/19 12:32	Dismantled Parts		Load JPG	☒
55	15/10/19 12:33	After Repair Photo		Load JPG	☒
56	15/10/19 12:33	After Repair Photo		Load JPG	☒
57	15/10/19 12:33	After Repair Photo		Load JPG	☒
58	15/10/19 12:33	After Repair Photo		Load JPG	☒
59	15/10/19 12:33	After Repair Photo		Load JPG	☒
60	15/10/19 12:33	After Repair Photo		Load JPG	☒

Documentation

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	1 per page	Thumbnail	Print
1	27/09/19 13:37	E-filed GIA report		Load PDF	
2	27/09/19 14:15	AUDATEX REPORT		Load PDF	
3	15/10/19 14:17	Purchase Invoice		Load PDF	

Assessment Reports

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/19 14:32	MARK ESTIMATE	Thumbnail	Print
2	02/10/19 14:35	AUDATEX	1 Load PDF	
3	03/10/19 10:03	SURVEYOR'S MARKING	1 Load PDF	
			1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset

Save

Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19017150/GVF3S2

Date: 23/10/2019

REFERENCE

Insured/Claimant: GORDEN KOH TIEN CHYE Policy No: DMPCSN3080171800

Date of Loss: 20/09/2019

Nature of Claim: OD

Claim No: SNM19D204501-SMG3159R-CML

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG3159R	Engine No:	A876H496N46B20BA
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBAVA76010NK18547
Reg. Date:	05/04/2006 (Man. Year: 2005)	Odometer:	121639 km
Colour:	Blue		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$10,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	265/30 ZR19	Rear Tyre Size:	265/30 ZR19
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,384.20	2,575.70	1,808.50	41.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,298.64	1,186.64	112.00	8.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,682.84	3,762.34	1,920.50	33.79
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	5,682.84	3,000.00	2,682.84	47.21
+ GST 7.00/7.00% (S\$)	397.80	210.00	187.80	47.21
Nett Amount (S\$)	6,080.64	3,210.00	2,870.64	47.21

INSPECTION

Date of Assignment:	30/09/2019	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	01/10/2019	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Oct 2019)	
Parts:	N/A	BMW 320I 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG3159R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL			
2	1		*L/R DOOR LOCK	Bent	4,384.20 F	*- F
3	1		*REAR BUMPER COVER	Deformed	-	*192.00 F
4	1		*TOWING EYE COVER	Cut	-	*656.00 F
5	1		*REAR BUMPER SUPPORT	Not Necessary	-	*16.00 F
6	1		*REAR NUMBER PLATE	Cracked	-	*- F
7	1		*BOOTLID / TAILGATE	Buckled	-	*35.00 F
8	1		*LOCK	Bent	-	*632.00 F
9	1		*REAR BADGE	Necessary	-	*80.00 F
10	1		*REAR SCREEN	Cracked	-	*55.00 F
11	1		*REAR SCREEN BOND KIT	Necessary	-	*480.00 F
12	1		*CLEANER R1	Necessary	-	*131.55 F
13	1		*UP/COVER REAR SCREEN	Cut	-	*26.15 F
14	1		*LOWER R/SCREEN TRIM	Cut	-	*86.00 F
15	1		*REVERSE SENSOR	Not Necessary	-	*86.00 F
16	1		*REVERSE SENSOR	Not Necessary	-	*- F
17	1		*REVERSE SENSOR	Not Necessary	-	*- F
18	1		*REVERSE CAMERA	Not Necessary	-	*- F
19	1		*FIXED SUNDRY PARTS PRICE	Necessary	-	*- F
						*100.00 F
Total Parts (S\$)						4,384.20 2,575.70

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL TOTAL LABOUR	New	423.50	311.50
2	TOTAL PAINT WORK	New	875.14	0.00
3	PAINT WORK: LABOUR COST.	New	-	600.60
4	PAINT WORK: MATERIAL COST.	New	-	274.54
Gross Labour Cost (S\$)			1,298.64	1,186.64

Report was unsubmitted during this print-out.

< END OF ESTIMATES >