

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 02 Oct 2019

Preliminary Advice

Vehicle No	: SMG3159R	Accident Date	: 20/09/2019
Make	: BMW 320I	Policy No.	: DMPCSN3080171800
Assignment Date	: 30/09/2019	Excess	: S\$0.00
Date of Inspection	: 01/10/2019	Est. Duration of Repair	: 6.00
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,682.84
Revised Amount	:S\$	3,947.84
Check Items (Estimated)	:S\$	1,735.00
Total	:S\$	5,682.84
Lump Sum Repair	:S\$	4,550.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	7,157.00
Salvage Value	:S\$	
Margin for Repair	:S\$	2,843.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$2,843.00