Jin Auto Services Pte Ltd #01-410/412, 14 Defu Lane 10 539195

Insurer Reference: Dmpcsn3080171800 Repairer Reference: SMG 3159R(Bmw320i) Date calculated: 27/09/2019 12:38 PM

Full Report Registration: SMG3159R Printed: 03/10/2019 9:50 AM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

KK LAU Dmpcsn3080171800 Currency:
Date of Incident:

SGD 20/09/19

Estimated Repair Time:

7

Hire Car Start:

Hire Car Start:

Actual Repair Days: **Vehicle Details**

Vehicle

Manufacturer:

BMW

Model:

3 SERIES E90/91

Sub Model:

320 I 01 12 01

Model Sheet Number: Registration:

SMG3159R

VIN number:

WBAVA76010NK18547

Odometer:

120840

Model Specs

4-DOOR

TWO COAT METALLIC

PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All

Underbody



Labour

Time Base 12 WU/h

Price = 42.00 SGD/h

Audatex System Using Manufacturer Times

Page 1 of 4

PRINT DATE 03/10/2019

Code	Description		WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
51 42 503	R + R L/R DOOR TRIM		6.0	21.00
51 48 570)	R + R L/R DOOR INSULATION	100	3.0	10,50
51 22 590)	R + R LEFT REAR DOOR LOCK		2.0	7.00
51 12 656	R + R REAR BUMPER		11.0	⊴ 38,50
	INCLUDES: R + R TAILLAMPS			West Even
51 12 552	R + R REAR BUMPER CARRIER (BUMPER REMOVED)		2.0	7.00
51 12 657	RENEW REAR BUMPÉR TRIM (BUMPER REMOVED)		1.0	3.50
41 62 510	R + R TAILGATE		7.0	24.50
41 62 501	**REPLACE TAILGATE	£	9.0	31.50
	(WITH TAILGATE REMOVED)	9	· 154	3. 2
51 43 751	R + R L/R C-PILLAR TRIM		1.0	3.50
51 43 751	R + R R/R C-PILLAR TRIM		1.0	3.50
51 31 731)	RENEW REAR SCREEN	A	21.0	73.50
2353	ROOF PANEL REPAIR	· 4. 7.	25.0*	87.50
2711	REAR PANEL REPAIR	.9	30.0*	105.00
	Labour Cost Panel / Mechanical Labour	Hrs 10.10	WU 121.0	423.50
	Total of Labour			423.50
Paint				
Paint Work	SYSTEM AZT	Tin	ne Basis	10 WU/h
Paint Work	SYSTEM AZT	Tin		10 WU/h
Paint Work Code	SYSTEM AZT Description - TWO COAT METALLIC	Tin	wu WU	Price SGD
	Description - TWO COAT METALLIC	Tin	WU	Price SGD
Code	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P	Tin	WU 29,0	Price SGD
	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING >50%	Tin	WU 29.0 39.0	Price SGD
Code	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P	Tin	WU 29,0	Price SGD
Code	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P. ROOF W/OUT ROOF FRAM REPAIR PAINTING >50% REAR PANEL REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50%	T in	29.0 39.0 15.0	Price SGD
Code	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P. ROOF W/OUT ROOF FRAM REPAIR PAINTING >50% REAR PANEL REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50%	Tin	29.0 39.0 15.0	Price SGD
Code Paint Materia Code	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING >50% REAR PANEL REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50% al Per Part Description	Tin	29.0 39.0 15.0	Price SGD
Code Paint Materia Code 2583	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% al Per Part Description REAR BUMPER NEW PART PAINT K1G/P	Tin	29.0 39.0 15.0	Price SGD Price SGD 117.90
Code Paint Materia Code 2583 2353	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING >50% REAR PANEL REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50% al Per Part Description	Tin	29.0 39.0 15.0	Price SGD
Code Paint Materia Code 2583	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% al Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50%	Tin	29.0 39.0 15.0	Price SGD Price SGD 117.90 63.99
Code Paint Materia Code 2583 2353 2711	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% Al Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50%		WU 29.0 39.0 15.0 27.0	Price SGD Price SGD 117.90 63.99 12.64 38.71
Code Paint Materia Code 2583 2353 2711	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% All Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% Labour Cost - Paint	Hrs	29.0 39.0 15.0	Price SGD Price SGD 117.90 63.99 12.64
Code Paint Materia Code 2583 2353 2711	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% al Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% Labour Cost - Paint Factor 42.00 SGD/h		WU 29.0 39.0 15.0 27.0	Price SGD Price SGD 117.90 63.99 12.64 38.71
Code Paint Materia Code 2583 2353 2711	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% All Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% Labour Cost - Paint Factor Time Paint	Hrs	WU 29.0 39.0 15.0 27.0 WU 110.0	Price SGD Price SGD 117.90 63.99 12.64 38.71 Price SGD
Code Paint Materia Code 2583 2353 2711	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% All Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% Labour Cost - Paint Factor Time Paint Preparation Main Work Metal	Hrs 2.50	WU 29.0 39.0 15.0 27.0 WU 110.0 25.0	Price SGD 24.53 Price SGD 117.90 63.99 12.64 38.71 Price SGD
Code Paint Materia Code 2583 2353 2711	REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING >50% REAR PANEL REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50% Al Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING >50% REAR PANEL REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50% BOOTLID/TAILGATE REPAIR PAINTING >50% Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic	Hrs 2.50 0.80	WU 29.0 39.0 15.0 27.0 WU 110.0 25.0 8.0	Price SGD 24.50 24.50 Price SGD 117.90 63.99 12.64 38.71 Price SGD 105.00 33.60
Code Paint Materia Code 2583 2353 2711	Description - TWO COAT METALLIC REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% All Per Part Description REAR BUMPER NEW PART PAINT K1G/P ROOF W/OUT ROOF FRAM REPAIR PAINTING > 50% REAR PANEL REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% BOOTLID/TAILGATE REPAIR PAINTING > 50% Labour Cost - Paint Factor Time Paint Preparation Main Work Metal	Hrs 2.50	WU 29.0 39.0 15.0 27.0 WU 110.0 25.0	Price SGD 24.53 Price SGD 117.90 63.99 12.64 38.71 Price SGD

N ite	۶
Material Cost - Paint	Price SGD
New Part Painting - Plastic K1G/PUR	117.90
Repair Painting	115.34
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	274.54

Spare	Pa	rts
--------------	----	-----

Code	Description	Part Number	Supplier	prices as at 201	8-09-10/11 Price SGD
	•			1900 program and 1900 p	
1877	L/R DOOR LOCK	51 22 7 202 147			240.00
2583	REAR BUMPER COVER	51 12 7 141 053	1eg.		820.00
2613	TOWING EYE COVER	51 12 7 187 542	16t =		20.00
2643	REAR BUMPER SUPPORT		7		315.00
2702	REAR NUMBER PLATE	KNPL6	- CO4) =		40.00
2931	BOOTLID/TAILGATE	41 62 7 254 425	_bnē		790.00
2976	LOCK	51 24 7 840 617			100.00
3011	REAR BADGE	51 14 8 219 237	/ NE(_{⊇, 7} 69.50
3151	REAR SCREEN	51 31 7 138 639	~ COA	er e	480.00
3160	REAR SCREEN BOND KIT		- 5461		131.55
3162 🖷 🐪 🗒 🐧	CLEANER R1	83 19 2 211 217			26.15
3171	UP/COVER REAR SCREEN	51 31 7 061 970	/ cmf		86.00
3172	LOWER RISCREEN TRIM	51 31 7 138 664	~ aut		86.00
1000	Reverse Sensor	Reverse Sensor	9		200.00
1001	Reverse Sensor	Reverse Sensor	j j		200.00
1002	Reverse Sensor	Reverse Sensor	Ò	1 (L.)	200.00
1003	reverse camera	reverse camera	4	**************************************	Pri480.00
f: OEM Parts	Savings		•		0.00
n: Non-OEM Parts	Subtotal				4,284.20
u: Used parts	Fixed Sundry Parts F	Price			100.00
	Total			. At a second	4,384.20
Final Calculat	tion				
		(Den)		SGD	SGD
€.		Cupsum V			
Parts			۱۵ ۵ -	4,284.20	
Fixed Sundry P	arts Price	1 cup com V	upany.	100.00	
Total Parts		~ · • ·	l i		4,384.20

rillai Calculation			
•	Cupcom report.	SGD	SGD
Parts		4,284.20	# .
Fixed Sundry Parts Price	1 cup com Many.	100.00	
Total Parts			4,384.20
Labour Time Base 12 WU/h	After paint photos.		
Total 121.0 WU X 42.00 SGD/h	A FILL I	423.50	
Total of Labour	Not Authorized.		423.50
	Mit Awillery !.		
Paint Work Time Base 10 WU/h	700 }	600.60	
Labour Cost 143.0 WU X 42.00 SGD/h Material Cost	C. Wind	274.54	
Total Paint Including Material	ano Diony	2/4.54	875.14
	01/10/19		
Repair Cost Excludes GST	01/6/19.		5,682.84
GST (+7.0%)			397.80
Repair Cost Included GST	LKK Auto Consultants hence notify	7	6,080.64
	the Repairer of the following:		And the second of the second o

Audatex System Using Manufacturer Times

- To resurvey before/after spray painting
- To display damaged part(s) dur. , resurvey
- Parts prices are subject to confirmation
- Third party spacey is 90 of Without Prejudice basis
 No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

PRINT DATE 03/10/2019

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.