

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19017161/BBA3Q2

**Date:** 20/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994303

**Claimant**  
**Vehicle No :** SME6720K **Insured Vehicle No :** GBD3855K

Date of Loss: 25/09/2019 Nature of Claim: TP Claim No: 6235750432SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME6720K		
Make & Model:	HONDA MOBILIO SV, 1.5 CVT (A)	Engine No:	L15Z12100047
Reg. Date:	10/04/2015 (Man. Year: 2015)	Chassis No:	MRHDD4870FP000033
Colour:	White	Odometer:	150077 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,801.76	2,750.64	6,051.12	68.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,100.00	1,860.00	62.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,761.76</b>	<b>3,850.64</b>	<b>7,911.12</b>	<b>67.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,761.76</b>	<b>2,950.00</b>	<b>8,811.76</b>	<b>74.92</b>
<b>+ Loss of Use (7.0 x S\$80.00/day) (S\$)</b>		560.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>3,539.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,500.00</b>		

### INSPECTION

Date of Assignment: 30/09/2019

Date Inspected: 30/09/2019 Inspected At:

Team Autopro Pte Ltd - Sin Ming (HQ)  
160 SIN MING DRIVE #02-12 SIN  
MING AUTOCITY  
Singapore 575722

Estimated Period of Repair: 7.0 days

**Adjuster:** Lim Teow Guan**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Broken	672.50 FL	*324.10 FL
2	2		*HEADLAMP LOWER BRACKET	Not Applicable	150.40 FL	*- FL
3	1		*FRONT BUMPER	Cut	1,240.00 FL	*620.50 FL
4	2		*FRONT BUMPER RETAINER	Necessary	346.00 FL	*90.00 FL
5	2		*FRONT BUMPER BRACKET	Not Applicable	150.40 FL	*- FL
6	1		*FRONT BUMPER TOP GRILLE	Not Damaged	452.50 FL	*- FL
7	1		*FRONT BUMPER BOTTOM GRILLE	Broken	388.40 FL	*298.20 FL
8	1		*FRONT BUMPER CHROME GARNISH	Not Damaged	156.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	775.80 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP RH	Broken	466.00 FL	*410.00 FL
11	1		*FRONT BUMPER FOG LAMP GARNISH RH	Dislodged	175.00 FL	*175.00 FL
12	1		*FRONT FENDER RH	Dented	822.60 FL	*560.00 FL
13	1		*FRONT FENDER INNER SHIELD RH	Torn	253.90 FL	*81.80 FL
14	1		*FRONT WHEEL HUB GARNISH	Not Damaged	106.00 FL	*- FL
15	1		*FRONT FENDER TOP CHROME GARNISH	Not Damaged	98.00 FL	*- FL
16	1		*FRONT LOWER ARM RH	Not Damaged	697.70 FL	*- FL
17	1		*FRONT KNUCKLE ARM RH	Dented	881.90 FL	*366.20 FL
18	1		*FRONT KNUCKLE ARM BEARING RH	Dented	758.90 FL	*150.00 FL
19	1		*FRONT SHOCK ABSORBER RH	Not Damaged	390.00 FL	*- FL
20	1		*FRONT SHOCK ABSORBER BUSH RH	Not Damaged	112.00 FL	*- FL
21	1		*FRONT SHOCK ABSORBER MOUNTING RH	Not Damaged	145.70 FL	*- FL
22	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*FRONT BUMPER TOP GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
24	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Damaged	50.00 FS	*- FS
25	1		*FRONT FENDER INNER SHIELD CLIPS	Not Applicable	50.00 FS	*- FS
26	1		*ALLOY RIM (LOCAL REPAIR)	Damaged	800.00 FS	*200.00 FS
27	1		*TYRE	Not Damaged	250.00 FS	*- FS
28	1		*SUNDRIES	Not Applicable	80.00 FS	*- FS
29	1		*FRONT FENDER SEALANT	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,649.70</b>	<b>3,365.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>1,847.94</b>	<b>615.16</b>
<b>Total Parts (\$)</b>	<b>8,801.76</b>	<b>2,750.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	R&R UNDERCARRIAGE	New	200.00	80.00
2	PANEL BEATING	New	1,200.00	500.00
3	RUST PROOFING	New	100.00	30.00
4	SPRAY PAINTING	New	1,200.00	400.00
5	CHECK WIRING	New	80.00	30.00
6	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
7	WHEEL ALIGNMENT	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,960.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >