

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III19017162/GGA3Q2**Date:** 24/06/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SGV145S	<b>Insured Vehicle No :</b>	SHA1221Y
Date of Loss: 27/09/2019	Nature of Claim: TP	Claim No: MCT19090675

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGV145S</b>		
Make & Model:	HONDA STREAM, 1.8 (A)	Engine No:	R18A1734847
Reg. Date:	30/05/2007 (Man. Year: 2007)	Chassis No:	RN61031108
Colour:	Red	Odometer:	258405 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Linglong 5 mm	Rear Left Side:	Linglong 5 mm
Front Right Side:	Linglong 5 mm	Rear Right Side:	Linglong 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	11,722.32	6,109.99	5,612.33	47.88	
Miscellaneous Items	11.00	11.00	0.00	0.00	
Labour	1,910.00	1,260.00	650.00	34.03	
Paintwork Labour	1,200.00	1,000.00	200.00	16.67	
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>14,843.32</b>	<b>8,380.99</b>	<b>6,462.33</b>	<b>43.54</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>			
	<b>(S\$)</b>	14,843.32	5,800.00	9,043.32	60.93
<b>+ GST 7.00/7.00% (S\$)</b>		1,039.03	406.00	633.03	60.93
<b>Nett Amount (S\$)</b>	<b>15,882.35</b>	<b>6,206.00</b>	<b>9,676.35</b>	<b>60.93</b>	
<b>+ Car Rental (11.5 x S\$92.11/day) (S\$)</b>		1,059.27			
<b>Nett Liability (S\$)</b>		<b>7,265.27</b>			

INSPECTION

Date of Assignment:	30/09/2019	Present Location:	Tan Lim Motor Pte Ltd (Defu)
Date Inspected:	30/09/2019	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	7.0 days		

**Adjuster:** XING GUO QIANG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2019)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGV145S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*bonnet	Buckled	880.00 FL	*616.90 FL
2	1		*Bonnet lock	Bent	107.10 FL	*68.50 FL
3	1		*Bonnet lock stay	Not Necessary	12.30 FL	*- FL
4	1		*Bonnet lock cable	Not Necessary	55.10 FL	*- FL
5	1		*Bonnet insulator	Deformed	110.20 FL	*110.20 FL
6	8		*Bonnet insulator clips	Necessary	30.00 FL	*30.00 FL
7	1		*Bonnet underseal weatherstrip with clip - outer	Twisted	22.90 FL	*22.90 FL
8	4		*Bonnet underseal weatherstrip inner clip	Necessary	61.20 FL	*61.20 FL
9	1		*Bonnet stopper LH	Missing	7.80 FL	*7.80 FL
10	1		*front support panel	Bent	581.40 FL	*466.30 FL
11	1		*Bumper, front	Cracked	1,132.20 FL	*635.70 FL
12	1		*front bumper beam	Not Necessary	275.40 FL	*- FL
13	2		*Bumper retainer, front	Cracked	49.80 FL	*49.80 FL
14	8		*front bumper fastener clips	Necessary	28.00 FL	*28.00 FL
15	1		*front bumper reinforcement	Bent	350.00 FL	*268.90 FL
16	1		*front bumper fog lamp	Distorted	413.10 FL	*286.70 FL
17	1		*front bumper fog lamp garnish	Cracked	55.60 FL	*55.60 FL
18	1		*front bumper centre air grille	Torn	107.60 FL	*85.60 FL
19	1		*front bumper lower splashshield cover	Torn	165.70 FL	*165.70 FL
20	6		*front bumper lower splashshield cover clips	Necessary	22.80 FL	*22.80 FL
21	1		*headlamp	O/S Cracked	1,760.00 FL	*589.30 FL
22	2		*headlamp lower bracket	Cracked	111.80 FL	*73.00 FL
23	1		*radiator assy	Bent	1,866.60 FL	*1,284.20 FL
24	1		*radiator coolant	Necessary	20.00 FS	*20.00 FS
25	1		*radiator fan assy	Damaged	620.00 FL	*98.70 FL
26	1		*radiator grille	Cracked	214.20 FL	*195.54 FL
27	1		*radiator grille emblem badge	Necessary	30.60 FL	*30.60 FL
28	1		*radiator grille garnish	Cracked	244.80 FL	*210.35 FL
29	4		*radiator grille clips	Necessary	14.00 FL	*14.00 FL
30	2		*radiator top mounting bracket	Bent	25.00 FL	*25.00 FL
31	2		*radiator top mounting bushing	Necessary	9.80 FL	*9.80 FL
32	1		*radiator bottom mounting bushing	Necessary	12.60 FL	*12.60 FL
33	1		*radiator top hose	Not Necessary	36.70 FL	*- FL
34	1		*radiator expansion tank	Deformed	39.80 FL	*39.80 FL
35	1		*horn high pitch	Not Necessary	73.50 FL	*- FL
36	1		*horn low pitch	Not Necessary	61.20 FL	*- FL
37	1		*aircon condenser	Bent	1,040.40 FL	*826.40 FL
38	2		*aircon condenser top mounting bracket	Bent	15.60 FL	*15.60 FL
39	2		*aircon condenser top mounting bushing	Necessary	8.40 FL	*8.40 FL
40	2		*aircon condenser bottom bushing	Necessary	9.20 FL	*9.20 FL
41	1		*aircon hose - condenser to compressor	Not Necessary	275.40 FL	*- FL
42	1		*aircon pipe - condenser to evaporator	Not Necessary	214.20 FL	*- FL
43	1		*aircon fan assy	Damaged	566.00 FL	*85.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*windscreen washer tank	Not Necessary	107.10 FL	*- FL
45	1		*windscreen washer tank motor	Not Necessary	82.60 FL	*- FL
46	1		*windscreen washer tank cover	Not Necessary	55.00 FL	*- FL
47	1		*exhaust manifold heat shield	Not Necessary	76.50 FL	*- FL
48	1		*air cleaner tank - intake hose	Not Necessary	85.70 FL	*- FL
49	1		*wiper tank	Deformed	89.70 FL	*89.70 FL
50	1		*wiper tank motor	Not Necessary	90.90 FL	*- FL
51	1		*o/s front shock absorber	Not Necessary	413.10 FL	*- FL
52	1		*o/s front shock absorber top mount	Not Necessary	89.90 FL	*- FL
53	1		*lower arm	Not Necessary	350.00 FL	*- FL
54	1		*o/s engine mount top	Torn	199.70 FL	*199.70 FL
55	1		*o/s engine mount rear	Not Necessary	208.10 FL	*- FL
56	1		*n/s gearbox mount	Not Necessary	198.70 FL	*- FL
57	1		*o/s front fender	Buckled	550.00 FL	*550.00 FL
58	1		*o/s front fender inner cowling	Torn	90.90 FL	*90.90 FL
59	5		*o/s front fender inner cowling clips	Necessary	21.00 FL	*21.00 FL
60	1		*o/s front fender top garnish	Deformed	55.80 FL	*55.80 FL
61	4		*o/s front fender top garnish clips	Necessary	15.20 FL	*15.20 FL
62	1		*front number plate	Cut	80.00 FS	*40.00 FS
63	1		*front number plate garnish	Cut	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,627.90</b>	<b>7,622.49</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	2,905.58	1,512.50
<b>Total Parts (S\$)</b>	<b>11,722.32</b>	<b>6,109.99</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	Putty and spray painting of the affected portion.	New	1,200.00	1,000.00
<b>Labour Items</b>				
2	Towing charges.	New	80.00	50.00
3	To check electrical lighting concerned.	New	60.00	30.00
4	To check steering geometry and computer wheel alignment.	New	80.00	0.00
5	To rust-proofing of the affected areas.	New	150.00	60.00
6	To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	New	150.00	0.00
7	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New	120.00	80.00
8	To remove and refit radiator	New	70.00	40.00
9	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	1,200.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,110.00</b>	<b>2,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >