

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017165/T1PS3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLG7887H	Insured Vehicle No :	SHB4355U
Date of Loss: 25/09/2019	Nature of Claim: TP	Claim No: MCT19090628

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7887H		
Make & Model:	LEXUS ES250, 2.5 Luxury (ASV60) (A)	Engine No:	2ARF227929
Reg. Date:	26/08/2016 (Man. Year: 2016)	Chassis No:	JTHBJ1GG302093307
Colour:	Beige	Odometer:	42461 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,344.20	19,045.80	8,298.40	30.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,650.00	4,730.00	3,920.00	45.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,994.20	23,775.80	12,218.40	33.95
Approved Total (Overridden) (S\$)		21,300.00		
(S\$)	35,994.20	21,300.00	14,694.20	40.82
+ GST 7.00/7.00% (S\$)	2,519.59	1,491.00	1,028.59	40.82
Nett Amount (S\$)	38,513.79	22,791.00	15,722.79	40.82
+ Car Rental (14.0 x S\$150.00/day + 7.00% GST) (S\$)		2,247.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		25,045.45		
Global Sum Settlement (S\$)		25,000.00		

INSPECTION

Date of Assignment:	27/09/2019	
Date Inspected:	30/09/2019 Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
		No 8 Fourth Lok Yang Road
		Singapore 629705
Estimated Period of Repair:	14.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$116,000.00(est) less LTA Rebate: \$76,946.00(est) = Nett Value :\$39,054.00(est)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2020)
Parts:	143	LEXUS ES250 2.5 Luxury (ASV60) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7887H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	935.00 FL	*935.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	65.00 FL	*65.00 FL
4	1		*HEADLAMP RH	Cut	6,115.00 FL	*6,115.00 FL
5	1		*FRONT FENDER RH	Bent	1,314.00 FL	*1,314.00 FL
6	1		*FRONT FOG LAMP CHROME RH	Not Necessary	98.00 FL	*- FL
7	1		*FRONT FENDER SHIELD RH	Not Necessary	285.00 FL	*- FL
8	10		*FRONT FENDER SHIELD CLIP RH	Not Necessary	55.00 FL	*- FL
9	1		*BOOT LID	Bent	865.00 FL	*865.00 FL
10	1		*BOOT LID LOGO	Necessary	75.00 FL	*75.00 FL
11	1		*BOOT LID LOGO LEXUS	Necessary	56.00 FL	*56.00 FL
12	1		*BOOT LID LOGO ES 250	Necessary	68.00 FL	*68.00 FL
13	1		*BOOT LID CHROME	Cut	348.00 FL	*348.00 FL
14	1		*BOOT LID INSULATOR	Not Necessary	650.00 FL	*- FL
15	10		*BOOT LID INSULATOR CLIP	Not Necessary	55.00 FL	*- FL
16	2		*BOOT LID HINGE R/L	Repair	402.00 FL	*- FL
17	1		*BOOT LID LOCK (WITH MOTOR)	Cut	1,297.20 FL	*1,297.20 FL
18	1		*BOOT LID LAMP R/L	N/S Cut / O/S Not Necessary	1,082.00 FL	*541.00 FL
19	1		*REAR BUMPER	Deformed	766.00 FL	*766.00 FL
20	10		*REAR BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
21	2		*REAR BUMPER SIDE RETAINER R/L	Necessary	196.00 FL	*196.00 FL
22	1		*REAR BUMPER REFLECTOR R/L	N/S Cracked / O/S Not Necessary	120.00 FL	*60.00 FL
23	1		*REAR BUMPER SPONGE	Cracked	107.00 FL	*107.00 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	381.00 FL	*381.00 FL
25	4		*REVERSE SENSOR	Not Working (2 PCS ONLY)	1,364.00 FL	*682.00 FL
26	1		*TAILLAMP R/L	N/S Cracked / O/S Not Necessary	1,210.00 FL	*605.00 FL
27	1		*TAILLAMP LOWER BRACKET R/L	N/S Distorted / O/S Not Necessary	190.00 FL	*95.00 FL
28	1		*EXHAUST TAILPIPE CHROME LH	Dented	313.00 FL	*313.00 FL
29	2		*TAILLAMP WHITE CLIP R/L	Necessary	11.80 FL	*11.80 FL
30	1		*REAR LH FENDER	Repair	1,460.00 FL	*- FL
31	1		*REAR WINDSCREEN MOULDING	Not Necessary	78.00 FL	*- FL
32	1		*BOOT LID WEATHERSTRIP	Twisted	226.00 FL	*226.00 FL
33	1		*REAR BUMPER SIDE COVER LH	Missing	12.00 FL	*12.00 FL
34	1		*REAR END PANEL	Bent	752.00 FL	*752.00 FL
35	1		*REAR END PANEL TOP GARNISH	Deformed	323.00 FL	*323.00 FL
36	1		*SPARE TYRE COMPARTMENT	Buckled	907.00 FL	*907.00 FL
37	1		*SPARE TYRE COMPARTMENT BOARD	Not Necessary	658.00 FL	*- FL
38	1		*SPARE TYRE PANEL LH	Repair	298.00 FL	*- FL
39	1		*SPARE TYRE SPONGE R/L		470.00 FL	*235.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				N/S Cracked / O/SNot Necessary		
40	1		*REAR LICENCE PLATE W CASING	Bent	45.00 FS	*45.00 FS
41	1		*REAR WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
42	1		*FRONT DOOR RH (NPA)	Repair	0.00 FS	*- FS
43	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
44	1		*SPARE TYRE UNDER COVER	Deformed	415.00 FL	*415.00 FL
45	1		*EXHAUST SILENCER LH	Bent	1,258.00 FL	*1,258.00 FL
46	1		*EXHAUST FRONT PIPE LH	Not Necessary	2,919.00 FL	*- FL
47	1		*EXHAUST MIDDLE PIPE LH	Bent	995.00 FL	*995.00 FL
48	1		*EXHAUST ALUMINIUM	Bent	235.00 FL	*235.00 FL
49	1		*SPARE TYRE COMPARTMENT NUT	Cracked	48.00 FL	*48.00 FL
50	1		*REAR TOW HOOK PANEL	Bent	396.00 FL	*396.00 FL
51	1		*LH EXHAUST MTG RUBBER RH	Distorted	45.00 FL	*45.00 FL
52	1		*LH EXHAUST MTG RUBBER LH	Distorted	45.00 FL	*45.00 FL
53	1		*COMPARTMENT INSULATION PAD	Necessary	214.00 FL	*214.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 30,373.00 21,157.00
- List Item Discount on L Items 10.00/10.00% (S\$) 3,028.80 2,111.20

Total Parts (S\$) 27,344.20 19,045.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT ,CUT ,WELD ,RE-ALIGN & REPLACE DAMAGED PARTS OF FRONT AFFECTED AREA	New	750.00	500.00
2	PANEL BEAT ,CUT ,WELD ,RE-ALIGN & REPLACE DAMAGED PARTS OF REAR AFFECTED AREA	New	3,250.00	2,000.00
3	PUTTY ,BLEND AND SPRAY PAINT ON FRONT AFFECTED AREA	New	1,000.00	500.00
4	PUTTY ,BLEND AND SPRAY PAINT ON REAR AFFECTED AREA	New	2,000.00	1,250.00
5	CHECK WIRING ,RE-ALIGN HEADLAMPS & TAILLAMPS ,ENSURE PROPER FUNCTIONING	New	80.00	40.00
6	REMOVE & REINSTALL CUSHIONS ,SEATS ,BACKRESTS ,INNER TRIM ,GARNISH ,ROOF LINING AND /OR UPHOLSTERY TO FACILITATE REPAIR	New	180.00	60.00
7	REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE REPAIR	New	180.00	0.00
8	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	150.00	60.00
9	REMOVE AND REINSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK	New	150.00	0.00
10	DISMANTLE AND TRANSFER BOOT LID FITTINGS & MECHANISMS TO NEW BOOT LID	New	180.00	60.00
11	REMOVE AND REPLACE EXHAUST PIPE /SYSTEM TO FACILITATE REPAIR	New	250.00	100.00
12	REMOVE AND REINSTALL REVERSE SENSOR	New	120.00	30.00
13	REMOVE AND REINSTALL REAR REVERSE CAMERA	New	120.00	30.00
14	CAVITY TREATMENT ON NEW PARTS	New	120.00	60.00
15	CONDUCT WATER SEEPAGE TEST	New	120.00	40.00
Gross Labour Cost (\$)			8,650.00	4,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >