MWRA18175731 / Weames Automotive Pte Ltd - Leng Kee ENTRY DATE & TIME: 23/09/2019 14:24 SUBMITTED BY: Michelle Ong Siew Bee

## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the independent of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report 23/09/2019 14:24

Date Of Accident 20/09/2019 11:55

Exact Location Of Accident JALAN KEBUN PISANG

Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE** 

Vehicle Registration Number SKP7717E

Insured/Policyholder

Name Of Registered Owner MOHD REDZWA BIN MAT NOR

NRIC NO S6922718Z Email Address

NOEMAIL Mobile Phone No.

(LOCAL) +65-96996466 Alternative Phone No Others-96996466

Vehicle Particulars

Manufacturer VOLVO

Model V40-1.6 V40 CROSS COUNTRY T4 (A)

Exact Purpose for which vehicle was being used at SOCIAL

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No. Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100389455-05

Cover Note Number

Driver

Name of Driver SUZANA BINTE SUJAT

NRIC No S7725435H Date Of Birth 02/09/1977 Occupation INDOOR Date Of Driving Pass 02/02/2008

Driving Experience 11 YEARS AND 7 MONTHS

Gender FEMALE Mobile Number

(LOCAL) +65-96996466

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

Postcode

29 MILTONIA CLOSE

#07-18 768062

SPOUSE

Was driver an employee of the Insured's Company NO

if No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle.

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

FIRE, EXPLOSION OR LIGHTNING

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

1 NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

NO

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

3

Number of Passengers (Including Driver)

Passenger 1

Name:

: NUR AMIRAH BINTI MOHD RAMLAN

Gender:

: Female

Passenger 2

Name:

: RAHAYU ABDUL RAHMAN

Gender:

: Female

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE

ROAD: 32 YISHUN ST 81, POSTCODE: 768456, COUNTRY: Police Station Address

SINGAPORE

Police Station Contact

TEL NO: 1800-8522999 - FAX NO: 68522239

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO. T/201909020/2152.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### Accident Sketch Plan





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999

2013 Report No. T/20190920/2152


CONTINUATION OF REPORT

## Brief Details.

I was driving my car bearing plate number SKP7717E at the junction of Balestier Road and Jalan Kebun Limas Suddenly, there was smoke coming from my car and subsequently, fire emerged. All of us managed to get out of the car in time and no one was injured.

Police and SCDF came and assisted us reference A/20190920/0047 under AlO Ho Chiow Yee.

#### Accident Sketch Plan



Accident Sketch Plan

# **AUTOMAX SURVEY**

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile : 9855 6879 Email : automaxsurvey@gmail.com

Registration No. 53110062J

Invoice no.:

TP19050009

Date:

23 July 2019

Billing To: Kuganesh S/O Berabaharan

c/o Eng Soon Painting SVC Blk 4 Yew Tee Ind Est 393 - J

Woodlands Road Singapore 677969

Vehicle no: AY2000T

Model: YAMAHA SNIPER T150

ITEM	DESCRIPTION		AMOU	NT
1	Date of Inspection : 29 May 2019 Copies of the inspection / survey report Correspondence, postages and etc.		\$	790.00
2	Photography Services  Develop photographs  Storage of digital photographs			
3.	To submit report by hand.			
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.			
5	Transportation Charges			
6	Reinspection Charges			
		TOTAL:	\$	790.00

Notes:

Official Stamp

<sup>1.</sup> All cheque payment should be "crossed" and made payable to "Automax Survey".

<sup>2.</sup> Please contact us if there are further enquiries on the involce.

# **AUTOMAX SURVEY**

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110 Mobile: 9855 6879 Email: automaxsurvey@gmail.com Registration No. 53110062J

Report Ref: TP19050009

Date:

23 July 2019

Kuganesh S/O Berabaharan c/o Eng Soon Painting SVC Blk 4 Yew Tee Ind Est 393 - J Woodlands Road Singapore 677969

THIRD PARTY SURVEY ACCIDENT OCCCURED ON 20 May 2019

Workshop Name and Address

Eng Soon Painting SVC Blk 4 Yew Tee Ind Est 393 - J Woodlands Road Singapore 677969

As per your instruction dated

29 May 2019

with regard to the above matter.

We have carried out a physicial inspection on the said

AY2000T

We enclosed herewith our report and findings as follows:

#### 1. VEHICLE PARTICULARS

Registration No : AY2000T

: YAMAHA SNIPER T150

-Year / Capacity: Mar 2019 / 149 cc

shassis No : MH3UG0740K0152635

Engine No: G3E6E0484403

Mileage: n.a km Colour: Multi colour

2. TYRES CONDITION

Size

FRONT: REAR : 70/90/R17 70/90/R17

Pirelli Pirelli

Made

Balance 9.00 mm 9.00 mm

Rim Sport Sport

# **AUTOMAX SURVEY**

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile : 9855 6879 Email : automaxsurvey@gmail.com Registration No. 53110062J

#### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the <u>ALL</u> portion(s). For more detail of the damages, please see photograph attached.

- 4. Estimated normal period of repair: 15 working days to complete
- In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- Should you discover any discrepancy in the report, please kindly notify us <u>within 1 week</u>, or the report will be treated as correct.

#### sclaimer

he rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to be surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of amages must not be used in any circumstances for comprarison with other vehicles and/or other accidents in other accidents.

Vehicle Number : AY2000T

# SPARE PARTS

QTY	PARTS DESCRIPTION	ARTS DESCRIPTION CONDITION Estimation (S\$)		Our Revised Estimation (S\$)		
	<u>List Items</u>					
1 pc	Headlamp assy with casing	electronically shocked	\$	435.00	\$	435.00/ 3/
1 pc	Front mudguard	deformed	\$	108.00	\$	108.00/
1 pc	Rim	bent/distorted	\$	450.00	\$	450.00 280
1 set	Front fork cover	grazed/deformed	\$	94.00	\$	94.00 X V
2 pcs	Front fork tube	bent/distorted	\$	222.00	\$	222.00/
2 pcs	Front fork oil seal	grazed/deformed	\$	104.00	\$	104.00 60/
1 pc	Handle bar	bent/distorted	\$	228.00	\$	228.00 /25
1 set	Handle bar grip	bent/distorted	\$	88.00	\$	88.00 XSV
2 pcs	Handle bar balance ( PH)	grazed/deformed	\$	108.00	\$	108.00 30/
1.nc	Master cylinder assy	grazed/deformed	\$	88.00	\$	88.00
. et	Ignition switch assy	shocked	\$	435.00	\$	435.00 × 1/
1 pc	Meter assy	electronically shocked	\$	458.00	\$	458.00 × JV
1 pc	Meter casing	grazed/deformed	\$	156.00	\$	156.00 /00/
1 pc	Horn switch	grazed/deformed	\$	70.00	\$	70.00 × 540
1 pc	Starter switch	grazed/deformed	\$	92.00	\$	92.00 × 1/0
1 pc	Crankshaft cover	grazed/deformed	\$	255.00	\$	255.00 × JV
1 pc	Main stand	bent/distorted	\$	128.00	\$	128.00× SV
1 pc	Front wheel shaft	bent/distorted	\$	68.00	\$	68.00 45/
1 pc	Brake pedal	bent/distorted	\$	65.00	\$	65.00
1 pc	Front fork bracket	bent/distorted	\$	115.00	\$	
1 pc	Steering cone	bent/distorted	\$	145.90	\$	115.00 X SV
1 pc	Steering cone bearing	bent/distorted	\$		- 3:	145.90/
1 pc	Kick starter		200	85.00	\$	85.00× JV
1 pc	Body frame assy	bent/distorted bent - repair	\$	86.00 1,880.00	\$	86.00 X √

QTY	PARTS DESCRIPTION		CONDITION	(3.5%	orkshop stimation (S\$)		ur Revised Stimation (S\$)
1	List Items						
2 pcs	Rear side fairing cover		cracked	\$	188.00	\$	188.00 94
1 pc	Shift gear pedal		distorted	\$	68.00	\$	68.00 / S
1 pc	Throttle handle		distorted	\$	62.00	\$	62.00
1 pc	Brake lever		distorted	\$	52.00	\$	52.00 35/
1 pc	Clutch lever		distorted	\$	52.00	\$	52.00 XSV
1 pc	Inner cover		grazed/deformed	\$ \$ \$ \$	118.00	\$	118.00 /
1 pc	Front inner frame cover		grazed/deformed	\$	225.00	\$	225.00 /
2 pcs	Front side cover		grazed/deformed	\$	340.00	\$	340.00 × J
1 pc	Front side cover with signal lamp		grazed/deformed	\$	280.00	\$	280.00 2001
		1	Parts Sub-Total	\$	6,913.90	\$	5,033.90
		Discount	0.00%	\$	*	\$	144
	AVOCCOT		1940.90	\$	6,913.90	\$	5,033.90
GuiCl	e Number: AY2000T		- 10%		7348.A	D	
SF	PARE PARTS		1746-81				

ΣΤΥ	PARTS DESCRIPTION	CONDITION		forkshop stimation (S\$)	Our Revised Estimation (S\$)
	Special Nett Items				 
pc	Number plate	Necessary	\$	45.00	\$ 45.00 /5
blts	Fork oil	Necessary	\$	60.00	\$ 60.00 40
blts	Brake oil	Necessary	\$	60.00	\$ 60.00 30
pc	Meter cable	grazed/loose	\$	65.00	\$ 65.00 X
рс	Throttle cable	grazed/loose	\$ \$	65.00	\$ 65.00 ×
set	Wiring harness	open cicruit	\$	250.00	\$ 250.00 X
рс	Horn assy	open cicruit	\$	65.00	\$ 65,00 ×
рс	Tyre	deformed	\$	200.00	\$ 200.00 ×
pc	Brake disc	wraped	\$	183.00	\$ 183.00 /65
pc	Front basket	wraped	\$	88.00	\$ 88.00 X^
	ERP assy	Necessary	\$	58.00	\$ 58.00XA
		Special Nett Sub-Total	\$	1,139.00	\$ 1,139.00
		Spare Parts Total	\$	8,052.90	\$ 6,172.90

## LABOUR COST

S/No	JOB DESCRIPTIONS	Vorkshop stimation (S\$)	0.73	our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 8,052.90	\$	6,172.90
1	Labour charges to repair and panel beat body frame structure cutting/welding and replacing the above mentioned parts.	\$ 3,000.00	\$	2,600.00 30
2	Transport	\$ 60.00	\$	60:00 40
3	To replace wiring harness system incl checking	\$ 240.00	\$	220.00 30
	To tuff coat affected areas	\$ 180.00	\$	150.00 20
5	To respray affected areas	\$ 1,600.00	\$	1,400.00 20
	Total	\$ 13,132,90	\$	10,602.90
	The repairer has agreed to undertake the repair under a lump Sum Basis. We have further adjusted the amount to lump	13567	994	590
	Sum Repair of:	\$ 9,000.00		

Fong Kok Heng Qualified Appraiser

P- 1746.81 N- 259 L- 590 2586.81

4 apr days

L/S- 2069-44 = 2050

# ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J Woodlands Road Singapore 677978 Tel: 6760 6271 Fax: 6764 6676

KUGANESH S/O BERABAHARAN
BLOCK 62 TEBAN GARDENS ROAD
#25-629
SINGAPORE 600062

DATE: 23/07/19

DEAR SIRS

ACCIDENT DATE: 20/05/19 FINAL REPAIR BILL TO AY 2000 T

DOLLARS: NINE THOUSAND ONLY



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	ationale Des Experts En Autom	obile
NDIA I	NTERNATIONA	L INSURANCE PL	Ref : CS3/III1900953	8/Etd3s2-1
4 CEC 05-02	CIL STREET IOB BUILDING	SINGAPORE 049711	Date: 03-10-2019 Code: III2	
		Policy Particula	ers :- THIRD PARTY CLAI	M
In	nsured Veh.	SHC 8532T	Veh. Inspected	AY 2000T
F	Policy No.	MCOM0015	Coverage (\$)	0.00
	Claim No.	MCT19050569	Excess (\$)	0.00
-	Assign From	STANLEY LAI	Assign Date	30/09/2019
253	A STATE OF THE STA	Vehicle Pa	articulars & Condition	
n	Make & Model	YAMAHA SNIPER T150	c.c	150
E	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3UG0740K0152635	Colour	GREEN
	Odometer	7896	Steering	IN ORDER
E	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
VISI SI		Con	ditions of Tyres	
		Size	Make	Balance
ı	R/H Front Tyre	70/90-17	DUNLOP	7 mm
ı	L/H Front Tyre			mm
	R/H Rear Tyre	120/70-17	DUNLOP	7 mm
	L/H Rear Tyre			mm
. 180			iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT PORTION AND O/S	BODY.
5.	DAWAGES SEE L		neral Information	
	Accident Date	20/05/2019	Inspection Date	29/05/2019
-	Survey held at	ENG SOON PAINTING SVO		
		BLK 4 YEW TEE IND EST 3 WOODLANDS ROAD SINGAPORE 677969		雄
5a.			Remarks	
	A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A ICE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.	CONTRACTOR OF STATE	Estin	nate Days of Repair	ELECTRICAL PROPERTY.
	ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	4 Working Da	iys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AY 2000T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP ASSY WITH CASING	SERVICEABLE	435.00	
1	FRONT MUDGUARD	DEFORMED	108.00	108.00
-1	RIM	BENT / DISTORTED	450.00	280.00
1	SET FRONT FORK COVER	SERVICEABLE	94.00	62
2	FRONT FORK TUBE	BENT / DISTORTED	222.00	222.00
2	FRONT FORK OIL SEAL	GRAZED / DEFORMED	104.00	60.00
1	HANDLE BAR	BENT / DISTORTED	228.00	125.00
1	SET HANDLE BAR GRIP	SERVICEABLE	88.00	-
2	HANDLE BAR BALANCE	O/S GRAZED / DEFORMED	108.00	30.00
1	MASTER CYLINDER ASSY	GRAZED / DEFORMED	88.00	88.00
1	SET IGNITION SWITCH ASSY	SERVICEABLE	435.00	
1	METER ASSY	SERVICEABLE	458.00	
1	METER CASING	GRAZED / DEFORMED	156.00	100.00
1	HORN SWITCH	SERVICEABLE	70.00	
1	STARTER SWITCH	SERVICEABLE	92.00	
1	CRANKSHAFT COVER	SERVICEABLE	255.00	
1	MAIN STAND	SERVICEABLE	128.00	
1	FRONT WHEEL SHAFT	BENT / DISTORTED	68.00	45.00
1	BRAKE PEDAL	BENT / DISTORTED	65.00	65.00
1	FRONT FORK PEDAL	SERVICEABLE	115.00	
1	STEERING CONE	BENT / DISTORTED	145.90	145.90
1	STEERING CONE BEARING	SERVICEABLE	85.00	
-	KICK STARTER	SERVICEABLE	86.00	
1	BODY FRAME ASSY	TO REPAIR SEE LABOUR	1,880.00	
2	REAR SIDE FAIRING COVER	CRACKED 1PC ONLY	188.00	94.00
1	SHIFT GEAR PEDAL	SERVICEABLE	68.00	)
	THROTTLE HANDLE	SERVICEABLE	62.00	

Report Ref No. CS3/III19009538/Etd3s2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	BRAKE LEVER	DISTORTED	52.00	35.00
1	I	SERVICEABLE	52.00	-
1	HMMED COVER	GRAZED / DEFORMED	118.00	118.00
1	IERONT INNER FRAME COVER	GRAZED / DEFORMED	225.00	225.00
2	FRONT SIDE COVER	SERVICEABLE	340.00	0.0000000000000000000000000000000000000
577	ERONT SIDE COVER WITH SIGNAL LAMP	GRAZED / DEFORMED	280.00	
	LESS 10% DISCOUNT		7,348.90	-194.09 1,746.81
			7,348.90	1,740.01
	SPECIAL NETT ITEMS		45.00	15.00
	NUMBER PLATE (SN)	NECESSARY	60.00	1 37.55
;	BLTS FORK OIL (SN)	NECESSARY	60.00	
	BLTS BRAKE OIL (SN)	NECESSARY	7.717	3600000
9	1 METER CABLE (SN)	SERVICEABLE	65.00	
150	1 THROTTLE CABLE (SN)	SERVICEABLE	65.00	
1 8	1 SET WIRING HARNESS (SN)	SERVICEABLE	250.0	
	1 HORN ASSY (SN)	SERVICEABLE	65.0	
1	1 TYRE (SN)	SERVICEABLE	200.0	1000000
1	1 BRAKE DISC (SN)	WARPED	183.0	
	1 FRONT BASKET (SN)	NOT NECESSARY	88.0	2
	1 ERP ASSY (SN)	NOT NECESSARY	58.0	
			1,139.0	250.00
	LABOUR		0.000	300.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT BODY FRAME STRUCTURE CUTTING / WELDING AND REPLACING THE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF BODY FRAME ASSY.		3,000.0	
	TRANSPORT.		60.0	784 J. S.
	TO REPLACE WIRING HARNESS SYSTEM INCL CHECKING.		240.0	
	TO TUFF COAT AFFECTED AREAS.	1	180.0	00 20.0



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	
	TO RESPRAY AFFECTED AREAS.		1,600.00	200.00
	TO RESTRICT A LEGICAL TO THE STATE OF THE ST		5,080.00	590.00
	GRAND TOTAL		13,567.90	2,586.81

	100 A CONTRACTOR OF THE PROPERTY OF THE PROPER
RECOMMENDED COST OF LUMP SUM REPAIRS	2,050.00
(TO ITS PRE-ACCIDENT CONDITION)	R 10 10 10 10 10 10 10 10 10 10 10 10 10

Report Ref No. CS3/III19009538/Etd3s2-1

Car.

CHEN TSUE YEE

**Automotive Assessor** 

St. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.