

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19017216/T1SF3E2

Date: 21/01/2020

REFERENCE

Insured/Claimant: JULIUS LIM KOON KIAT Policy No: 29109660
Date of Loss: 01/09/2019 Nature of Claim: OD Claim No: 604720

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF7653J
Make & Model: VOLKSWAGEN GOLF GTI, 2.0 L 5DR 5K19V3 (A) Engine No: CHH297543
Reg. Date: 23/11/2018 (Man. Year: 2018) Chassis No: WVVZZZAUZKW014027
Colour: Grey Odometer: 0 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$145,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	66,117.57	57,505.17	8,612.40	13.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	30,415.50	18,428.00	11,987.50	39.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	96,533.07	75,933.17	20,599.90	21.34
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	95,033.07	74,433.17	20,599.90	21.68
+ GST 7.00/7.00% (S\$)	6,652.31	5,210.32	1,441.99	21.68
Nett Amount (S\$)	101,685.38	79,643.49	22,041.89	21.68

INSPECTION

Date of Assignment: 01/10/2019

Date Inspected: 30/09/2019 Inspected At:

Volkswagen Group Singapore Pte Ltd
(Tuas)
No: 17 Tuas Ave 9
Singapore 639197

Estimated Period of Repair: 26.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2020)
Parts:	144	VOLKSWAGEN GOLF GTI 2.0 L 5DR 5K19V3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF7653J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRAME FOR SLIDING ROOF OP SUNROOF FRAME	Distorted	5,306.49 FS	*5,306.49 FS
2	1		*ALL PURPOSE CLEANER	Necessary	64.76 FS	*64.76 FS
3	1		*SPECIAL LUBRICANT	Necessary	85.25 FS	*85.25 FS
4	1		*2K-GLASS GLUE APPLICATION	Necessary	88.57 FS	*88.57 FS
5	1		*MOULDED HEADLINING TITANI ROOFLINING	Deformed	647.55 FS	*647.55 FS
6	4		*CLAMP	Necessary	3.28 FS	*3.28 FS
7	1		*TRIM WITH EMBLEM TITANIUM (2PCS)	Necessary	21.79 FS	*21.79 FS
8	2		*GRAB HANDLE FOLDING TITAN FRT ROOF TOP HANDLE	Not Necessary	167.99 FS	*- FS
9	2		*ROOF GRAB HANDLE TITANIUM ROOF TOP HANDLE REAR	Not Necessary	181.76 FS	*- FS
10	1		*HEAD AIRBAG UNIT LHS CURTAIN AIRBAG	Activated	954.60 FS	*954.60 FS
11	1		*HEAD AIRBAG UNIT RHS CURTAIN AIRBAG	Activated	954.60 FS	*954.60 FS
12	1		*DASHBOARD TITANIUM BLACK	Deformed	2,124.06 FS	*2,124.06 FS
13	1		*AIRBAG UNIT AIRBAG (PASSENGER)	Cut	2,784.78 FS	*2,784.78 FS
14	1		*KNEE AIRBAG UNIT	Activated	1,027.64 FS	*1,027.64 FS
15	1		*AIRBAG UNIT FOR STEERING	Cut	1,794.02 FS	*1,794.02 FS
16	1		*STEERING COLUMN MULTI-SWI S/WHEEL SPRING LOCK	Activated	356.22 FS	*356.22 FS
17	1		*AIR BAG CONTROL MODULE AIRBAG CONTROL UNIT	Activated	1,160.38 FS	*1,160.38 FS
18	1		*CRASH SENSOR FOR AIRBAG	Activated	173.60 FS	*173.60 FS
19	1		*A-PILLAR TRIM WITH TWEETE A-PILLAR TRIM COVER LH	Deformed	290.82 FS	*290.82 FS
20	1		*THREE-POINT AUTOMATIC SEA SEAT BELT LH	Activated	652.61 FS	*652.61 FS
21	1		*THREE-POINT AUTOMATIC SEA SEAT BELT RH	Activated	652.61 FS	*652.61 FS
22	1		*SEAT BELT HEIGHT ADJUSTER (2PCS)	Activated	149.17 FS	*149.17 FS
23	1		*WINDSHIELD GLASS FRT W/SCREEN	Cracked	645.64 FS	*645.64 FS
24	1		*COVER SECTION W/SCREEN SEAL	Necessary	63.48 FS	*63.48 FS
25	1		*RAIN AND HUMIDITY SENSOR	Necessary	355.77 FS	*355.77 FS
26	1		*2K-GLASS GLUE APPLICATION	Necessary	88.57 FS	*88.57 FS
27	1		*ADHESIVE REMOVER	Necessary	83.33 FS	*83.33 FS
28	1		*PRIMER	Necessary	18.66 FS	*18.66 FS
29	1		*ACTIVATOR FOR PRECOATED W	Necessary	17.01 FS	*17.01 FS
30	1		*APPLICATOR (2PCS)	Necessary	13.65 FS	*13.65 FS
31	1		*ERP STICKER	Necessary	7.06 FS	*7.06 FS
32	1		*WATER DEFLECTOR STRIP BLA W/SCREEN MLDG LH	Deformed	21.38 FS	*21.38 FS
33	1		*COVER FOR PLENUM CHAMBER WIPER COWLING LH	Cracked	67.69 FS	*67.69 FS
34	1		*HOOD FRT BONNET	Bent	751.74 FS	*751.74 FS
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*FLAP HINGE LH	Bent	45.56 FS	*45.56 FS
36	1		*FLAP HINGE RH	Bent	45.56 FS	*45.56 FS
37	1		*LOCKING CATCH LATCH	Bent	50.04 FS	*50.04 FS
38	1		*HOOD CATCH LOCK	Bent	180.28 FS	*180.28 FS
39	1		*CABLE HOOD LATCH LOCK CABLE	Distorted	22.51 FS	*22.51 FS
40	2		*HEXAGON SOCKET OVAL HEAD	Necessary	2.28 FS	*2.28 FS
41	1		*DECKLID WEATHERSTRIP BONNET SEAL LH	Necessary	41.96 FS	*41.96 FS
42	1		*DECKLID WEATHERSTRIP BONNET SEAL RH	Not Necessary	41.96 FS	*- FS
43	2		*JOUNCE BUMPER STOP BUFFER	Necessary	11.22 FS	*11.22 FS
44	1		*HOOD SILENCER BONNET INSULATOR	Deformed	131.59 FS	*131.59 FS
45	1		*COVER FOR BUMPER PRIMED	Deformed	780.22 FS	*780.22 FS
46	1		*RETAINER FOR SPOILER SATI	Distorted	125.66 FS	*125.66 FS
47	1		*LICENSE PLATE BRACKET SAT	Deformed	54.39 FS	*54.39 FS
48	1		*RIVET (6PCS)	Necessary	2.29 FS	*2.29 FS
49	1		*IMPACT BEAM REINFORCEMENT	Bent	423.24 FS	*423.24 FS
50	8		*SCREW HEX.HD.	Necessary	23.44 FS	*23.44 FS
51	1		*FOAM INSERT	Cracked	27.90 FS	*27.90 FS
52	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Necessary	13.81 FS	*13.81 FS
53	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Necessary	13.81 FS	*13.81 FS
54	1		*SUPPORT PART BUMPER INNER BRACKET LH	Deformed	36.35 FS	*36.35 FS
55	1		*COVER SATIN BLACK INNER BRACKET COVER LH	Deformed	40.58 FS	*40.58 FS
56	1		*SUPPORT PART BUMPER INNER BRACKET RH	Deformed	36.35 FS	*36.35 FS
57	1		*COVER SATIN BLACK INNER BRACKET COVER RH	Deformed	40.58 FS	*40.58 FS
58	1		*SENSOR BRACKET	Necessary	8.34 FS	*8.34 FS
59	1		*SENSOR BRACKET	Necessary	8.34 FS	*8.34 FS
60	1		*SENSOR BRACKET	Necessary	8.40 FS	*8.40 FS
61	1		*SENSOR BRACKET (2PCS)	Necessary	15.81 FS	*15.81 FS
62	1		*SENSOR BRACKET	Necessary	8.40 FS	*8.40 FS
63	1		*SENSOR BRACKET (2PCS)	Distorted (1Pc Only)	237.05 FS	*118.53 FS
64	1		*SENSOR BRACKET (4PCS)	Not Working (2Pcs Only)	474.11 FS	*237.05 FS
65	6		*SEAL RING SATIN BLACK	Necessary	5.10 FS	*5.10 FS
66	1		*HARNES FOR BUMPER SENSOR WIRE HARNES	Torn	60.06 FS	*60.06 FS
67	1		*2K-PLASTIC ADHESIVE	Necessary	53.49 FS	*53.49 FS
68	1		*BONDING AGENT FOR PLASTIC	Necessary	40.97 FS	*40.97 FS
69	1		*SOUND BAFFLE ENGINE LOWER COVER	Torn	98.90 FS	*98.90 FS
70	1		*RADIATOR GRILLE BLACK / SAT	Cracked	404.62 FS	*404.62 FS
71	1		*VW SIGN BLACK / BRIGHT CHRO	Cracked	60.40 FS	*60.40 FS
72	1		*COOLING AIR GRILL SATIN B CENTRE LOWER GRILLE	Cracked	82.16 FS	*82.16 FS
73	1		*COOLING AIR GRILL SATIN B LHS FOG LAMP GRILLE	Cracked	60.93 FS	*60.93 FS
74	1		*COOLING AIR GRILL SATIN B FOG LAMP GRILLE RH	Cut	60.93 FS	*60.93 FS
75	1		*COVER PART FOR BUMPER SAT FOG LAMP BRACKET LH	Cut	43.37 FS	*43.37 FS
76	1		*COVER PART FOR BUMPER SAT FOG LAMP BRACKET RH	Distorted	43.37 FS	*43.37 FS
77	1		*END PLATE SATIN BLACK LH	Distorted	17.66 FS	*17.66 FS
78	1		*END PLATE SATIN BLACK RH	Distorted	17.66 FS	*17.66 FS
79	1		*LED HEADLIGHT H/LAMP LH	Cracked	2,155.74 FS	*2,155.74 FS
80	1		*LED HEADLIGHT H/LAMP RH	Cracked	2,155.74 FS	*2,155.74 FS
81	2		*POWER MODULE FOR MAIN LIG	Not Necessary	520.27 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
82	2		*CONTROL UNIT FOR LIGHT CO	Distorted	421.33 FS	*210.66 FS
83	1		*CAP H/LAMP CAP LH	Not Necessary	20.89 FS	*- FS
84	1		*CAP H/LAMP CAP RH	Not Necessary	20.89 FS	*- FS
85	1		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING (2PCS)	Distorted	25.85 FS	*25.85 FS
86	1		*BOLT HEX.HD. (4PCS)	Necessary	4.29 FS	*4.29 FS
87	1		*LED FOG LAMP LH	Cracked	633.74 FS	*633.74 FS
88	1		*LED FOG LAMP RH	Cracked	633.74 FS	*633.74 FS
89	2		*FLAT CONTACT HOUSING WITH FOG LAMP WIRE HOUSING	Distorted	12.82 FS	*12.82 FS
90	1		*LOCK CARRIER WITH MOUNTIN	Cracked	790.55 FS	*790.55 FS
91	1		*SUPPORT FOR LOCK CARRIER	Bent	28.79 FS	*28.79 FS
92	1		*GUIDE BUMPER CENTRE BRACKET	Distorted	26.37 FS	*26.37 FS
93	1		*CROSS SUPPORT H/LAMP TOP PANEL LH	Bent	23.93 FS	*23.93 FS
94	1		*CROSS SUPPORT H/LAMP TOP PANEL RH	Bent	23.93 FS	*23.93 FS
95	1		*REFRIGERANT CONDENSER WIT	Bent	485.44 FS	*485.44 FS
96	1		*REFRIGERANT LINE A/C HOSE LONG	Bent	340.37 FS	*340.37 FS
97	1		*REFRIGERANT LINE A/C HOSE SHORT	Bent	340.37 FS	*340.37 FS
98	1		*REFRIGERANT LINE A/C PIPE LONG	Bent	427.46 FS	*427.46 FS
99	1		*BRACKET A/C HOSE BRACKET	Bent	14.14 FS	*14.14 FS
100	1		*BRACKET FOR EXTERNAL TEMP	Distorted	0.84 FS	*0.84 FS
101	1		*AMBIENT TEMPERATURE SENSO TEMPER SENSOR	Missing	27.57 FS	*27.57 FS
102	1		*CHARGE AIR COOLER	Bent	347.57 FS	*347.57 FS
103	1		*PRESSURE HOSE LOWER RH	Not Necessary	88.62 FS	*- FS
104	1		*CONNECTING PIPE PRESSURE HOSE LOWER LH	Distorted	118.00 FS	*118.00 FS
105	1		*PRESSURE PIPE CENTRE	Distorted	141.67 FS	*141.67 FS
106	1		*RADIATOR	Bent	445.41 FS	*445.41 FS
107	1		*WATER HOSE WITH QUICK COU RADIATR LOWER HOSE RH	Distorted	161.83 FS	*161.83 FS
108	1		*WATER PUMP ELECTR WATER PUMP	Not Necessary	634.28 FS	*- FS
109	1		*BRACKET FOR ADDITIONAL WA BRACKET ELECTR WATER PUMP	Not Necessary	9.55 FS	*- FS
110	1		*WATER TUBE	Deformed	57.10 FS	*57.10 FS
111	1		*WATER HOSE WITH QUICK COU	Deformed	58.53 FS	*58.53 FS
112	1		*WATER HOSE WITH QUICK COU RADIATOR TOP HOSE LH	Deformed	96.11 FS	*96.11 FS
113	1		*AIR DUCT AIR GUIDE LH	Deformed	15.32 FS	*15.32 FS
114	1		*AIR DUCT AIR GUIDE RH	Deformed	15.32 FS	*15.32 FS
115	1		*SEALING STRIP LH	Necessary	10.15 FS	*10.15 FS
116	1		*SEALING STRIP RH	Necessary	10.15 FS	*10.15 FS
117	1		*BUSHING RADIATOR LOWER BUSH	Distorted	6.55 FS	*6.55 FS
118	2		*BRACKET RADIATOR BRACKET	Distorted	42.74 FS	*42.74 FS
119	2		*COOLANT CONCENTRATE	Necessary	61.68 FS	*61.68 FS
120	1		*ELECTRIC FAN WITH FAN COW	Cracked	992.34 FS	*992.34 FS
121	1		*COVER ENGINE TOP COVER	Cut	91.30 FS	*91.30 FS
122	1		*THERMOSTAT WATER PUMP HOUSING	Cracked	542.66 FS	*542.66 FS
123	1		*WATER PUMP	Not Necessary	211.64 FS	*- FS
124	1		*OIL SUMP-LOWER PART	Not Necessary	196.47 FS	*- FS
125	1		*ENGINE OIL SUMP UPPER PAR	Bent	261.95 FS	*261.95 FS
126	1		*GASKET FOR OIL PAN	Necessary	31.64 FS	*31.64 FS
127	1		*SEAL RING (2PCS)	Necessary	12.05 FS	*12.05 FS
128	1		*SILICONE ADHESIVE SEALANT	Necessary	36.73 FS	*36.73 FS
129	1		*HEXAGON SOCKET FLAT HEAD (20PCS)	Necessary	20.88 FS	*20.88 FS
130	1		*FILTER ELEMENT WITH GASKE OIL FILTER	Necessary	26.86 FS	*26.86 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
131	1		*MOTOR OIL (5PCS)	Necessary	141.88 FS	*141.88 FS
132	1		*COVER AIR INTAKE TOP COVER	Cracked	19.70 FS	*19.70 FS
133	1		*AIR DUCT AIR INTAKE TOP HOUSING	Cracked	38.58 FS	*38.58 FS
134	1		*AIR DUCT AIR INTAKE CENTRE HOUSING	Cracked	23.24 FS	*23.24 FS
135	1		*AIR DUCT AIR INTAKE LOWER HOUSING	Cracked	13.37 FS	*13.37 FS
136	1		*AIR CLEANER	Cracked	237.14 FS	*237.14 FS
137	1		*CAP	Distorted	8.34 FS	*8.34 FS
138	1		*WATER DRAIN HOSE AIR CLEANER WATER DRAIN HOSE	Not Necessary	17.68 FS	*- FS
139	1		*INTAKE MANIFOLD	Cracked	409.12 FS	*409.12 FS
140	1		*THROTTLE BODY	Cracked	543.73 FS	*543.73 FS
141	1		*FLAT CONTACT HOUSING WITH THROTTLE BODY WIRE HOUSING	Distorted	5.85 FS	*5.85 FS
142	1		*PRESSURE SENSOR	Not Necessary	93.79 FS	*- FS
143	1		*FLAT CONTACT HOUSING WITH SENSOR WIRE HOUSING	Not Necessary	3.77 FS	*- FS
144	1		*BATTERY TRAY	Cracked	76.36 FS	*76.36 FS
145	1		*BATTERY FILLED AND CHARGE	Deformed	321.73 FS	*321.73 FS
146	1		*BATTERY PROTECTION COVER	Deformed	54.48 FS	*54.48 FS
147	1		*SHEER BOLT SELF-LOCKING (4PCS)	Necessary	4.55 FS	*4.55 FS
148	1		*FLAT CONTACT HOUSING WITH ENGINE ECU WIRE HOUSING	Not Necessary	33.49 FS	*- FS
149	1		*FLAT CONTACT HOUSING WITH ENGINE ECU WIRE HOUSING	Not Necessary	33.38 FS	*- FS
150	1		*HOUSING FOR CENTR. ELEC. S FUSE BOX HOUSING	Not Necessary	35.14 FS	*- FS
151	1		*END PLATE FUSE BOX PLATE	Cracked	9.96 FS	*9.96 FS
152	1		*HORN LH	Deformed	71.53 FS	*71.53 FS
153	1		*HALTER FUER SIGNALHORN HORN BRACKET LH	Bent	15.13 FS	*15.13 FS
154	1		*HORN RH	Deformed	65.80 FS	*65.80 FS
155	1		*HALTER FUER SIGNALHORN HORN BRACKET RH	Bent	15.99 FS	*15.99 FS
156	2		*FLAT CONNECTOR HOUSING WI HORN WIRE HOUSING	Necessary	14.60 FS	*14.60 FS
157	1		*AIR CONDITIONER COMPRESSO A/C COMPRESSOR	Bent	1,488.33 FS	*1,488.33 FS
158	1		*OIL FOR REFRIGERANT COMPR	Necessary	124.14 FS	*124.14 FS
159	1		*WASH WATER RESERVOIR WIPER TANK	Deformed	76.75 FS	*76.75 FS
160	1		*GASKET	Necessary	1.31 FS	*1.31 FS
161	1		*WINDSCREEN WASHER SYSTEM PUMP	Distorted	86.70 FS	*86.70 FS
162	1		*WINDSHIELD CLEANER CONCEN	Necessary	11.38 FS	*11.38 FS
163	1		*ENGINE MOUNTING	Distorted	174.69 FS	*174.69 FS
164	1		*GEARBOX MOUNTING	Cracked	139.23 FS	*139.23 FS
165	1		*BRACKET GEAR BOX MTG BRACKET	Bent	102.62 FS	*102.62 FS
166	1		*BOLT HEX. HD. WITH SHOUL (4PCS)	Necessary	12.73 FS	*12.73 FS
167	1		*PENDULUM SUPPORT GEAR BOX LOWER SUPPORT	Bent	48.97 FS	*48.97 FS
168	1		*BOLTHEX.HD.WITH SHOUL.	Necessary	4.20 FS	*4.20 FS
169	1		*SCREW HEX. HD.	Necessary	2.40 FS	*2.40 FS
170	1		*6-SPEED DUAL CLUTCH GEARB	Cracked	8,702.78 FS	*8,702.78 FS
171	3		*DUAL CLUTCH GEARBOX OIL	Necessary	136.56 FS	*136.56 FS
172	1		*SUB-FRAME	Bent	361.65 FS	*361.65 FS
173	1		*SET BONDED RUBBER BUSHE	Necessary	117.02 FS	*117.02 FS
174	1		*HEXAGON FLANGE SCREW (4PCS)	Necessary	23.10 FS	*23.10 FS
175	1		*STABILIZER COMPLETE	Not Necessary	255.28 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
176	1		*DRIVE SHAFT WITH CONSTANT DRIVE SHAFT LH	Bent	703.95 FS	*703.95 FS
177	1		*STEERING GEAR	Not Necessary	2,127.40 FS	*- FS
178	2		*RETAINING CLIP	Not Necessary	6.68 FS	*- FS
179	1		*ABS UNIT WITH ELEC. CONTR. ABS ASSY	Not Necessary	2,623.06 FS	*- FS
180	1		*BRACKET FOR ABS UNIT	Not Necessary	25.52 FS	*- FS
181	1		*BRAKE FLUID	Necessary	30.84 FS	*30.84 FS
182	1		*COVER PLATE CHASSIS MEMBER END PLATE RH	Bent	57.90 FS	*57.90 FS
183	1		*COVER PLATE CHASSIS MEMBER END PLATE LH	Not Necessary	57.90 FS	*- FS
184	1		*SIDE MEMBER LH	Not Necessary	320.49 FS	*- FS
185	1		*COVER PLATE FOR CROSS MEM	Not Necessary	275.14 FS	*- FS
186	1		*MOUNTING BRACKET FOR GEAR	Not Necessary	43.11 FS	*- FS
187	1		*FENDER RH	Bent	410.16 FS	*410.16 FS
188	1		*CROSS SUPPORT FENDER BRACKET RH	Necessary	20.98 FS	*20.98 FS
189	4		*RIVETTED CAP NUT	Necessary	3.28 FS	*3.28 FS
190	1		*WHEELHOUSE LINER RHS FENDER LINER UPPER	Torn	110.15 FS	*110.15 FS
191	1		*WHEELHOUSE LINER RHS FENDER LINER LOWER	Torn	62.42 FS	*62.42 FS
192	1		*FENDER LH	Bent	410.16 FS	*410.16 FS
193	1		*CROSS SUPPORT FENDER BRACKET LH	Necessary	20.98 FS	*20.98 FS
194	1		*WHEELHOUSE LINER FENDER LINER UPPER LH	Torn	121.18 FS	*121.18 FS
195	1		*WHEELHOUSE LINER FENDER LINER LOWER LH	Torn	62.42 FS	*62.42 FS
196	1		*SOUND ABSORBER FOR FENDER FENDER ELEMENT LH	Necessary	31.47 FS	*31.47 FS
197	1		*EMBLEM LHS FENDER EMBLEM GTI	Necessary	56.58 FS	*56.58 FS
198	1		*EMBLEM RHS FENDER EMBLEM GTI	Necessary	56.58 FS	*56.58 FS
199	1		*SIDE WINDOW A-PILLAR GLASS LH	Deformed	79.59 FS	*79.59 FS
200	1		*2K-GLASS GLUE APPLICATION	Necessary	88.57 FS	*88.57 FS
201	1		*PRIMER	Necessary	18.66 FS	*18.66 FS
202	1		*ACTIVATOR FOR PRECOATED W	Necessary	17.01 FS	*17.01 FS
203	1		*APPLICATOR (2PCS)	Necessary	13.65 FS	*13.65 FS
204	1		*DOOR LHS FRT DOOR	Bent	1,443.81 FS	*1,443.81 FS
205	1		*DOOR SEAL	Necessary	67.82 FS	*67.82 FS
206	1		*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	27.93 FS	*27.93 FS
207	1		*BLACKVUE 2CH CAMERA 16GB	Cut	255.56 FS	*255.56 FS
208	1		*FRT NUMBER PLATE	Missing	80.00 FS	*80.00 FS
209	1		*ALTERNATOR	Cracked	932.80 FS	*932.80 FS
210	1		*PRESSURE PIPE FRT	Bent	127.96 FS	*127.96 FS
211	1		*PRESSURE RADIATOR	Distorted	93.79 FS	*93.79 FS
212	1		*PRESSURE SENSOR WIRE HOUSING	Cracked	5.74 FS	*5.74 FS
213	1		*GROMMET (4PCS)	Necessary	7.49 FS	*7.49 FS
214	1		*WATER PUMP	Dented	24.19 FS	*24.19 FS
215	1		*BATTERY EARTH LINE	Distorted	48.07 FS	*48.07 FS
216	1		*HARNESS FOR BATTERY	Distorted	86.18 FS	*86.18 FS
217	1		*HARNESS FOR ALTERNATOR	Distorted	94.80 FS	*94.80 FS
218	1		*FLAT HOUSING WIRE	Distorted	7.30 FS	*7.30 FS
219	1		*STRAINER	Distorted	8.29 FS	*8.29 FS
220	1		*HEXAGON SOCKET HEAD PANEL (20PCS)	Necessary	5.62 FS	*5.62 FS
221	1		*LHS MEMBER	Bent	956.71 FS	*956.71 FS
222	1		*WEBBING ADHESIVE TAPE	Necessary	15.70 FS	*15.70 FS
223	1		*HOSE	Distorted	9.99 FS	*9.99 FS
224	1		*PRESSURE HOSE UPPER	Distorted	55.58 FS	*55.58 FS
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
225	1		*V-RIBBED BELT	Cut	40.55 FS	*40.55 FS
226	1		*WIRE HOUSING BRACKET	Cracked	7.16 FS	*7.16 FS
227	1		*SUB FRAME BRACKET	Bent	12.23 FS	*12.23 FS
228	1		*WIRE HARNESS HOLDER	Distorted	9.96 FS	*9.96 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **66,117.57** **57,505.17**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	DIAGNOSTIC AND PROGRAMMING	New	360.00	360.00
3	LEAKED CHECK, VACUUM & REGAS	New	238.00	238.00
4	R&R ROOFLINING	New	1,425.00	712.50
5	R&R D/BOARD H	New	1,425.00	712.50
6	R&R SEAT BELT & AIRBAG CONTROL UNIT	New	950.00	475.00
7	R&R ENGINE	New	1,425.00	712.50
8	R&R GEAR BOX	New	950.00	475.00
9	R&R OIL SUMP	New	950.00	237.50
10	R&R MANIFOLD	New	1,425.00	475.00
11	R&R SUB FRAME	New	950.00	475.00
12	R&R FRT U/CARRIAGE	New	1,900.00	712.50
13	R&R ABS ASSY	New	1,425.00	475.00
14	R&R A/C COMPRESSOR	New	475.00	237.50
15	WHEEL ALIGNMENT	New	300.00	300.00
16	R&R BLACKVUE	New	250.00	250.00
17	TOWING	New	195.00	195.00
18	A/C GAS	New	60.00	60.00
19	LABOUR	New	5,700.00	4,275.00
20	SPRAY PAINTING	New	4,500.00	3,000.00
21	R&R SUNROOF FRAME	New	1,900.00	950.00
22	R&R FRT W/SCREEN	New	550.00	550.00
23	R&R LHS A-PILLAR GLASS	New	550.00	275.00
24	TRANSFER DOOR MECHANISM	New	475.00	237.50
25	FRT W/SCREEN SOLAR FILM	New	400.00	400.00
26	VEHICLE ON BENCH - CELETTE	New	1,200.00	1,200.00
27	R&R INTERIOR TRIM AND FRT SEAT	New	237.50	237.50
Gross Labour Cost (S\$)			30,415.50	18,428.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >