

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 30/09/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMH7605M	<i>Khanchana.</i>	
MODEL	: HONDA FIT 1.3 A	<i>GK31331078</i>	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 29-Sep-19
		TIME	: 15:40HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS (REAR)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented.</i>	1	\$ 1,122.00	\$ 1,122.00
2	TAIL GATE LOGO <i>new</i>	1	\$ 58.00	\$ 58.00
3	TAIL GATE EMBLEM 'FIT' <i>new</i>	1	\$ 58.00	\$ 58.00
4	TAIL GATE LOGO GARINISH <i>replaced</i>	1	\$ 162.30	\$ 162.30
5	TAIL GATE DETECTOR <i>not new (replaced)</i>	1	\$ 155.30	\$ 155.30
6	TAIL GATE BUZZEL <i>replaced</i>	1	\$ 180.00	\$ 180.00
7	TAIL GATE LAMP <i>replaced</i>	2	\$ 230.00	\$ 460.00
8	TAIL GATE INNER LOCK <i>Replaced</i>	1	\$ 225.80	\$ 225.80
9	TAIL GATE INNER HANDLE <i>Replaced</i>	1	\$ 90.00	\$ 90.00
10	TAIL GATE WEATHER STRIP <i>cut</i>	1	\$ 128.00	\$ 128.00
11	TAIL GATE INNER TRIM <i>replaced</i>	1	\$ 230.00	\$ 230.00
12	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00
13	REAR BUMPER <i>Rebond</i>	1	\$ 730.00	\$ 730.00
14	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 42.00	\$ 84.00
15	TAIL LAMP <i>replaced</i>	2	\$ 330.00	\$ 660.00
16	TAIL LAMP PANEL <i>LH Dented</i>	2	\$ 210.00	\$ 420.00
17	REAR FENDER <i>Repaired</i>	2	\$ 830.60	\$ 1,661.20
18	REAR FENDER INNER TRIM <i>LH replaced</i>	2	\$ 350.00	\$ 700.00

814.

68

55

105

493.

210

285

19	REAR END PANEL <i>Dented</i>	1	\$ 520.00	\$ 520.00 420
20	REAR END PANEL TOP GARNISH <i>delnd</i>	1	\$ 190.00	\$ 190.00 = 63
21	REAR FLOOR PANEL <i>Pegis</i>	1	\$ 833.60	\$ 833.60 +
22	REAR FLOOR PANEL TOP BOARD <i>Delnd</i>	1	\$ 233.60	\$ 233.60 ✓
23	REAR TOOL SPONGE TYRE <i>cracked</i>	1	\$ 355.20	\$ 355.20 225

5091.90
 407352

TOTAL PRICE	\$ 9,447.00
LESS 20%	\$ 1,889.40
SUB TOTAL PRICE	\$ 7,557.60

SPECIAL NETT ITEMS (REAR)

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>cracked</i>	1	\$ 50.00	\$ 50.00 -
2	TAIL GATE SEALANT <i>Nu</i>	1	\$ 80.00	\$ 80.00 60
3	TAIL GATE INNER TRIM CLIP(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00 ✓
4	TAIL GATE WINDSCREEN SEALANT <i>3 per</i>	1	\$ 80.00	\$ 80.00 40
5	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00 30
6	REAR BUMPER CLIP(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00 -
7	REAR BUMPER LOWER LID <i>cracked</i>	1	\$ 1,100.00	\$ 1,100.00 880
8	REAR FENDER INNER TRIM CLIP(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00 ✓
9	TAIL LAMP CLIP(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00 -
10	REAR END PANEL TOP GARNISH CLIPS <i>Nu</i>	1	\$ 20.00	\$ 20.00 ✓
11	REAR END PANEL INSULATION SEAL <i>Nu</i>	1	\$ 120.00	\$ 120.00 60
12	REVERSE CAMERA <i>Damaged</i>	1	\$ 550.00	\$ 550.00 380
13	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 200

2000

TOTAL \$ 2,360.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00 1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00 1400	
3	TUFF COAT	\$ 250.00 60	
4	WIRING CHECK	\$ 80.00 30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00 50	
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00 50	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	

8	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓	
---	-----------------------------	----------	---	--

TOTAL

\$4,690.00

2980

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,917.60
TOTAL LABOUR COST : \$ 4,690.00
TOTAL REPAIR COST : \$ 14,607.60

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King
h/s 01/10/19

07 Days.

total 8663.52
L/s 6.9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(6.9K)