

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017270/KGA3Q2
Date: 28/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKW5336Y	Insured Vehicle No :	SKQ1379G
Date of Loss:	27/09/2019	Nature of Claim:	TP
		Claim No:	0400485189SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW5336Y	Engine No:	1NZX858999
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305098243
Reg. Date:	12/01/2009 (Man. Year: 2008)	Odometer:	176654 km
Colour:	Metallic Green		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,083.06	2,619.16	463.90	15.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,440.00	960.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,483.06	4,059.16	1,423.90	25.97
Approved Total (Overridden) (S\$)		3,200.00		

Nett Amount (S\$)	5,483.06	3,200.00	2,283.06	41.64
		+ Car Rental (6.0 x S\$100.00/day) (S\$)	600.00	
		+ Doc/Search Fee (S\$)	7.49	
		Nett Liability (S\$)	3,807.49	

INSPECTION

Date of Assignment: 01/10/2019

Date Inspected: 02/10/2019

Inspected At:

Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming Autocare
 Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	451.60 FL	*451.60 FL
2	1		*REAR BUMPER LH REFLECTOR	Serviceable	92.90 FL	*- FL
3	1		*REAR BUMPER LH INNER SIDE BRACKET	Bent	56.30 FL	*56.30 FL
4	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	171.20 FL	*85.60 FL
5	2		*REAR BUMPER CORNER RETAINER	Cracked	86.00 FL	*86.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*REAR BOOT LID	Bent	589.10 FL	*589.10 FL
8	1		*REAR BOOT OUTER HANDLE GARNISH	Warped	175.00 FL	*175.00 FL
9	1		*REAR BOOT CENTRE TOYOTA LOGO	Necessary	48.10 FL	*48.10 FL
10	1		*REAR BOOT LH VIOS EMBLEM	Necessary	55.60 FL	*55.60 FL
11	1		*REAR BOOT RH E EMBLEM	Necessary	45.30 FL	*45.30 FL
12	1		*REAR BOOT TOP LOCK	Dented	121.35 FL	*121.35 FL
13	1		*REAR BOOT LOWER LOCK CATCH	Repair	41.40 FL	*- FL
14	1		*REAR BOOT WEATHERSTRIP	Serviceable	176.80 FL	*- FL
15	1		*LH TAILLAMP PANEL	Repair	128.50 FL	*- FL
16	2		*TAILLAMP	Cut / Cracked	655.20 FL	*655.20 FL
17	1		*REAR END PANEL	Bent	575.00 FL	*575.00 FL
18	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	211.40 FL	*211.40 FL
19	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
20	1		*SET REAR END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,010.75	3,415.55
- List Item Discount on L Items 25.00/25.00% (\$)	927.69	796.39
Total Parts (\$)	3,083.06	2,619.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES	New	1,000.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	1,000.00	600.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE ,REFIT REVERSES SENSORS	New	80.00	50.00
5	TO REMOVE ,REFIT REAR BOOT LID FITTINGS	New	80.00	50.00
6	TO REMOVE ,REFIT REAR UPHOLSTERY AND ATTACHMENTS	New	120.00	60.00
7	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
Gross Labour Cost (S\$)			2,400.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >