

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SJX 4439Y

Qty	Description of Parts	Condition	Recommended (\$)
	REPLACEMENT OF PARTS		
1	FRT BUMPER	CRUSHED	858.00
1	SET FRT BUMPER CLIPS	NECESSARY	30.00
1	SET FRT BUMPER RIVET	NECESSARY	30.00
1	FRT BUMPER SIDE RETAINER L/H	CRUSHED	56.00
1	FRT HEADLAMP ASSY L/H	CRUSHED	792.00
1	FRT LOWER ARM L/H	DAMAGED	292.00
1	FRT BUMPER LOWER SPOILER	TO REPAIR SEE LABOUR	-
1	FRT FENDER L/H	CRUSHED	561.00
1	FRT FENDER INNER PANEL L/H	TO REPAIR SEE LABOUR	-
1	FRT WHEEL BEARING L/H WITH KNUCKLE	BENT	450.00
	LESS 10% DISCOUNT		-306.90
			2,762.10
	SPECIAL NETT ITEMS		
1	FRT SPORT RIM L/H (SN)	SCRATCHED	380.00
			380.00
	<u>LABOUR</u>		
	REMOVE AND INSTALL UNDER CARRIAGE.		80.00
	CHECK WIRING.		20.00
	WHEEL ALIGNMENT.		60.00
	SPRAY PAINT LABOUR.		400.00
	SPRAY PAINT SPORT RIM.		80.00
	LABOUR. INCLUSIVE OF THE REPAIR OF FRT BUMPER LOWER SPOILER AND FRT FENDER INNER PANEL L/H.		300.00
			940.00
	GRAND TOTAL		4,082.10

RECOMMENDED COST OF LUMP SUM REPAIRS	3,250.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS3/SPF19017284/Hvf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,200-\$3,500

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser