



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION (TP)

Ref: CS3/SPF19017284/Hvf3e2

ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date: 14/10/2019

ATTN : HAFIZUL FARHAN RAHMAT

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 299C	Veh. Inspected	SJX 4439Y
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/096	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	01/10/2019

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER GLX	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JMYSRCS3AAU000398	Colour	GREY
Odometer	165974 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	FALKEN	5 mm
L/H Front Tyre	205/55 R16	FALKEN	5 mm
R/H Rear Tyre	205/55 R16	PIRELLI	5 mm
L/H Rear Tyre	205/55 R16	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/09/2019	Inspect Date / Time	01/10/2019 (05:44 PM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:

3 Working Days