ASS, REC, BY:		REF CSIZN	C19017287	AV43N2	Special Instruction:
Surveyor:	Adrian		IGNMENT		
From (Person)	Theresa vimalo	of	INC		Date/Time: orlio 2019
	Ľ			to:	
	TP RES / OD RES		IMV i CS		
To Inspect Vel	hicle No: SLR	Y8088			Insured: SLX 71390
at Workshop n	m/s <u>Yision</u> Aut	owork Pee	Ltd		Tel: 9856 4815
of & Kaki &	Bukit Ave 4 #0	8-09			
Policy No:	11	-5 55W;	(laim No:	100-8F3F301/TM
Sum Insured:				Excess:	
Make of Veh: (Client's Record					D.O.A. 29/09/2019
		" W	P"		
	REP. / REV 24 H				H.O.D. Endorsement:
Date/Time: 61	110/2019 @04:47pr	n Person Co	ntacted:	bby	Vehicle (DLOUT
Date/Time	Action/Instruction	(v) B	timate		
	SLX 7139U: X				1/4
	SLR 8808Y: X		TEORE COLLECTION		
141019	Adrian Cov	virmed	LS \$ 7	(100	(Red 15, 738.40, 6990
		1			

. Adrean	SSIGNMENT	
From: Date:	Veh No: 548 88087 YEE	team 2013 June .
Estimated Cost:	Type: M.Car M.Cycle / Bus / Van / Lorry / Tax	
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No:	Make: Subarn Foreste	5 00 1998
at Workshop m/s	Colour Silves. A/C.	Insured / Std / NI / NA
of	Sp.Reading 98123. T/Rad	fio: Insured / Std / NI / NA
Insured:	Eng/No:	
Policy No.	C/No: JFISJGK85D6	002175
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt	
Sum Insured: Excess:	Steering: Inorden/ Jammed / Leaked / Burnt of	ır
(Client's Record)	Brake: porder / Jammed / Leaked / Burnt of	r
Make of Veh:	Modi: Nil / SRim / STD A/Rim or	
	Tyre Size: F: 225/SS R	118 .
(Policy Condition)	Tyre Size: F: 225/SS R R: 225/SS R	8.
Remark: The veh had commenced its N/S O	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OF	HTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Faller.	
Bal, or Market Value:	<u>Front</u> <u>Rear</u>	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. o6 mm R/Bal	06 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal, 06 mm L/Bal	o C mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I	01/10/19.
Lum Sum: % 3 Val.: Yes or No	'Survey held at Vision	J.05pm
CA / REV / REP. / 24 HRS Vehicle: IN / 0	Des. of Damages : Frt / Rear / O/S / N/S / t	J/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structur	re affected due to collision.
Date / Time Action / Instruction		
TP INC		
	m b Park	
mv: 481c (Depreciation (5)	2 Min Porf (10.5K x 3.6 Years + 10K) = 48K	
PV:40.3K	10312 x 3.6 Jeers + 10 K) = 4810	.)
	ED 1 5 00T 2019	
KEGEIVI	11 1 201 2010	
Dale/Time, File Pass to? : Preli. Report	Days Of Repair: 7	3
1) : Final Report	Resurvey No. of Trip: \ Surve	y Fee:
Date/Time, File Return to?	-	ortation
3 Islo-typist Add	-ee: Site Insp (\$)_8-	PS9
	:Interview (\$) shold	ě .
Report Formst: TP	Tech, Inve (%) Other	1
Lump & nm / LEJ: (+ LS \$ 7100 2)	: West sayd (8	
	77.0	250

Nivitha (LKK Auto)

From:

Sent:

To:

Subject:

RE: TP CASES FARMED OUT TO LKK ON 01/10/2019 Theresa Vimala D/O Balagangadharan

Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Tuesday, 1 October 2019 10:43 AM

assignments

Here is the OIC, clm ref details. Thank you.

With Regards

www.income.com.sg Senior Administrator Motor Insurance T+65 6430 7898 Theresa Vimala







innovation and impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. At Income, we are 'In with You' on Performance, Growth, Find out more at income.com.sg/careers

From: Theresa Vimala D/O Balagangadharan Sent: Tuesday, 1 October 2019 10:38 AM

To: assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: FW: TP CASES FARMED OUT TO LKK ON 01/10/2019

Dear LKK

Please assist to survey the following vehicles as per Tse Kiat instruction :-

p Workshop Survey OI VEH DOA Remarks	IKIT 4 #08- IER @ michelle/abby PC2779T 30/9	ENUE 800 leong keat 10:00- SGC5233M 19/9	Gi 2#01- APORE LIEW / SKH9807H 27/9	UKIT 4 #08- 4@KAKI CHRIS / SKR4181] 24/9	UKIT 4 #08- 3@KAKI chris/ YP2054B 27/9	UKIT 4 #08- R@KAKI julie / SKK6194X 24/9	KKIT : 4#08- 1.4#08- AIER @ abby / SJD1575L 27/9 G3416789 KKIT 98564815	
hap WarkShap Address	AIC AVENUE 4 #08- VORK 09 PREMIER ® D KAKI BUKIT	NO 8 KAKI BUKIT AVENUE BUKIT AVENUE 4 #05-24 ENGINEERING PREMIER @ PTE LTD KAKI BUKIT	23 CHANGI SOUTH TIVE AVENUE 2 #01- 02 SINGAPORE 486443	SK ASKI BUKIT AVENUE 4 #08- , 45/46 AUTOMOBILE PREMIER@KAKI BUKIT BUKIT	SK 46 AUTOMOBILE PREMIER©KAKI	8 KAKI BUKIT AVENUE 4 #08- 5K 46 AUTOMOBILE PREMIER©KAKI PTE LTD BUKIT	KAKI BUKIT VISION AVENUE 4 #08- 09 PREMIER ® PTE. LTD. KAKI BUKIT	
WorkShop Vehicle	40				DC1827U	SIK96065	S1A5802Y	The same of the sa
Survey	9100/01/1	9/10/201/1	1/10/2019	9/10/2014				4/ 40/ 4042
N mind	MT/1064658-					MT/1064644-		
-								7 chariote
1	Z,	4 1	1	9	4	n '	1	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

www.income.com.sg Senior Administrator Motor Insurance T+65 6430 7898 Theresa Vimala


















as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers mode different D

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.





Follow sgCarMart.com











About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Singapore NRIC	
Owner ID Type:		
Owner ID:	396B	×.5
Vehicle Details	SLR8808Y	
Vehicle No.:	Yes	
Vehicle to be Exported:	02 Oct 2019	
Intended Deregistration Date:		
Vehicle Make:	SUBARU FORESTER 2.0XT AWD CVT	
Vehicle Model:	X A	
Primary Colour:	Silver	
Manufacturing Year:	2012	
Engine No.:	FA20G898433	
Chassis No.:	JF1SJGK85DG002175	
Maximum Power Output:	177.0 kW (237 bhp)	
Open Market Value:	\$19,155.00	
Original Registration Date:	21 Jun 2013	
First Registration Date:	21 Jun 2013	
Transfer Count:	.1	
Actual ARF Paid:	\$19,155.00	(mile
Intended PARF Rehate Dotails		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	20 Jun 2023	
PARF Rebate Amount:	\$12,450.00	-
Intended COF Rebate Details	20 Jun 2023	
COE Expiry Date:		
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
QP Paid:	\$75,000.00	
COE Rebate Amount:	\$27,875.00	
Total Rebate Amount:	\$40,325.00	

The information contained herein is correct as at 02 Oct 2019

MVAG19128961 / VAG Singapore Pte Ltd - HQ ENTRY DATE & TIME: 30/09/2019 11:47 SUBMITTED BY: Ong Min Choon

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. repudiate policy liability.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	30/09/2019 11:47
Date Of Accident	29/09/2019 18:00
Exact Location Of Accident	CROSS JUNCTION BUKIT BATOK 3 AND BUKIT BATOK 23
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLR8808Y
Insured/Policyholder	
Name Of Registered Owner	KENNY LIM SENG LEONG
NRIC No	S7631396B
Email Address	KENNYLIM8190@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97478190
Alternative Phone No	OFFICE-97478190
Vehicle Particulars	
Manufacturer	SUBARU
Model	FORESTER-2,0 XT AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
	110

NO Fleet Policy

MT/00634920 Policy Number

Cover Note Number

Driver

KENNY LIM SENG LEONG Name of Driver

S7631396B NRIC No 29/09/1976 Date Of Birth INDOOR Occupation 12/08/1999 Date Of Driving Pass

20 YEARS AND 1 MONTH **Driving Experience**

MALE Gender

(LOCAL) +65-97478190 Mobile Number

Fax Number

OFFICE-97478190 Contact Number

KENNYLIM8190@YAHOO.COM.SG EMail Address

Address

BLK 296C BUKIT BATOK STREET 22 #32-88 SINGAPORE 653298

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

: SERENE POH

GENDER:

: FEMALE

Passenger 2

NAME:

: HAYDEN LIM

GENDER:

: MALE

Passenger 3

NAME:

: WAYNE LIM

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Please see attached files

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

BIG FILE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLX7139U

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Page 2 of 26

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose of the pu
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder'y Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN NO SHAPPS PET

Sketch Plan #2

Cross Juction of Bukit Butok Ave 3 and Bukit Batok Street 23 SKETCH PLAN A= SLR 8808 Y B= SLX 71394 DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Refer to attach DECLARATION I/We declare the foregoing particulars are true in every respect. Reporting Cents Personnel's Signature Name Cony ONT NRIC/FIN No. Set Free SCAF Policyholder's Signature Oriver's Signature (If driver's not the policyholder) Date & Time: Date & Time

On 29.09.19 at about 18:00 hours at the Cross- junction of Bukit Batok Ave 3 and Bukit Batok Street 23. While I was travelling on the lane 3 going straight in the direction of Bukit Batok Ave 3 towards Bukit Batok Ave 6.

When I stationary waiting for the traffic light to turn green. Suddenly, I heard a loud bang from behind and when I alighted, I realized it was Vehicle (B) who hit my rear left hand side portion of my vehicle (A) causing damages to my vehicle. I wish to state that I have three passengers inside my vehicle.

Vehicle (A): SLR8808Y

Vehicle (B): SLX7139U

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E) 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Fax: 6341 6778 Tel: 6341 6789 E-mail:visionautowork@gmail.com

DATE: 30.09.19

TO

: NTUC MOTOR CLAIMS DEPTS

VEHICLE NO

: SLR8808Y

Veron.

MODEL

: SUBARU FORESTER

DATE OF ACCIDENT : 29.09.19 TIME OF ACCIDENT : 18:00HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL: PARTS

/N	N DESCRIPTION (UNIT LIST PRICE		TOTAL LIST PRICE		
	TAILGATE Dented	1	\$	1,192.00	\$	1,192.00	
2	TAILGATE SPOILER 3RD BRAKE LAMP	1	\$	170.00	\$	170.00	
- 1	TAILGATE OUTER CENTRE GARNISH	1	\$	260.00	\$	260.00	
4	TAILGATE NUMBER PLATE LAMP GARNISH	1	\$	78.00	\$	78.00	
5	TAILGATE OUTER SWITCH BUTTON (OPEN)	1	\$	286.00	\$	286.00	
6	TAILGATE OUTER SWITCH BUTTON (LOCK)	1	\$	560.00	\$	560.00	
7	TAILGATE DETECTOR HELD	1	\$	325.00	\$	325.00	
8	TAILGATE EMBLEM 'SUBARU'	1	\$	85.00	\$	85.00	
9	TAILGATE EMBLEM 'FORESTER'	1	\$	80.00	\$	80.00	
10	TAILGATE EMBLEM 'AWD'	1	s	70.00	\$	70.00	
11	TAILGATE EMBLEM 'SYSTEMATICAL'	1	\$	85.00	\$	85.00	
12	TAILGATE EMBLEM 'XT'	1	\$	75.00	\$	75.00	
13	TAILGATE SIDE SENSOR LH P	2	\$	390.00	\$	780.00	
14	TAILGATE AUTO MOTOR 7 2	1	\$	864.00	\$	864.00	
15	TAILGATE AUTO BUTTON SWTICH	1	\$	286.00	\$	286.00	
16	TAILGATE INNER LOCK NE M	1	\$	560.00	\$	560.00	
17	TAILGATE LOWER LOCK Hem	1	\$	24.00	\$	24.00	
18	TAILGATE STOPPER ~~~	2	\$	19.00	\$	38.00	
19	TAILGATE WEATHER STRIP Lt	1	\$	170.00	\$	170.00	
20	TAILGATE INNER TRIM (LOWER) unld	1	\$	235.00	\$	235.00	
21	TAIL GATE DAMPER	2	\$	140.00	\$	280.00	
22	TAIL GATE HINGE ME M	2	\$	44.00	\$	88.00	
23	TAILGATE WINDSCREEN C/W MOULDING	1	\$	980.00	\$	980.00	
	REAR BUMPER Distorted	1	\$	680.00	\$	680.00	
	REAR BUMPER TOWING COVER	401	\$	20.00	\$	20.00	
	REAR BUMPER REFLECTOR LH	1	\$	42.00	\$	42.00	
	REAR BUMPER SIDE RETAINER	2	\$	36.00	\$	72.00	
	B REAR BUMPER REINFORCEMENT BENT	1	\$	475.00	\$	475.00	
Page 1	TAILLAMP LH Conclud	1	\$	437.00	\$	437.00	

TO

: NTUC MOTOR CLAIMS DEPTS

VEHICLE NO

: SLR8808Y

MODEL

: SUBARU FORESTER

DATE OF ACCIDENT : 29,09.19

TIME OF ACCIDENT : 18:00HRS

30 TAILLAMP BRACKET (LOWER) CALLY LE	+ 2	\$	475.00	\$	950.00
31 TAIL LAMP PANEL (OUTER) LH	1	\$	170.00	\$	170.00
32 TAIL LAMP LOWER PANEL (INNER) LH	2	\$	190.00	\$	380.00
33 TAIL LAMP TOP COVER GARNISH	2	\$	62.00	\$	124.00
34 REAR FENDER LH Regis	1	\$	960.00	\$	960.00
35 REAR FENDER INNER COWLING LH	2	\$	120.00	\$	240.00
36 REAR FENDER INNER TRIM LH COULD	- 1	\$	298.00	\$	298.00
37 REAR FENDER AIR VENT LH Deld	1	\$	84.00	\$	84.00
38 REAR FENDER 1/4 GLASS WITH MOULDING	77.11.00	\$	395.00	\$	395.00
39 REAR END PANEL Deutel	1	\$	460.00	\$	460.00
40 REAR END PANEL TOP GARNISH Red	. 1	s	135.00	\$	135.00
41 REAR FLOOR PANEL TOP TRAY (SPONGE)	4 1	\$	265.00	\$	265.00
42 REAR FLOOR PANEL TOP BOARD (SIDE) LH	Nu~ 1	\$	80.00	\$	80.00
43 REAR FLOOR PANEL SIDE SPONGE LH	-4d1	\$	170.00	\$	170.00
44 REAR FLOOR PANEL TOP BOARD DE	d 1	\$	195.00	\$	195.00
45 CENTER EXHAUST 2M	1	\$	1,140.00	\$	1,140.00
46 CENTER EXHAUST GASKET (SET)	1	\$	80.00	\$	80.00
47 REAR EXHAUST BOX LH Derted	1	\$	890.00	\$	890.00
48 REAR EXHAUST INSULATOR LH capled	1	\$	199.00	\$	199.00
49 REAR EXHAUST GASKET (SET)	1	\$	80.00	s	80.00
50 REAR EXHAUST PIPE MOUNTING	4	\$	39.00	\$	156.00
7.051.60	TOT	AL PR	ICE	\$	16,748.00

5641.20	SUB TOTAL PRICE	\$ 13,398.40
10313	LESS 20%	\$ 3,349.60
7051.50	TOTAL PRICE	\$ 16,748.00

S/N	DESCRIPTION	QTY	UNI	S/NETT	TOTA	L S/NETT
1	REAR NUMBER PLATE	1	\$	50.00	\$	50.00
2	REAR BUMPER CLIPS (SET) NA	1	\$	60.00	\$	60:00
3	REAR BUMPER STICKER 'STI'	1	\$	120.00	\$	120,00
4	TAILLAMP CLIP (SET)	1	\$	30.00	\$	30,00
5	THE STATE OF A SALE AND	1	\$	60.00	\$	60.00
6	THE PARTY OF THE P	1	\$	60.00	s	60.00
7	TAILGATE NUMBER PLATE LAMP GARNISH CLIP (SET)	4141	\$	40.00	\$	40.00
8	TAILGATE OUTER CENTRE GARNISH CLIP (SET	1/2	\$	40.00	\$	40.00
	TAILGATE INNER TRIM (LOWER) CLIP (SET)		\$	60.00	\$	60.00
	TAILGATE LOGO (SPECIAL TYPE)	1	\$	150.00	\$	150.00
11	TAILGATE EMBLEM 'STI' (SPECIAL TYPE) New	1	\$	150.00	\$	150.00
12		1	\$	80.00	\$	80.00
10	TAILGATE WINDSCREEN INNER SHIELD HEN	1	\$	60.00	\$	60.00

TO

: NTUC MOTOR CLAIMS DEPTS

VEHICLE NO

: SLR8808Y

MODEL

: SUBARU FORESTER

DATE OF ACCIDENT : 29.09.19

TIME OF ACCIDENT

: 18:00HRS

14	TAILGATE WINDSCREEN SOLAR FILM	1	\$	550.00	\$ 550.00
	REAR FENDER LH SEALANT	1	\$	150.00	\$ 150.00
	REAR FENDER INNER COWLING CLIP (SET)	1	\$	60.00	\$ 60.00
_	REAR FENDER INNER TRIM (LOWER) CLIP (SET)	1	s	80.00	\$ 80.00
_	REAR FENDER QUARTER GLASS SEALANT	1	\$	60.00	\$ 60.00
_	REAR FENDER QUARTER GLASS INNER SEALAR	1	\$	40.00	\$ 40.00
_	REAR FENDER QUARTER GLASS SOLAR FILM	1	\$	250.00	\$ 250.00
21	REAR END PANEL INSULATION SEAL ALL	1	\$	150.00	\$ 150.00
22	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$	40.00	\$ 40.00
	REAR EXHAUST PIPE (CHROME)	1	\$	350.00	\$ 350.00
_	REVERSE CAMERA NO NO	1	\$	450.00	\$ 450.00
	REVERSE SENSOR	1	\$	220.00	\$ 220.00

630 **TOTAL** \$

3,360.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR) ADJUSTED COST PRICE JOB DESCRIPTION S/N TO PANEL BEAT, REMOVE AND 1000. 1,600:00 1 REPLACE PARTS 1000. 2 TO SPRAY PAINT AFFECTED AREA \$ 1,600.00 60 S 250.00 3 TUFF COAT 30 180:00 \$ 4 WIRING AND BULB CHECK 180.00 5 CONDUCT WATER LEAKAGE TEST \$ REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO 80 350.00 6 FACILIATE REPAIR REMOVE AND REFIX REVERSE 50 7 SENSOR AND DISTANCE SETTING 80.00 REMOVE AND REFIX REVERSE 50 80.00 \$ 8 CAMERA AND DISTANCE SETTING REMOVE AND REFIX VIDEO 9 RECORDER AND DISTANCE SETTING 80.00 250.00 10 REAR CHASSIS ALIGNMENT \$ 11 TRANSFER TAILGATE MECHANISM \$ 80.00 120.00 12 CONDUCT WATER LEAKAGE TEST \$ REMOVE AND REFIX TAILGATE 120.00 13 WINDSCREEN \$

TO

: NTUC MOTOR CLAIMS DEPTS

VEHICLE NO

: SLR8808Y

MODEL

: SUBARU FORESTER

DATE OF ACCIDENT

: 29.09.19

TIME OF ACCIDENT

: 18:00HRS

14	REMOVE AND REFIX EXHAUST PIPE	s	180.00	- 80.
	REMOVE AND REFIX REAR FENDER GLASS	\$	100.00	×
16	REMOVE, REFIX AND RESET TAILGATE AUTO SYSTEM	\$	650.00	100
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	+

TOTAL

6080

2700

ESTIMATE REPORT

TOTAL PARTS COST

\$16,758.40

TOTAL LABOUR COST:

\$6,080.00

TOTAL REPAIR COST :

\$22,838.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY

HP: 9856 4815

Adrian him - total: 8971.20
4/5 01/10/19.

07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

inture:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		DAMAGE ASSES		
NTUC	INCOME INSURA	ANCE CO-OPERATIVE LTD	Ref: CS/INC19017287/	
3 BR	AS BASAH ROAD NTUC TRADE U		Date: 15-10-2019	
ATTN:	CHARLOTTE		Code: INC	
١.			:- THIRD PARTY CLAIM	OLD 0000V
ı	nsured Veh.	SLX 7139U	Veh. Inspected	SLR 8808Y
1	Policy No.		Coverage (\$)	0.00
-	Claim No.	MT/1064678-001	Excess (\$)	0.00
	Assign From	THERESA VIMALA	Assign Date	01/10/2019
2.		Vehicle Parti	culars & Condition	
	Make & Model	SUBARU FORESTER	c.c	1998
$\overline{}$	Engine No.	HIDDEN	Year of Reg.	2013
_	Chassis No.	JF1SJGK85DG002175	Colour	SILVER
	Odometer	98123 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condit	tions of Tyres	
1		Size	Make	Balance
	R/H Front Tyre	225/55 R18	FALKEN	6 mm
	L/H Front Tyre	225/55 R18	FALKEN	6 mm
	R/H Rear Tyre	225/55 R18	FALKEN	6 mm
	L/H Rear Tyre	225/55 R18	FALKEN	6 mm
4.		Descript	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR N/S PORTION.	
5.		Gener	al Information	
	Accident Date	29/09/2019	Inspect Date / Time	01/10/2019 (02:05 PM
	Survey held at	VISION AUTOWORK PTE LTD)	
	3	8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BU SINGAPORE 415875	КІТ	
5a.			Remarks	
	A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A''W CE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHORISE	S. ED REPAIRS.
5b.	A FE A SELECTION		e Days of Repair	A PROPERTY OF THE PARTY OF THE
	ESTIMATED NO	RMAL PERIOD FOR REPAIR:	7 Working Days	5



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8808Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED	1,192.00	1,192.00
1	TAILGATE SPOILER 3RD BRAKE LAMP	NOT NECESSARY	170.00	-
,	TAILGATE OUTER CENTRE GARNISH	NOT NECESSARY	260.00	
	TAILGATE NUMBER PLATE LAMP GARNISH	NOT NECESSARY	78.00	
	TAILGATE OUTER SWITCH BUTTON (OPEN)	NOT NECESSARY	286.00	
1	TAILGATE OUTER SWITCH BUTTON (LOCK)	NOT NECESSARY	560.00	-
4	TAILGATE DETECTOR	NOT NECESSARY	325.00	1
	TAILGATE EMBLEM "SUBARU"	NECESSARY	85.00	
	TAILGATE EMBLEM "FORESTER"	NECESSARY	80.00	
	TAILGATE EMBLEM "AWD"	NECESSARY	70.00	
	TAILGATE EMBLEM "SYSTEMATICAL"	NECESSARY	85.00	
	TAILGATE EMBLEM "XT"	NECESSARY	75.00	75.00
	TAILGATE SIDE SENSOR @\$390.00	N/S DAMAGED	780.00	390.00
	1 TAILGATE AUTO MOTOR	NOT NECESSARY	864.00	· ·
	1 TAILGATE AUTO BUTTON SWITCH	NOT NECESSARY	286.00	o -
	1 TAILGATE INNER LOCK	NOT NECESSARY	560.0	o -
	1 TAILGATE LOWER LOCK	NOT NECESSARY	24.0	0
	2 TAILGATE STOPPER @\$19.00	NOT NECESSARY	38.0	0
	1 TAILGATE WEATHER STRIP	сит	170.0	
100	1 TAILGATE INNER TRIM (LOWER)	CRACKED	235.0	0 235.00
	2 TAIL GATE DAMPER @\$140.00	NOT NECESSARY	280.0	0
11 3	2 TAIL GATE HINGE @\$44.00	NOT NECESSARY	88.0	0
	1 TAILGATE WINDSCREEN C/W MOULDING	NOT NECESSARY	980.0	0
	1 REAR BUMPER	DISTORTED	680.0	680.0
	1 REAR BUMPER TOWING COVER	DEFORMED	20.0	20.0
	1 REAR BUMPER REFLECTOR LH	CRACKED	42.0	00 42.0
	2 REAR BUMPER SIDE RETAINER @\$36.00	NECESSARY	72.0	100000
	1 REAR BUMPER REINFORCEMENT	BENT	475.0	200
	1 TAILLAMP LH	CRACKED	437.0	100 N
	2 TAILLAMP BRACKET (LOWER) @\$475.00	N/S CRACKED	950.0	00 47.5

Report Ref No. CS/INC19017287/Avf3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
4.0	TAIL LAMP PANEL (OUTER) LH	TO REPAIR SEE LABOUR	170.00	-
2	TAIL LAMP LOWER PANEL (INNER) LH @\$190.00	TO REPAIR SEE LABOUR	380.00	5.
2	TAIL LAMP TOP COVER GARNISH @\$62.00	NOT NECESSARY	124.00	8
	REAR FENDER LH	TO REPAIR SEE LABOUR	960.00	5
2	REAR FENDER INNER COWLING LH @\$120.00	N/S TORN	240.00	1
	REAR FENDER INNER TRIM LH	CRACKED	298.00	298.00
	REAR FENDER AIR VENT LH	DEFORMED	84.00	84.00
	REAR FENDER 1/4 GLASS WITH MOULDING LH	NOT NECESSARY	395.00	12
	REAR END PANEL	DENTED	460.00	460.0
	REAR END PANEL TOP GARNISH	DEFORMED	135.00	135.0
	REAR FLOOR PANEL TOP TRAY (SPONGE)	CRACKED	265.00	265.0
	REAR FLOOR PANEL TOP BOARD (SIDE) LH	NOT NECESSARY	80.00	
	REAR FLOOR PANEL SIDE SPONGE LH	CRACKED	170.00	170.0
	REAR FLOOR PANEL SIDE SI ONGE EN	DEFORMED	195.00	195.0
	1 CENTER EXHAUST	NOT NECESSARY	1,140.00	o l
	1 SET CENTER EXHAUST GASKET	NOT NECESSARY	80.00	p
	1 REAR EXHAUST BOX LH	DENTED	890.0	890.0
	1 REAR EXHAUST INSULATOR LH	CRUMPLED	199.0	199.0
	1 SET REAR EXHAUST GASKET	NECESSARY	80.0	0.08
	4 REAR EXHAUST PIPE MOUNTING @\$39.00	NOT NECESSARY	156.0	0
	LESS 20% DISCOUNT	(Secretary Anna Secretary Secretary	-3,349.6	0 -1,410.3
	LESS 20% DISCOUNT		13,398.4	0 5,641.2
	SPECIAL NETT ITEMS			
	1 REAR NUMBER PLATE (SN)	NOT NECESSARY	50.0	52783
	1 SET REAR BUMPER CLIPS (SN)	NECESSARY	60.0	
	1 REAR BUMPER STICKER "STI" (SN)	NECESSARY	120.0	
	1 SET TAILLAMP CLIP (SN)	NECESSARY	30.0	
3	1 TAIL LAMP PANEL (OUTER) SEALANT (SN)	NOT NECESSARY		
	1 SET TAIL LAMP TOP COVER GARNISH CLIP (SN)	NOT NECESSARY		
1	1 SET TAILGATE NUMBER PLATE LAMP GARNISH CLIP (SN)	NOT NECESSARY	40.0	10

Report Ref No. CS/INC19017287/Avf3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
393265	SET TAILGATE OUTER CENTRE GARNISH CLIP (SN)	NOT NECESSARY	40.00	
1	SET TAILGATE OUTER CENTRE GARAGET SEE (SN)	NECESSARY	60.00	30.00
	TAILGATE LOGO (SPECIAL TYPE)(SN)	NOT NECESSARY	150.00	-
	TAILGATE EMBLEM "STI" (SPECIAL TYPE)(SN)	NECESSARY	150.00	80.00
	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
	TAILGATE WINDSCREEN INNER SHIELD (SN)	NOT NECESSARY	60.00	
	TAILGATE WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	550.00	-
		NOT NECESSARY	150.00	-
	REAR FENDER LH SEALANT (SN)	NECESSARY	60.00	30.00
1	SET REAR FENDER INNER COLWING CLIP (SN) SET REAR FENDER INNER TRIM (LOWER) CLIP (SN)	NECESSARY	80.00	30.00
1	REAR FENDER QUARTER GLASS SEALANT (SN)	NECESSARY	60.00	30.00
1	REAR FENDER QUARTER GLASS SEALANT (617) REAR FENDER QUARTER GLASS INNER SEAL (SN)	NOT NECESSARY	40.00	-
1	REAR FENDER QUARTER GLASS SOLAR FILM (SN)	NOT NECESSARY	250.00	-
1		NECESSARY	150.00	60.00
- 5	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	40.00	10.00
	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	350.0	o -
	REAR EXHAUST PIPE (CHROME)(SN)	NOT NECESSARY	450.0	o -
	1 REVERSE CAMERA (SN)	DAMAGED	220.0	200.00
2	1 REVERSE SENSOR (SN)	DANIAGED	3,360.0	0 630.00
	LABOUR		0.0153349800	
	TO PANEL BEAT.REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL (OUTER) LH,TAIL LAMP LOWER PANEL (INNER) LH AND REAR FENDER LH.		1,600.0	
	TO SPRAY PAINT AFFECTED AREA.		1,600.0	5. D.
	TUFF COAT.		250.0	
	WIRING AND BULB CHECK.		180.0	30.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	180.0	(2) (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR.		350.0	
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	:	80.0	
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.0	50.00

Report Ref No. CS/INC19017287/Avf3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE		80.00	50.00
	SETTING. REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	
	TRANSFER TAILGATE MECHANISM.	The state of the s	80.00	80.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	1
	REMOVE AND REFIX EXHAUST PIPE.		180.00	80.00
	REMOVE AND REFIX REAR FENDER GLASS.	NOT NECESSARY	100.00	
	REMOVE, REFIX AND RESET TAILGATE AUTO SYSTEM.		650.00	0.0000000000000000000000000000000000000
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO	NOT NECESSARY	180.00	
	SPECIFICATION ETC.		6,080.00	2,700.00
	GRAND TOTAL		22,838.40	8,971.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,100.0

Report Ref No. CS/INC19017287/Avf3n2

ADRIAN LING WAI PING

(CONFIRMED)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.