

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017351/KES3Q2

Date: 28/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994112

Claimant
Vehicle No : SLR9673L **Insured Vehicle No :** YP832K

Date of Loss: 30/09/2019 Nature of Claim: TP Claim No: 6408973543SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9673L		
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Engine No:	1NZR530308
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	NHP1707092690
Colour:	Metallic Pearl White	Odometer:	25317 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,396.75	6,553.50	4,843.25	42.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,100.00	1,170.00	51.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,666.75	7,653.50	6,013.25	44.00
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		8,220.99		
Global Sum Settlement (S\$)		8,220.00		

INSPECTION

Date of Assignment: 01/10/2019

Date Inspected: 02/10/2019 Inspected At: Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	421.70 FL	*421.70 FL
2	2		*FRONT BUMPER FOG LAMP	Serviceable	473.80 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Serviceable	113.40 FL	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
5	1		*FRONT BUMPER INNER FOAM	Serviceable	85.70 FL	*- FL
6	1		*FRONT BUMPER INNER REINFORCEMENT	Repair	387.90 FL	*- FL
7	1		*FRONT GRILLE ASSY	Cracked	846.30 FL	*846.30 FL
8	1		*FRONT TOYOTA LOGO	Scratched	56.90 FL	*56.90 FL
9	2		*HEADLAMP	Mtg Cracked	6,091.60 FL	*4,600.00 FL
10	1		*FRONT BONNET	Bent	696.50 FL	*696.50 FL
11	2		*FRONT BONNET HINGE	Repair	161.80 FL	*- FL
12	1		*FRONT BONNET LOCK	Repair	162.90 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Repair	1,097.10 FL	*- FL
14	1		*FRONT INTERCOOLER	Punctured	720.60 FL	*720.60 FL
15	1		*AIR CON CONDENSER	Bent / Punctured	1,218.00 FL	*1,218.00 FL
16	1		*RADIATOR	Serviceable	2,154.90 FL	*- FL
17	1		*RADIATOR FAN COWLING	Serviceable	261.90 FL	*- FL
18	1		*FRONT NUMBER PLATE	Serviceable	50.00 FS	*- FS
19	1		*FRONT BUMPER TOP BEAM	Bent	138.00 FL	*138.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,179.00** **8,738.00**

- List Item Discount on L Items 25.00/25.00% (\$\$) **3,782.25** **2,184.50**

Total Parts (\$\$) **11,396.75** **6,553.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE/REFIT AND REPLACE DAMAGE PARTS	New	1,000.00	450.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	1,000.00	600.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE,REFIT A/C CONDENSER ,RADIATOR ETC....INCLUDING REFILL A/C GAS	New	150.00	0.00
5	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	30.00
Gross Labour Cost (S\$)			2,270.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >