Adjuster Report Page 1 of 3

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017354/KDA3Q2

Date: 04/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SKQ1889B Insured Vehicle No: SMJ3579X Vehicle No:

Date of Loss: ΤP 01/10/2019 Nature of Claim: Claim No: 9838302321SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SKQ1889B** Reg No:

Make & Model: LEXUS IS250, 2.5 STD (A) Engine No: 4GR0601288

Reg. Date: 10/02/2010 (Man. Year: 2009) Chassis No: JTHFK252702507507

Colour: Metallic Dark Blue Odometer: 118348 km

**Engine Capacity:** Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

2500 cc

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 235/35ZR19 Rear Tyre Size: 235/35ZR19 Front Left Side: Kumho 8 mm Rear Left Side: Kumho 8 mm Front Right Side: Rear Right Side: Kumho 8 mm Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,794.20	1,691.17	4,103.03	70.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	920.00	1,560.00	62.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,274.20	2,611.17	5,663.03	68.44
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	8,274.20	1,400.00	6,874.20	83.08
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 01/10/2019

02/10/2019 Inspected At: Date Inspected: Autoworx House - Sin Ming (HQ)

176 SIN MING DRIVE #02-01

Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	1,656.40 FL	*1,656.40 FL
2	1		*REAR BUMPER PARKING SENSOR	O/s Dented	734.80 FL	*367.40 FL
3	1		*REAR BUMPER REINFORCEMENT	*Check	656.20 FL	*- FL
4	1		*REAR BUMPER LOWER SPONGE	*Check	457.20 FL	*- FL
5	1		*REAR BUMPER UPPER SPONGE	*Check	213.10 FL	*- FL
6	1		*REAR BUMPER REFLECTOR	Serviceable	167.30 FL	*- FL
7	1		*REAR BUMPER TOW COVER	Serviceable	67.80 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER	Serviceable	130.20 FL	*- FL
9	1		*REAR BOOT LOCK SENSOR RECEIVER	*Check	368.30 FL	*- FL
10	1		*REAR BOOT EMBLEM LOGO	Necessary	78.50 FL	*78.50 FL
11	1		*REAR BOOT EMBLEM IS250C	Necessary	76.30 FL	*76.30 FL
12	1		*REAR BOOT LAMP	Serviceable	578.40 FL	*- FL
13	1		*REAR BOOT WEATHER STRIP	Serviceable	315.10 FL	*- FL
14	1		*REAR BOOT LOCK CATCH	Repair	215.00 FL	*- FL
15	1		*REAR BOOT EMBLEM LEXUS	Necessary	76.30 FL	*76.30 FL
16	1		*REAR END PANEL	Repair	785.20 FL	*- FL
17	1		*REAR END PANEL TRIM	Serviceable	451.10 FL	*- FL
18	1		*REAR TAIL LAMP	*Check	698.40 FL	*- FL
F=Fra	anchise	part. L=ListIt	emDisc.			
				Sub Total (S\$)	7,725.60	2,254.90
			- List Item Discount on L Item	ns 25.00/25.00% (S\$)	1,931.40	563.73
				Total Parts (S\$)	5,794.20	1,691.17

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,000.00	400.00
2	TO CHECK WIRING SYSTEM	New	40.00	20.00
3	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	120.00	0.00
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	120.00	0.00
	Gross Labour Cost (S\$)		2,480.00	920.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.