



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 7494S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	AIR-COND CONDENSER (WCP)	NOT NECESSARY	220.00	-
1	BONNET (WCP)	BENT	198.00	198.00
1	BONNET HINGE LH (WCP)	NOT NECESSARY	48.00	-
1	BONNET HINGE RH (WCP)	NOT NECESSARY	48.00	-
1	BONNET LOCK (WCP)	BENT	42.00	42.00
1	BONNET RUBBER (WCP)	NOT NECESSARY	23.00	-
1	BUMPER AIR GRILLE CENTER, FRONT (WCP)	NOT NECESSARY	52.00	-
1	BUMPER BRACKET LH, FRONT (WCP)	NOT NECESSARY	19.00	-
1	BUMPER BRACKET RH, FRONT (WCP)	NOT NECESSARY	19.00	-
1	BUMPER REINFORCEMENT, FRONT (WCP)	NOT NECESSARY	100.00	-
1	BUMPER, FRONT (WCP)	DEFORMED	210.00	210.00
1	HEADLAMP LH (WCP)	NOT NECESSARY	190.00	-
1	HEADLAMP RH (WCP)	NOT NECESSARY	190.00	-
1	RADIATOR (WCP)	NOT NECESSARY	280.00	-
1	RADIATOR GRILLE (WCP)	CRACKED	182.00	182.00
1	RADIATOR PANEL (WCP)	NOT NECESSARY	280.00	-
1	RADIATOR UPPER HOSE (WCP)	NOT NECESSARY	20.00	-
1	BUMPER INNER SPONGE, FRONT (WCP)	NOT NECESSARY	70.00	-
1	AIR CON AUXILLARY FAN ASSY (WCP)	NOT NECESSARY	175.00	-
1	HORN (WCP)	NOT NECESSARY	45.00	-
1	REAR BUMPER (WCP)	TO REPAIR SEE LABOUR	200.00	-
1	REAR BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	110.00	-
	COST PLUS 10%		272.10	63.20
			2,993.10	695.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT NUMBER PLATE W/FAME (SN)	CRACKED	45.00	45.00
1	BATTERY (SN)	NOT NECESSARY	150.00	-
			195.00	45.00

Report Ref No. CS1/SPF19017392/Dyf3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b>LABOUR</b> TO PUTTY AND RESPRAY PAINTING ON BONNET, FRT & REAR BUMPER AND AFFECTED AREAS. TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTINGS, ADJUST HEADLAMP FOCUSING. TO REMOVE, REPLACE AIR CON PARTS, VACUUM AND RECHARGE AIR CON GAS. TO REMOVE, REPLACE DAMAGED BODYPARTS, REPAIR & RE-ALIGN BODYWORKS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.	NOT NECESSARY  NOT NECESSARY	800.00 60.00 200.00 800.00	600.00 - - 600.00
			1,860.00	1,200.00
<b>GRAND TOTAL</b>			<b>5,048.10</b>	<b>1,940.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,550.00</b>

Report Ref No. CS1/SPF19017392/Dyf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,550.00 - \$2,900.00

RECOMMENDED REPAIR DAYS : 4

WEEKENDS : 0

TOTAL DAYS : 4

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.