



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 399L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	O/S HEADLAMP	CRACKED	1,198.80	1,198.80
2	O/S HEADLAMP CLIP @\$5.00	NECESSARY	10.00	10.00
1	FRONT SUPPORT PANEL	CRACKED	949.30	949.30
1	FRONT BUMPER FOG LAMP COVER O/S	SERVICEABLE	115.40	-
1	BONNET	BADLY DENTED	1,910.80	1,910.80
1	FRONT GRILLE ASSY	CRACKED	495.80	495.80
1	FRONT BUMPER UPPER STRIPE	SERVICEABLE	31.40	-
1	FRONT BUMPER BRACKET O/S	BENT	28.00	28.00
1	FRONT BUMPER	BADLY DENTED	474.00	474.00
1	FRONT BUMPER SPONGE	TORN	117.00	117.00
8	FRONT BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
	LESS 20% DISCOUNT		-	-1,044.74
			5,370.50	4,178.96
<u>LABOUR</u>				
	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN FRONT O/S FENDER AND HEADLAMP PANEL AND REPLACE PARTS.		980.00	600.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		900.00	400.00
	CHECK ELECTRICAL.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	30.00
	REMOVE AND REFIT BONNET COMPONENTS.		100.00	40.00
	REWIRE FRONT PORTION AND REFOCUS O/S HEADLAMP BEAM.		50.00	30.00
			2,130.00	1,100.00
GRAND TOTAL			7,500.50	5,278.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS3/LPC19013765/R1vf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.