

2000000

ASS. REG. BY:

REF:

CS3/AIG19009303/T19d3-01

Instruction:

Survey: TANACH

ASSIGNMENT (Office)

From (Person): NG Jeffrusykat

of AIG

Date/Time: 2/10/2019

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JSM 6326

Insured: GBB 5739K

at Workshop m/s Motor Intel

Tel: 62810087

of 13 Kaki Bukit Rd 4 #01-20

Policy No: 2100146734

Claim No: 418198639686

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/5/2019

CA / REV / REP. / REV 24 HRS

28/5/2019

H.O.D. Endorsement:

Date/Time: 27/5

Person Contacted:

Svy

Vehicle IN/OUT

Date/Time	Action/Instruction
	Tanach / X
	JSM 6326 - X
	GBB 5739K - X
	Dismantle: 30/5/2019
	After repair: 24/6/2019

RECEIVED 01 NOV 2019

Submit L7 \$21950, 14 days  
(Ref \$2350, 10%)

4/5 \$21,950, 14 days

  
23/10/2019

INSPECTED BY: Tanpin  
**PRS**


ALG

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 28/5/2019  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY  
 To Inspect Vehicle No: JSM6326  
 at Workshop m/s: Motor Intel 62810087  
 of B Kaki Bukit Rd 4 #01-20  
 Insured: \_\_\_\_\_  
 Policy No.: \_\_\_\_\_  
 Claims No.: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$78K  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: JSM6326 Reg: 2014 Mar  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai Santa Fe cc 2359  
 Colour: white ACI: Insured / Std / NI / NA  
 Sp Reading: \_\_\_\_\_ Tftadio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: PL884D586R01300234  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / Siftim / STD A/Rim or  
 Tyre Size: F: 235/60R18  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A: \_\_\_\_\_ D.O.A: 28/5/19 0325p  
 Survey held at: Motor Intel  
 Des. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>Battery mark</u>
	<u>PRS</u>

Date/Time, File Pass (o) ☐ : Prel. Report  
☐ : Final Report

Days Of Repair: 7  
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. 1\$  
☐ Interview 1\$  
☐ Traffic Sign 1\$  
☐ Signatures 1\$

Survey Fee:	<u>180</u>
Conspiration:	
Other:	
Other:	<u>11</u>
Total:	<u>191</u>

Report Format: DAR  
 Using Sma / LER /

## Nivitha (LKK Auto)

---

**From:** Ng, Jeffreysaykiat <Jeffreysaykiat.Ng@aig.com>  
**Sent:** Wednesday, 2 October 2019 3:48 PM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** assignments; SUR  
**Subject:** RE: AIG ref: 4181986396SG003  
**Attachments:** 4181986396SG003 part 1.pdf

(Email 1 of 2)

Dear Hsiao Tong,

Noted that you have conducted the PRI and post inspection of TP vehicle JSM6326.

Please conduct a paper re-inspection of TP vehicle, thank you.

Jeffrey Ng  
AIG  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1916 | Fax +(65) 6835 7416

[Jeffreysaykiat.Ng@aig.com](mailto:Jeffreysaykiat.Ng@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.  
[Click here to find out more.](#)

Follow us:



### IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

Our Ref. : RSS/1905-7274 (MI)(PD)  
Your Ref. :

W : Natalie Ng  
E : natalie\_ng@rssolomon.com

13 September 2019

**AIG Asia Pacific Insurance Pte Ltd**

No. 78 Shenton Way  
#07-16 Lippo Centre  
Singapore 079120  
Attn: Motor Claim Dept

Dear Sirs,



By PDX: 8181  
**WITHOUT PREJUDICE**

**ACCIDENT INVOLVING JSM6326, GBB5739K & OTHERS ALONG JUNCTION OF MARINA BOULEVARD AND SHEARES AVENUE LAMP POST NO. 53F ON 25<sup>TH</sup> MAY 2019 AT ABOUT 1630 HRS**

We act for Teong Hoi Moi ("our client"), owner of vehicle registration no. JSM6326, and refer to the above-captioned matter.

2. We are instructed that you are the insurers of vehicle registration no. GBB5739K at the material time. We are further instructed that the aforesaid accident was caused solely by your insured and/or insured driver's negligence in her/his driving, controlling and/or management of the said vehicle. As a result of the accident, our Client's vehicle was damaged and she has been put to loss and expense, particulars of which are as follows: -

(a) Cost of Repair	\$ 26,001.00
(b) Loss of use for 26 working days at \$120.00 per day (i.e. including two days for Pre-repair survey)	\$ 3,120.00
(c) VEP Charges from 25 <sup>th</sup> May 2019 to 1 <sup>st</sup> July 2019 (after deduct of 7 days of VEP at \$35.00 per day)	\$ 492.40
(d) Towing fee	\$ 100.00
(e) Survey report fee	\$ 1,249.00
(f) LTA search fee	\$ 7.49
(g) Costs	\$ 900.00
(h) Transport, Xerox, postages & Other Incidentals	\$ 50.00
Total:	<b><u>\$31,919.89</u></b>

3. We enclose herewith copies of the following documents in support of our Client's claim: -
- (a) Final Repair Bill dated 30<sup>th</sup> July 2019 from Motor Intelligence Automoto Pte. Ltd;
  - (b) Survey Report with Invoice No. CL/190917 from CL Appraiser Pte Ltd;
  - (c) Payment receipt of Vehicle Entry Permit dated 1<sup>st</sup> July 2019 from Land Transport Authority;
  - (d) Tax Invoice No. 30338 dated 25<sup>th</sup> May 2019 for the payment of towing fee from Efficient Towing Services;

...2

Our Ref. : RSS/1905-7274 (MI)(PD)  
Your Ref. :

W : Natalie Ng  
E : natalie\_ng@rssolomon.com

13 September 2019



PAGE 2

- (e) Police Report lodged by our client's driver;
- (f) GIA search result on your insured vehicle (Client Not Found x3);
- (g) LTA search result with payment advice; and
- (h) 179 coloured photographs depicting damages to our client's vehicle registration No. JSM6326.

4. **TAKE NOTICE** that unless we receive your acknowledgement of receipt to this letter and enclosures **within fourteen (14) days from the date hereof**, our Client will have no alternative but to commence proceedings against your insured and/or its driver without further notice to you.

Yours faithfully,

**R. S. SOLOMON LLC**  
ADVOCATES & SOLICITORS

Encl.

Cc: **MPR INTERNATIONAL PTE LTD**  
2 Kallang Avenue  
#08-12 CT Hub  
Singapore 339407

**BY CERTIFICATE OF POSTING  
WITHOUT PREJUDICE**

*Note to insured and/or the driver: No enclosures have been provided to you; should you require copies of the afore-mentioned enclosures, please contact our office.*

**TAKE NOTICE** that if you have a counterclaim against our Client arising out of the above-captioned accident, you are required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of you receiving this letter.

PHOTOCOPY

		Motor Intelligence Automoto Pte. Ltd. Regn & GST No. : 201732961N Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807 Phone: 6281 0087/Fax: 6281 0187/Mobile: 9150 1587 Email: sales@mia.com.sg				
		Customer: <b>TEONG HOI MOI C/O MOTOR INTELLIGENCE AUTOMOTO PTE LTD</b>		Tax Invoice No: <b>INVOICE</b>		Date: <b>30/Jul/2019</b>
Contact Details:		Make and Model: <b>HYUNDAI SANTA FE</b>		Due upon receipt		
		Mileage: <b>60227KM</b>		Chassis/Car Plate No: <b>JSM 6326</b> <b>PL84D58GRD1300234</b>		
S/No:	Product	Description	Qty	Unit	Priced (SGD)	Amount (SGD)
1	COST OF REPAIR	LUMP SUM REPAIR OF ACCIDENT PORTION	1	JOB	24300.00	24300.00
Sub Total (SGD)						24300.00
GST 7%						1701.00
Total (SGD)						26001.00
Amount in words: DOLLARS TWENTY SIX THOUSAND AND ONE ONLY.						
Declaration: We declare that this Tax Invoice shows the actual price of the goods described and that all particulars are true and correct.				or Motor Intelligence Automoto Pte. Ltd.  Authorised Signatory		
Remarks :				Receiver Chop & Sign		

PHOTOCOPY

# C L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## INVOICE

Teong Hoi Moi  
C/o: Motor Intelligence Automo Pte Ltd  
13 Kaki Bukit Road 4, #01-20  
Bartley Biz Centre, Singapore 417807

Invoice No: CL/190917

Ref No: MITA/05/1908/TP

Date: 25 July 2019

### DESCRIPTION

### AMOUNT

#### OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. JSM 6326
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES  
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL      S\$1,249.00

E & O E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



# LCL APPRAISER PTE LTD

24 Penhurst Place, Singapore 556440  
Email: clappriser@yahoo.com Hp: 9068 8689 Fax: 6452 9781  
Reg No: 20190022RE

## VEHICLE INSPECTION REPORT

To: Teong Hoi Moi  
C/o: Motor Intelligence Automo Pte Ltd  
13 Kaki Bukit Road 4, #01-20  
Bartley Biz Centre, Singapore 417807

Date: 25 July 2019  
Our ref: MITA/05/1908/TP

Accident Date: 25 May 2019  
Inspection Date: 27 May 2019  
Repairer Name: Motor Intelligence Automo Pte Ltd  
13 Kaki Bukit Road 4, #01-20  
Bartley Biz Centre, Singapore 417807

Type of Survey: Third Party

### PARTICULARS OF VEHICLE

Registration No: JSM 6326  
Make / Model: Hyundai Sante Fe  
Chassis No: PL84D58GRD1300234  
Engine No: G4KEDU087463

Year / Capacity: 2014 / 2359 cc  
Colour: White  
Mileage: 60227

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Michelin	235/60 R18	5 mm	Sport
Front Offside	Michelin	235/60 R18	5 mm	Sport
Rear Nearside	Michelin	235/60 R18	5 mm	Sport
Rear Offside	Michelin	235/60 R18	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 179 copies

### REMARKS

This inspection was conducted entirely on a **"WITHOUT PREJUDICE"** basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation

The repairer has agreed to undertake the job at a **Lump Sum of \$ 24,300.00** on a contractual basis.

Under normal circumstances, the repair period would be about 24 (Twenty-Four) working days.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*. F
2	1		*FRT BUMPER	Broken	0.00 F	*. F
3	6		*FRT BUMPER CLIPS	Necessary	0.00 F	*. F
4	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*. F
5	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*. F
6	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*. F
7	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*. F
8	1		*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*. F
9	1		*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*. F
10	1		*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*. F
11	1		*FRT LH BUMPER FOG LAMP	Cracked	0.00 F	*. F
12	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*. F
13	1		*FRT GRILLE	Cracked	0.00 F	*. F
14	1		*FRT GRILLE EMBLEM	Missing	0.00 F	*. F
15	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*. F
16	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*. F
17	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Distorted	0.00 F	*. F
18	1		*HORN	Dented	0.00 F	*. F
19	1		*FRT BRACE PANEL	Bent	0.00 F	*. F
20	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*. F
21	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*. F
22	1		*BONNET	Buckled	0.00 F	*. F
23	1		*BONNET LOCK	Bent	0.00 F	*. F
24	2		*BONNET HINGE	Bent	0.00 F	*. F
25	1		*BONNET DAMPER	Broken	0.00 F	*. F
26	1		*AIR CON CONDENSER	Dented	0.00 F	*. F
27	1		*AIR CON FAN ASSY	Cracked	0.00 F	*. F
28	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	Dented	0.00 F	*. F
29	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Bent	0.00 F	*. F
30	1		*RADIATOR	Dented	0.00 F	*. F
31	1		*RADIATOR COWLING	Cracked	0.00 F	*. F
32	1		*RADIATOR FAN ASSY	Cut	0.00 F	*. F
33	1		*RADIATOR FAN CLUTCH	Jammed	0.00 F	*. F
34	1		*RADIATOR HOSE TOP	Bent	0.00 F	*. F
35	1		*AIR DUCT	Broken	0.00 F	*. F
36	1		*AIR CLEANER RESONATOR	Cracked	0.00 F	*. F
37	1		*FRT INLET MANIFOLD	Cut	0.00 F	*. F
38	1		*ENGINE UNDER COVER	Cracked	0.00 F	*. F
39	1		*FRT LH FENDER WHEEL ARCH PROTECTOR	Cracked	0.00 F	*. F
40	1		*FRT LH FENDER INNER SHIELD	Cracked	0.00 F	*. F
41	1		*FRT RH FENDER	Buckled	0.00 F	*. F
42	1		*FRT RH FENDER WHEEL ARCH PROTECTOR	Cracked	0.00 F	*. F
43	1		*FRT RH FENDER INNER SHIELD	Cracked	0.00 F	*. F
44	1		*DASHBOARD ASSY	Broken	0.00 F	*. F
45	1		*STEERING WHEEL AIRBAG	Buckled	0.00 F	*. F
46	1		*STEERING WHEEL AIRBAG SENSOR	Necessary	0.00 F	*. F
47	1		*DASHBOARD AIRBAG	Buckled	0.00 F	*. F
48	1		*DASHBOARD AIRBAG SENSOR	Necessary	0.00 F	*. F
49	1		*AIRBAG CONTROL UNIT	* Check	0.00 F	*. F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRT RH SEAT BELT ASSY	Jammed	0.00 F	*. F
51	1		*FRT LH SEAT BELT ASSY	Jammed	0.00 F	*. F
52	2		*AIR CON CONDENSER SIDE AIR DEFLECTOR	Cracked	0.00 F	*. F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

# **SCL APPRAISER PTE LTD**

Vehicle Registration No: JSM 6326

Our Ref No: MITA/05/1908/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Front bonnet	Damage	\$ 1,889.50	\$ 1,889.50
2	Front bonnet dampers	Damage	\$ 370.40	\$ 185.20 <i>LH-SUCK, RH-4+</i>
2	Front bonnet hinges	Damage	\$ 571.60	\$ 571.60
1	Front bonnet rear rubber	Necessary	\$ 48.00	\$ 48.00
2	Front headlamps	Damage	\$ 5,458.00	\$ 5,458.00
1	Front grille assy	Damage	\$ 855.80	\$ 855.80
1	Front grille logo	Necessary	\$ 111.60	\$ 111.60
1	Front bumper	Damage	\$ 1,277.50	\$ 1,277.50
1	Front bumper - lower garnish	Damage	\$ 525.00	\$ 525.00
2	Front bumper brackets	Damage	\$ 150.00	\$ 150.00
2	Front bumper fog lamps	Damage	\$ 770.00	\$ 770.00
2	Front bumper fog lamp covers	Damage	\$ 265.60	\$ 265.60
1	Front bumper inner sponge	Damage	\$ 183.80	\$ 183.80
1	Front bumper lower beam	Damage	\$ 195.00	\$ 195.00
1	Front bumper lower grille	Damage	\$ 127.60	\$ 127.60
1	Front bumper reinforcement	Damage	\$ 695.80	\$ 695.80
2	Front bumper side retainers	Necessary	\$ 121.60	\$ 121.60 <i>521.60</i>
2	Front fenders	Damage	\$ 1,043.20	\$ 1,043.20 <i>LH-Re, RH-n+</i>
2	Front fender inner shields	Damage	\$ 281.40	\$ 281.40
2	Front fender wheel arch garnishes	Damage	\$ 470.00	\$ 470.00
1	Front support panel	Damage	\$ 1,250.40	\$ 1,250.40
1	Front support panel top cover	Damage	\$ 155.60	\$ 155.60
1	Horn	Damage	\$ 89.60	\$ 89.60
1	Air con condenser	Damage	\$ 950.00	\$ 950.00
1	Radiator	Damage	\$ 875.00	\$ 875.00
1	Radiator electric fan assy	Damage	\$ 685.00	\$ 685.00
2	Radiator side garnishes	Damage	\$ 250.00	\$ 250.00
1	Air cleaner box	Damage	\$ 280.20	\$ 280.20
1	Air intake duct	Damage	\$ 125.80	\$ 125.80
1	Front dashboard	Damage	\$ 1,565.00	\$ 1,565.00
1	Air bag control unit	Damage	\$ 960.80	\$ 960.80
1	Steering wheel clock spring	Damage	\$ 375.00	\$ 375.00
1	Front steering air bag	Damage	\$ 2,450.00	\$ 2,450.00
1	Front passenger air bag	Damage	\$ 2,450.00	\$ 2,450.00
2	Front safety belts	Damage	\$ 1,790.00	\$ 1,790.00
			\$ 29,663.80	\$ 29,663.80

# SCL APPRAISER PTE LTD

Vehicle Registration No: JSM 6326

Our Ref No: MITA/05/1908/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
List Items Sub Total c/f			\$ 29,663.80	\$ 29,663.80

## SPARE PARTS - LIST ITEMS

1	Front n/s chassis frame	Repair	\$ 755.00	
1	Front chassis frame S.R.S sensor	Necessary	\$ 174.40	\$ 174.40
			\$ 30,593.20	\$ 29,838.20
			Less 20%	\$ 6,118.64
			\$ 24,474.56	\$ 23,870.56
Total Cost - List Items				

29/31.40  
23305.12

## SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00
1	Front bumper lower spoiler	Damage	\$ 800.00	\$ 800.00
1	Front number plate with holder	Damage	\$ 50.00	\$ 50.00
2	Front fender inner shield clips (2 set)	Necessary	\$ 90.00	\$ 90.00
Total Cost - Special Nett items			\$ 1,000.00	\$ 1,000.00

715

Total cost of parts

\$ 25,474.56 \$ 24,870.56

# SCL APPRAISER PTE LTD

Vehicle Registration No: JSM 6326

Our Ref No: MITA/05/1908/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 25,474.56</b>	<b>\$ 24,870.56</b>

## LABOUR

1	To check wiring, lighting and resetting headlamps focussing.	\$ 80.00	\$ 50.00 <sup>30</sup>
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 <sup>Xnn</sup>
3	To remove, refit and reset Air bag systems.	\$ 300.00	\$ 250.00 <sup>180</sup>
4	To remove and replace air-con condenser, vacuum, refill gas and conduct leakage test.	\$ 180.00	\$ 120.00 <sup>/</sup>
5	To remove and refit dashboard to assist repair.	\$ 300.00	\$ 250.00 <sup>180</sup>
6	To apply undercoating on repaired and replaced panel.	\$ 200.00	\$ 150.00 <sup>100</sup>
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$ 2,500.00	\$ 2,250.00 <sup>1300</sup>
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 2,400.00	\$ 1,980.00 <sup>1320</sup>
9	To diagnose erase fault memory after repair.	\$ 300.00	\$ 300.00 <sup>200</sup>

## GRAND TOTAL

**\$ 31,884.56    \$ 30,340.56**

27450.12  
415121950  
14days

## C L APPRAISER PTE LTD

Vehicle Registration No: JSM 6326

Our Ref No: MITA/05/1908/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : S 24,300.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

### Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD



Cheong K. H  
Automotive Appraiser





PHOTOCOPY



# Efficient Towing Services

10000 10000 10000

CASH/SALE ORDER

TEL 800-332

25/5/5

Cash

BM 6326

PAY

Shane Ave

Bartley 1000 1000 1000

\$ 1000

AM D.

A/Ly

Per 1

1000



# SINGAPORE POLICE FORCE



T/20190525/2148

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

1 of 3

Report No. T/20190525/2148

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/05/2019 19:34	Vide Report No.: A/20190525/0098	Station Diary No.: 103
--	-------------------------------------	---------------------------

### Informant's Particulars

Name of Informant: NG SOON SONG			Address: 42 PANDAN ROAD SINGAPORE 609284		
ID Type / ID No.: FIN NO / F7778907M			Contact No.: Home/Office: Mobile: 88664840		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 56	Date of Birth: 22/11/1962	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: CONSTRUCTION SUPERVISOR			Driving Licence Information: Class: 2B,3,4 Date of Expiry:		

### General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/05/2019 16:30	Type of Location: X-Junction
Location: Along Road 1 MARINA BOULEVARD  Junction of Marina Boulevard and Sheares Avenue. Lamp Post Number: 53F				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB5739K	Lorry				Seriously Damaged	0
JSM6326	Car				Seriously Damaged	2
SHD8872G	Car				Slightly Damaged	1



**SINGAPORE  
POLICE FORCE**



T/20190525/2148

2 of 3

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

Report No: T/20190525/2148

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	NG SOON SONG	ID No.	F7778907M
Related Vehicle	JSM6326 (Car)	Contact No.	88664840
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On the above date, time and location, I was driving along marina boulevard, on the 3rd lane. I was the first car in front of the stop line when the traffic light was red. when it turn green, I moved on to move my vehicle, suddenly, I see one lorry that came at a high speed from my left, I could not brake in time and we collided. The impact was between his front part of his car to my front side of my car. His lorry toppled and my car was unable to drive anymore, after the lorry had the first impact with me, he had second impact with another taxi that was on my right side. I do not have any particulars of any drivers that was at scene. I do not need medical attention now but I might be going to see the doctor if the pain is unbearable.

that is all



**SINGAPORE  
POLICE FORCE**



T/20190525/2148

Police Station Of Origin:  
Rochor N.P.C  
11 Kampong Kapur Road SINGAPORE  
208678  
Tel No: 1800-2949999

3 of 3

Report No. T/20190525/2148

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

Sgt 1 NG WEI XIANG ALLAN

Signature Of Informant

Signature Of Interpreter:

Not applicable

Date/Time:

25/05/2019 19:34

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

Contact No.: 65476216

Classification Of Case:

Authentication Stamp

NP168

# Search History Of TP Accident Report

<< Back

Search

Use All

Accident Date

From

To

Date Of Search

From

To

Type

Vehicle

Passenger/Pedestrian

Foreign Vehicle

Requested Vehicle No

GBB573NK

Warrant To Act /

Signed & Scanned Application Form

Purchase/Status

NO.	DATE SEARCHED	DATE WHEN UPLOADED	TYPE	SET NUMBER	YOUR CLIENT	DATE OF ACCIDENT	PLACE OF ACCIDENT	SEARCH STATUS	IP ADDRESS	REMARKS	PURCHASE STATUS
1	11/09/2019 14:28	11/09/2019 14:28	VEHICLE	85561905-72740401(PD)	10M6126	25/05/2019	MAUNA BLVD & SHEARER AVE LPS3	Client Not Found Search Again	28B573NK		
2	11/09/2019 11:26	11/09/2019 11:26	VEHICLE	85561905-72740401(PD)	10M6126	25/05/2019	MAUNA BLVD & SHEARER AVE LPS3	Client Not Found	28B573NK		
3	11/09/2019 14:57	11/09/2019 14:57	VEHICLE	85561905-72740401(PD)	10M6126	25/05/2019	MAUNA BLVD & SHEARER AVE LPS3	Client Not Found	28B573NK		

**Enquire Vehicle & Owner Information ( Vehicle No. GBB5739K As At 25 May 2019 / 16:30:00 )****SEARCH REASON AND DETAILS**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: RSS/1905-7274(MI/PD)

**OWNER INFORMATION**

Owner ID Type: Company  
Owner ID: 199501819E  
Owner Name: MPR INTERNATIONAL PTE LTD  
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
Registered Block/House No.: 2  
Registered Street Name: KALLANG AVENUE  
Registered Unit No.: # 08 - 12  
Registered Building Name: CT HUB  
Registered Postal Code: 339407

**VEHICLE INFORMATION**

Vehicle No.: GBB5739K  
Make Description/Model: NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T  
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE LTD



Thank you

See Kai Noor has successfully logged out.

Your next login date will be on 27 May 2018, 11:55:44.

To return to ONE MOTORING, please click here

For security reasons, please CLEAR YOUR CACHE after each session.

## Session Transaction History

S No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	CEB5729K		SE 197 Escorted With Owner into Charge of the Lane Entry	7.40	27 May 2018 / 12:01:26

## Sherwin Beh (LKK Auto)

---

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Thursday, 3 October, 2019 8:23 AM  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto)  
**Cc:** Bryan Ang (LKKAuto); Intan Wulandari (SPF); Chee Sing TAN (SPF)  
**Subject:** Mechanical Inspection Report Request [URGENT]

Dear Sir,

May I seek your assistance to perform a detailed mechanical inspection of the following 1 vehicle on an urgent basis as the vehicles below are required to be returned to the owner ASAP:

**a) Case IAFP-IB-20191003 - Mechanical Inspection of Motor Van, GZ557R (TP/IP/44533/2019)**

On 17 July 2019 at about 04.50 pm, Police incident was created regarding an accident along Marymount Rd by Marymount Lane. The motor van, GZ557R, was travelling on the rightmost lane of 5-lanes along Marymount Rd towards Thomson Rd. Driver informed that upon approaching the said junction of Marymount Lane, traffic light was showing red. At the time, there was an unknown stationary motor car ahead of him. When he applied brakes, the vehicle continued moving forward and as such, in order for him to avoid colliding onto the rear of the said unknown motor car – he swerved to the right, mounted onto the centre divider and subsequently collided onto a traffic light pole. Driver did not sustain any injury however claimed that the motor van brakes are faulty.

**Vehicle to be inspected:** GZ557R - Driver (Potential Defendant)

IO In-Charge: IO Intan

2. Thank you Sirs.

cc: Bryan, fyip  
CIO Clement & IO Intan, as requested by you & fyip

Best regards,

Kamaliah Kamis (Miss)  
Senior Investigation Officer | Fatal Accident Investigation Team  
Traffic Police Department | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



**HOME TEAM**  
TRANSFORMATION 2025  
One Home. One Team  
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



## Sherwin Beh (LKK Auto)

---

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Thursday, 3 October, 2019 8:23 AM  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto)  
**Cc:** Bryan Ang (LKKAuto); Intan Wulandari (SPF); Chee Sing TAN (SPF)  
**Subject:** Mechanical Inspection Report Request [URGENT]

Dear Sir,

May I seek your assistance to perform a detailed mechanical inspection of the following 1 vehicle on an urgent basis as the vehicles below are required to be returned to the owner ASAP:

a) **Case IAFP-IB-20191003 - Mechanical Inspection of Motor Van, GZ557R (TP/IP/44533/2019)**

On 17 July 2019 at about 04.50 pm, Police incident was created regarding an accident along Marymount Rd by Marymount Lane. The motor van, GZ557R, was travelling on the rightmost lane of 5-lanes along Marymount Rd towards Thomson Rd. Driver informed that upon approaching the said junction of Marymount Lane, traffic light was showing red. At the time, there was an unknown stationary motor car ahead of him. When he applied brakes, the vehicle continued moving forward and as such, in order for him to avoid colliding onto the rear of the said unknown motor car – he swerved to the right, mounted onto the centre divider and subsequently collided onto a traffic light pole. Driver did not sustain any injury however claimed that the motor van brakes are faulty.

**Vehicle to be inspected:** GZ557R - Driver (Potential Defendant)

IO In-Charge: IO Intan

2. Thank you Sirs.

cc: Bryan, fyip  
CIO Clement & IO Intan, as requested by you & fyip

Best regards,

**Kamaliah** Kamis (Miss)  
Senior Investigation Officer | Fatal Accident Investigation Team  
Traffic Police Department | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG19009303/T1qd3e2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-11-2019	
ATTN : NG JEFFREY SAY KIAT		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBB 5739K	Veh. Inspected	JSM 6326
Policy No.	2100146734	Coverage (\$)	0.00
Claim No.	4181986396SG	Excess (\$)	0.00
Assign From	NG JEFFREY SAY KIAT	Assign Date	02/10/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI SANTA FE	c.c	2359
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	PL84D58GRD1300234	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/60 R18	MICHELIN	6 mm
L/H Front Tyre	235/60 R18	MICHELIN	6 mm
R/H Rear Tyre	235/60 R18	MICHELIN	6 mm
L/H Rear Tyre	235/60 R18	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	25/05/2019	Inspection Date	28/05/2019
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSM 6326

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BONNET	DAMAGED	1,889.50	1,889.50
2	FRONT BONNET DAMPERS	N/S SERVICEABLE / O/S BENT	370.40	185.20
2	FRONT BONNET HINGES	DAMAGED	571.60	571.60
1	FRONT BONNET REAR RUBBER	NECESSARY	48.00	48.00
2	FRONT HEADLAMPS	DAMAGED	5,458.00	5,458.00
1	FRONT GRILLE ASSY	DAMAGED	855.80	855.80
1	FRONT GRILLE LOGO	NECESSARY	111.60	111.60
1	FRONT BUMPER	DAMAGED	1,277.50	1,277.50
1	FRONT BUMPER - LOWER GARNISH	DAMAGED	525.00	525.00
2	FRONT BUMPER BRACKETS	DAMAGED	150.00	150.00
2	FRONT BUMPER FOG LAMPS	DAMAGED	770.00	770.00
2	FRONT BUMPER FOG LAMP COVERS	DAMAGED	265.60	265.60
1	FRONT BUMPER INNER SPONGE	DAMAGED	183.80	183.80
1	FRONT BUMPER LOWER BEAM	DAMAGED	195.00	195.00
1	FRONT BUMPER LOWER GRILLE	DAMAGED	127.60	127.60
1	FRONT BUMPER REINFORCEMENT	DAMAGED	695.80	695.80
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	121.60	121.60
2	FRONT FENDERS	N/S TO REPAIR SEE LABOUR / O/S BENT	1,043.20	521.60
2	FRONT FENDER INNER SHIELDS	DAMAGED	281.40	281.40
2	FRONT FENDER WHEEL ARCH GARNISHES	DAMAGED	470.00	470.00
1	FRONT SUPPORT PANEL	DAMAGED	1,250.40	1,250.40
1	FRONT SUPPORT PANEL TOP COVER	DAMAGED	155.60	155.60
1	HORN	DAMAGED	89.60	89.60
1	AIR CON CONDENSER	DAMAGED	950.00	950.00
1	RADIATOR	DAMAGED	875.00	875.00
1	RADIATOR ELECTRIC FAN ASSY	DAMAGED	685.00	685.00
2	RADIATOR SIDE GARNISHES	DAMAGED	250.00	250.00
1	AIR CLEANER BOX	DAMAGED	280.20	280.20
1	AIR INTAKE DUCT	DAMAGED	125.80	125.80

Report Ref No. CS3/AIG19009303/T1qd3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DASHBOARD	DAMAGED	1,565.00	1,565.00
1	AIR BAG CONTROL UNIT	DAMAGED	960.80	960.80
1	STEERING WHEEL CLOCK SPRING	DAMAGED	375.00	375.00
1	FRONT STEERING AIR BAG	DAMAGED	2,450.00	2,450.00
1	FRONT PASSENGER AIR BAG	DAMAGED	2,450.00	2,450.00
2	FRONT SAFETY BELTS	DAMAGED	1,790.00	1,790.00
1	FRONT N/S CHASSIS FRAME	TO REPAIR SEE LABOUR	755.00	-
1	FRONT CHASSIS FRAME S.R.S SENSOR	NECESSARY	174.40	174.40
	LESS 20% DISCOUNT		-6,118.64	-5,826.28
			24,474.56	23,305.12
	<b>SPECIAL NETT ITEMS</b>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	FRONT BUMPER LOWER SPOILER (SN)	DAMAGED	800.00	600.00
1	FRONT NUMBER PLATE WITH HOLDER (SN)	DAMAGED	50.00	45.00
2	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	90.00	40.00
			1,000.00	715.00
	<b>LABOUR</b>			
	TO CHECK WIRING, LIGHTING AND RESETTNG HEADLAMPS FOCUSING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE, REFIT AND RESET AIR BAG SYSTEMS.		300.00	180.00
	TO REMOVE AND REPLACE AIR-CON CONDENSER, VACUUM, REFILL GAS AND CONDUCT LEAKAGE TEST.		180.00	120.00
	TO REMOVE AND REFIT DASHBOARD TO ASSIST REPAIR.		300.00	180.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		200.00	100.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT, INCLUSIVE OF THE REPAIR OF FRONT FENDERS N/S AND FRONT N/S CHASSIS FRAME.		2,500.00	1,300.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		2,400.00	1,320.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.		300.00	200.00
			6,410.00	3,430.00
GRAND TOTAL			31,884.56	27,450.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				21,950.00

Report Ref No. CS3/AIG19009303/T1qd3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.