

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19017412/T1KA3Q2

**Date:** 22/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700094123

**Claimant**  
**Vehicle No :** SDE8136R **Insured Vehicle No :** SLV4361Z

Date of Loss: 30/09/2019 Nature of Claim: TP Claim No: 2201631403SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDE8136R</b>		
Make & Model:	BMW 740LI, 3.0 SR LED (A)	Engine No:	HIDDEN
Reg. Date:	27/11/2015 (Man. Year: 2015)	Chassis No:	WBA7E22060GD99707
Colour:	White	Odometer:	48430 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45R19	Rear Tyre Size:	245/45R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,827.20	10,253.25	573.95	5.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,169.00	4,958.00	1,211.00	19.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>16,996.20</b>	<b>15,211.25</b>	<b>1,784.95</b>	<b>10.50</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,189.73	1,064.79	124.94	10.50
<b>Nett Amount (\$\$)</b>	<b>18,185.93</b>	<b>16,276.04</b>	<b>1,909.89</b>	<b>10.50</b>
<b>+ Loss of Use (5.0 x S\$120.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>16,878.04</b>		

### INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*ALLOY RIM 8.5JX19 V SPK 620	Cut	1,305.95 FS	*1,305.95 FS
3	1		*FRT LH SIDE PANEL ALUMINIUM	Bent	1,298.50 FS	*1,298.50 FS
4	1		*FRT RH 1 SIDE PANEL BRACKET	Not Necessary	34.95 FS	*- FS
5	1		*SET MOUNTS PDC SENSOR FRT	Not Necessary	69.00 FS	*- FS
6	1		*GUIDE LH BOTTOM	Not Necessary	40.50 FS	*- FS
7	1		*GUIDE TOP LH	Not Necessary	40.50 FS	*- FS
8	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,612.90 FS	*1,612.90 FS
9	4		*DECOUPLING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
10	1		*ULTRASONIC SENSOR MINERALWEISS (WA96)	Not Necessary	368.80 FS	*- FS
11	2		*ADJUSTABLE BLIND RIVET	Necessary	6.60 FS	*6.60 FS
12	5		*RIVET	Necessary	2.50 FS	*2.50 FS
13	1		*LH HEADLIGHT LED AHL HIGH (ICON LIG)	Cut	5,876.80 FS	*5,876.80 FS
					<b>Total Parts (S\$)</b>	<b>10,827.20      10,253.25</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE LEFT LED AHL HEADLIGHT	New	481.00	481.00
2	TO REPLACE FRONT BUMPER ,FENDER LEFT AND ATTACHMENTS	New	2,550.00	1,700.00
3	PAINTING FRONT BUMPER AND FENDER LEFT	New	2,218.00	1,996.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
5	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,169.00</b>	<b>4,958.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >