

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017427/ABA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SME529L **Insured Vehicle No :** SLX8390C

Date of Loss: 28/09/2019 **Nature of Claim:** TP **Claim No:** 1395470088SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME529L		
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Engine No:	6ARP432174
Reg. Date:	17/09/2018 (Man. Year: 2018)	Chassis No:	MR053DK5100113582
Colour:	Black	Odometer:	21982 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,320.86	3,095.85	5,225.01	62.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,890.00	1,540.00	44.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,750.86	4,985.85	6,765.01	57.57
+ GST 7.00/7.00% (S\$)	822.56	349.01	473.55	57.57
Nett Amount (S\$)	12,573.42	5,334.86	7,238.56	57.57
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,136.86		
Global Sum Settlement (S\$)		6,050.00		

INSPECTION

Date of Assignment: 02/10/2019

Date Inspected: 02/10/2019 Inspected At:

Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
AutoHub
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,217.45 FL	*1,217.45 FL
2	1		*REAR BOOT LID CAMRY EMBLEM	Necessary	152.10 FL	*68.00 FL
3	1		*REAR BOOT LID TOYOTA LOGO	Necessary	161.50 FL	*70.00 FL
4	1		*REAR BOOT LID D4S EMBLEM	Necessary	82.70 FL	*82.70 FL
5	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	278.75 FL	*- FL
6	1		*REAR BOOT LID MECHANISM LOCK	Damaged	371.70 FL	*371.70 FL
7	2		*REAR BOOT LAMP L/R	Not Necessary	855.70 FL	*- FL
8	1		*REAR BOOT CHROME TRIM	Not Necessary	317.45 FL	*- FL
9	1		*REAR NO PLATE LAMP GARNISH	Not Necessary	281.90 FL	*- FL
10	1		*REAR LAMP ASSY L/R	N/S Cracked	942.20 FL	*471.10 FL
11	1		*REAR BUMPER ASSY	Deformed	758.45 FL	*758.45 FL
12	8		*REAR BUMPER CLIPS	Necessary	127.20 FL	*30.00 FL
13	1		*REAR BUMPER SIDE HOLDER LH	Necessary	191.70 FL	*191.70 FL
14	1		*REAR BUMPER BRACKET LH	Not Necessary	189.25 FL	*- FL
15	1		*REAR BUMPER INNER SPONGE	Not Necessary	218.90 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	431.70 FL	*431.70 FL
17	1		*REAR BUMPER SIDE INNER LINER LH	Not Necessary	198.05 FL	*- FL
18	1		*REAR LAMP PANEL LH	Repair	413.85 FL	*- FL
19	1		*REAR END PANEL	Repair	731.40 FL	*- FL
20	1		*REAR PANEL INNER TOP GARNISH	Not Necessary	391.70 FL	*- FL
21	1		*REAR SPARE TYRE PANEL	Not Necessary	471.45 FL	*- FL
22	1		*REAR BUMPER REFLECTOR LH	Cut	35.00 FL	*35.00 FL
23	1		*REAR BUMPER LOWER GARNISH	Not Necessary	321.05 FL	*- FL
24	1		*REAR CHASSIS FRAME LH	Repair	780.00 FL	*- FL
25	1		*SET REVERSE SENSOR	Damaged	880.00 FS	*300.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					10,801.15	4,027.80
- List Item Discount on L Items 25.00/25.00% (\$\$)					2,480.29	931.95
Total Parts (\$\$)					8,320.86	3,095.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REARRANGE ELECTRICAL WIRING ,CHECK LIGHTING	New	80.00	30.00
2	TO REMOVE,REINSTAL UPHOLSTERY INNER TRIM GARNISHES	New	250.00	60.00
3	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,600.00	1,000.00
4	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,430.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >