



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2007978  
INV Date 26/11/2020  
Reference CC6/CTI19017446/Aka3q2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SJK 6106M  
Insured Veh. PC 2128Y  
Claim No. SNM19D204647  
Policy No. DMB1SN1745521802  
Accident Date 01/10/2019  
Inspection Date 02/10/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19017446/Aka3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-11-2020



Code : CTI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 2128Y	Veh. Inspected	SJK 6106M
Policy No.	DMB1SN1745521802	Coverage (\$)	0.00
Claim No.	SNM19D204647	Excess (\$)	0.00
Assign From		Assign Date	02/10/2019

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305081729	Colour	GREY
Odometer	192316	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	NEUTON	6 mm
L/H Front Tyre	185/60 R15	NEUTON	6 mm
R/H Rear Tyre	185/60 R15	NEUTON	6 mm
L/H Rear Tyre	185/60 R15	NEUTON	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	01/10/2019	Inspection Date	02/10/2019
Survey held at	GREEN FOREST AUTOMOBILE PTE LTD 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		

#### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6106M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAIL LAMP-RH	CRACKED	333.70	333.70
4	REAR TAIL LAMP CLIPS @\$6.50	NECESSARY	26.00	26.00
1	REAR TAIL LAMP PANEL	NOT NECESSARY	281.10	-
1	REAR BUMPER	TORN	581.75	581.75
8	REAR BUMPER CLIPS @\$6.50	NECESSARY	52.00	30.00
1	REAR BUMPER REVERSE SENSOR	NOT NECESSARY	350.00	-
1	REAR BUMPER BRACKET	NOT NECESSARY	131.70	-
1	REAR BUMPER SIDE REFLECTOR-RH	NOT NECESSARY	83.10	-
1	REAR BUMPER INNER SPONGE (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REINFORCEMENT (NPA)	NOT NECESSARY	-	-
1	REAR FENDER-RH	DISTORTED	972.40	972.40
1	REAR FENDER INNER TRIM BOARD-RH	NOT NECESSARY	325.10	-
10	REAR FENDER INNER TRIM BOARD CLIPS @\$6.50	NOT NECESSARY	65.00	-
1	REAR FENDER MUD-SHIELD	NOT NECESSARY	112.10	-
2	REAR FENDER MUD-SHIELD CLIPS @\$12.90	NOT NECESSARY	25.80	-
1	REAR DOOR	TO REPAIR SEE LABOUR	1,020.00	-
1	REAR DOOR HANDLE	NOT NECESSARY	155.20	-
1	REAR DOOR CENTER PROTECTOR	NOT NECESSARY	158.20	-
1	REAR AXLE ASSY	BENT	2,350.00	1,670.00
1	REAR RIM	CUT	400.00	400.00
1	REAR SHOCK ABSORBER-RH	BENT	380.20	380.20
1	REAR AXLE BEARING-RH	DAMAGED	358.00	358.00
	LESS 25% DISCOUNT		-	-1,188.01
			8,161.35	3,564.04
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR TIRE-RH (SN)	DEFORMED	350.00	180.00
			350.00	180.00
<b><u>LABOUR</u></b>				
	TO REMOVE & REFIT CUSHION.		150.00	80.00

Report Ref No. CC6/CTI19017446/Aka3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIX REAR UNDERCARRIAGE WITH AXLE ASSY.		280.00	280.00
	TO CHECK WIRING.		60.00	30.00
	WHEEL ALIGNMENT (COMPUTER).		120.00	80.00
	TUFF KOTE.		120.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR.		1,000.00	600.00
	SPRAY PAINTING.		1,000.00	600.00
			2,830.00	1,780.00
<b>GRAND TOTAL</b>			<b>11,341.35</b>	<b>5,524.04</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,400.00</b>
---	--	--	--	-----------------

Report Ref No. CC6/CTI19017446/Aka3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJK 6106M

RE-INSPECTION





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJK 6106M

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJK 6106M

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

