

12/03/2002

ASS. REC. BY:

REF: CS/FCI/19017451/K29d3

Special Instruction:

SURVIVOR: Rasul

ASSIGNMENT (Office)

CWS

From (Person): Jason Tea

of FCI

Date/Time: 5.43pm @ 21/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 3982R

Insured:

SHB 4329X

at Workshop m/s

Cold Bell Engineering

Tel:

9739 6433

of

10 Juea Avenue 18

Policy No:

Claim No:

D19006310MFST

Sum Insured:

Excess:

Make of Vch:

D.O.A

26/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS up?

H.O.D. Endorsement:

Date/Time: 4. PM 23/10/19

Person Contacted:

Kon

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	PC 3982R - X
	SHB 4329X - CS/FCI/18014352/K19d3n2 D.O.A: 3/8/2018
18/10/19 @	1202x revised to Jason Tea by email.
06/11/19 @	11.4 bar checked with Yin Siew, the vehicle has not send in for repair due to awaiting liability issued.
06/11/19	Submit Prelim. report.
20/12/19	Reopen ref. for submit final report. (close 20/12/19) * kindly assist pass to transport after reopen
03/01/20 @ 2.41pm	confirmed with Yin Siew US \$ 950, 4 days. (Red to \$535.18, 85%).
7/1/20	reopen ref only & let close date 14/11/19. * ↓

ASS. REC. BY: ASULREF: FCI458H

ASSIGNMENT

From: _____ Date: 16.10.2019

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: PC 3982Rat Workshop m/s: Goldbell Engineeringof 10 Tunc Ave 12

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____


(Client's Record)

Make of Veh: _____

12pm - 1pmYm Slew

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 3982R Yr Regn: 2015 / SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MINI-BusMake: MITSUBISHI ROSA BG 641 CC 2998Colour WHITE A/C: Insured / Std / NI / NASp. Reading 35/65 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BE 641JK30047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/85R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 26/02/19 D.O.I. 16/10/19Survey held at GOLDBELL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +.

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 NOV 2019

Date/Time, File Pass to?

☒: Prel. Report10/11/2019☐: Final Report

Date/Time, File Return to?

3*

Rep. Format:

Lump Sum / L.B. / O.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos:

Others:

TOTAL

1455018213

Shiau Chan (LKKAUTO)

From: Kon Yin Siew <KonYinSiew@goldbell.com.sg>
Sent: Friday, 3 January 2020 2:41 PM
To: Shiau Chan (LKKAUTO); SUR
Cc: Brian Eng Kwok Long; Ramesh; Rasul (LKKAUTO); William Oh Soon Lee
Subject: RE: Finalise for PC3982R

Hi Shiau Chan,


Confirmed finalised at lump sum \$950.

Thank you.



Kon Yin Siew | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6861 0007 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9739 6433 |



From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, January 3, 2020 10:01 AM
To: Kon Yin Siew <KonYinSiew@goldbell.com.sg>; SUR <sur@lkkauto.com>
Cc: Brian Eng Kwok Long <EngKwokLong@goldbell.com.sg>; Ramesh <Ramesh@goldbell.com.sg>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: RE: Finalise for PC3982R

Dear Yin Siew,

Can confirm?

Best Wishes for Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 20 December 2019 1:44 PM



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 630824
Tel: +65 6881 0007 Fax: +65 6881 3675 (Sales)
Fax: +65 6883 0425 (Service) +65 6882 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No: 16803963D

Page 1 / 2

ESTIMATE

Date	: 01/10/2019	Reg No	: PC3982R
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: BE641JRMDEB AMT
Attn.	:	Chassis No	: BE641JK30047
Office / Mobile	:	Engine No	: 4P10B68915
Email Address	:	Quotation No.	: 96767
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 26/09/2019
Attn.	: KONYINSIEW	Policy No.	: B29134304MKC
Office / Mobile	: +65 9739 6433	Claim Type	: TP CLAIM - MS FIRST CAPITAL
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MR598528	MARK,THREE-DIA MITSUBISHI <i>for XAN</i>	1	38.85	-0	38.85	38.85
2	MK576269	BUMPER,FR <i>repair</i>	1	1,562.91	-0	1,562.91	1,562.91
3	MC180435	STAY,FR BUMPER,RH <i>X SUC</i>	1	43.00	-0	43.00	43.00
4	MC180434	STAY,FR BUMPER,LH <i>X SUC</i>	1	83.66	-0	83.66	83.66
5	MC180180	PANEL,FR SIDE -LH <i>repair</i>	1	2,852.70	-0	2,852.70	2,852.70
6	MK533362	LAMP ASSY,SIDE TURN SIGNAL <i>for</i>	1	62.37	-0	62.37	62.37
7	MK578149	PLATE ASSY,SIDE T/SIG LAMP <i>X SUC</i>	1	41.69	-0	41.69	41.69

PARTS TOTAL : 4,685.18

SPECIAL NETT ITEMS

1	STICKERS <i>n2c</i>	1	450	700.00
PARTS TOTAL:			700.00	

LABOUR CHARGES

1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	550	800.00
2	TO REMOVE AND INSTALL STICKERS	150	200.00
3	TO CHECK AND RECONNET ALL NECESSARY WIRING	30	100.00

LABOUR TOTAL : 1,100.00

SUB-TOTAL : 6,485.18

GST @ 7% for \$ 6,485.18 453.96

GRAND TOTAL (S\$) : 6,939.14



10 Tuas Avenue 10 Singapore 635554
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co Reg No. 198003963

ESTIMATE



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 1580010650

Page 1 / 2

ESTIMATE

Date	: 01/10/2019	Reg No	: PC3982R
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: BE641JRMDEB AMT
Attn.	:	Chassis No	: BE641JK30047
Office / Mobile	:	Engine No	: 4P10B68915
Email Address	:	Quotation No.	: 96767
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 26/09/2019
Attn.	: KONYINSIEW	Policy No.	: B29134304MKC
Office / Mobile	: +65 9739 6433	Claim Type	: TP CLAIM - MS FIRST CAPITAL
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MR598528	MARK,THREE-DIA MITSUBISHI MR X	1	38.85	-0	38.85	38.85
2	MK576269	BUMPER,FR <i>repair</i>	1	1,562.91	-0	1,562.91	1,562.91
3	MC180435	STAY,FR BUMPER,RH X	1	43.00	-0	43.00	43.00
4	MC180434	STAY,FR BUMPER,LH X	1	83.66	-0	83.66	83.66
5	MC180180	PANEL,FR SIDE -LH <i>repair</i>	1	2,852.70	-0	2,852.70	2,852.70
6	MK533362	LAMP ASSY,SIDE TURN SIGNAL <i>bro</i> ✓	1	62.37	-0	62.37	62.37
7	MK578149	PLATE ASSY,SIDE T/SIG LAMP X	1	41.69	-0	41.69	41.69

PARTS TOTAL : 4,685.18

SPECIAL NETT ITEMS

1	STICKERS	1	450	700.00
PARTS TOTAL:			700.00	

LABOUR CHARGES

1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	550	800.00
2	TO REMOVE AND INSTALL STICKERS	150	200.00
3	TO CHECK AND RECONNET ALL NECESSARY WIRING	30	100.00

LABOUR TOTAL : 1,100.00

SUB-TOTAL : 6,485.18

GST @ 7% for \$ 6,485.18 453.96

GRAND TOTAL (S\$) : 6,939.14

P: 62.37
SN: 450.00
L: 730.00
1242.37

450: \$990



Certificate No. AUR/S/0101243 Certificate No. AUR/S/0101243

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19017451/R1qd3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4329X	Veh. Inspected	PC 3982R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006310MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	02/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ROSA BE641	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	BE641JK30047	Colour	WHITE	
Odometer	35165	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/85 R16	DUNLOP	7 mm	
L/H Front Tyre	205/85 R16	DUNLOP	7 mm	
R/H Rear Tyre	205/85 R16	DUNLOP	7 mm	
L/H Rear Tyre	205/85 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/09/2019	Inspection Date	16/10/2019	
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3982R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MARK, THREE-DIA MITSUBISHI	NOT NECESSARY	38.85	-
1	BUMPER, FR	TO REPAIR SEE LABOUR	1,562.91	-
1	STAY, FR BUMPER, RH	SERVICEABLE	43.00	-
1	STAY, FR BUMPER, LH	SERVICEABLE	83.66	-
1	PANEL, FR SIDE - LH	TO REPAIR SEE LABOUR	2,852.70	-
1	LAMP ASSY, SIDE TURN SIGNAL	BROKEN	62.37	62.37
1	PLATE ASSY, SIDE T/SIG LAMP	SERVICEABLE	41.69	-
			4,685.18	62.37
SPECIAL NETT ITEMS				
1	STICKERS (SN)	NECESSARY	700.00	450.00
			700.00	450.00
LABOUR				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF BUMPER, FR AND PANEL, FR SIDE - LH.		800.00	550.00
	TO REMOVE AND INSTALL STICKERS.		200.00	150.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		100.00	30.00
			1,100.00	730.00
GRAND TOTAL			6,485.18	1,242.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				950.00

Report Ref No. CS/FCI19017451/R1qd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.