

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19017454/APA3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : YN5998T	Insured Vehicle No :	SHD4424T
Date of Loss: 01/10/2019	Nature of Claim: TP	Claim No: MCT19100010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN5998T		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Engine No:	4P10B28602
Reg. Date:	29/08/2014 (Man. Year: 2014)	Chassis No:	FEB21EA00767
Colour:	White	Odometer:	219565 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195 R15C
Front Left Side:	Delium 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Delium 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,543.00	4,398.00	4,145.00	48.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,860.00	900.00	32.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,303.00	6,258.00	5,045.00	44.63
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	11,303.00	5,000.00	6,303.00	55.76
+ GST 7.00/7.00% (S\$)	791.21	350.00	441.21	55.76
Nett Amount (S\$)	12,094.21	5,350.00	6,744.21	55.76
+ Loss of Use (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,077.45		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment:	02/10/2019	
Date Inspected:	02/10/2019 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$36,000.00(est) less LTA Rebate: \$9,360.00(est) = Nett Value :\$26,640.00(est)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Mar 2020)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN5998T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H CORNER PANEL	Repair	506.00 F	*- FL
2	1		*FRONT R/H HEAD LAMP	Cracked	501.00 F	*501.00 FL
3	1		*FRONT R/H SIDE REFLECTOR	Cracked	230.00 F	*230.00 FL
4	1		*FRONT R/H SIGNAL LAMP	Cracked	266.00 F	*266.00 FL
5	1		*FRONT R/H BUMPER SIDE COVER	Cut	341.00 F	*341.00 FL
6	1		*FRONT R/H STEP PANEL GARNISH	Cracked	613.00 F	*496.00 FL
7	1		*FRONT R/H DOOR	Buckled	2,070.00 F	*2,070.00 FL
8	1		*FRONT R/H DOOR HINGE	Bent	122.00 F	*122.00 FL
9	1		*FRONT R/H DOOR LOWER OUTER GARNISH	Not Necessary	88.00 F	*- FL
10	1		*FRONT DOOR PILLAR	Repair	1,481.00 F	*- FL
11	1		*FRONT BUMPER	Bent	1,060.00 F	*1,060.00 FL
12	1		*FRONT GRILLE	Cracked	1,105.00 F	*618.00 FL
13	1		*FRONT GRILLE EMBLEM LOGO	Necessary	82.00 F	*82.00 FL
14	1		*FRONT CANTER LOGO	Necessary	78.00 F	*78.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,543.00	5,864.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,466.00
Total Parts (S\$)	8,543.00	4,398.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT R/H DOOR ,LOCK ,GLASS ,GEAR MOTOR & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT FRONT WINDSCREEN	New	120.00	0.00
3	GUM	New	50.00	0.00
4	TO CHECK WIRING	New	60.00	30.00
5	TUFF KOTE	New	150.00	50.00
6	TOWING FEE	New	100.00	0.00
7	PANEL BEATING	New	1,000.00	800.00
8	SPRAY PAINTING	New	1,000.00	900.00
Gross Labour Cost (\$\$)			2,760.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >