

ASS. REC. BY:

REF: CS/MSG/1602473/AG43

Special Instruction:

Survivor: Adnan

ASSIGNMENT (Office)

From (Person): Jang Tan at Jang

of MSG

Date/Time: 3.10.19 1234pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 98774

Insured:

SJT 7222G

at Workshop m/s

Hua Mung Spring

Tel:

6747806#

of

NO 1 Kaki Bukit Ave 6 #01-61

Policy No:

28883756 AMX

Claim No:

607380

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2.10.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3.10.19 539pm

Person Contacted:

Jang Yu

Vehicle:

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 98774 - X

SJT 7222G - X

8/10/19

Sent Preli to Insurance Co (Pending Estimate) Merimen

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 987H Yr Regn: 2016, DecType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 cc 1998Colour: White A/C: Insured / Std / NI / NASp. Reading: 62931 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jm6CW107160124958Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 03/10/19Survey held at Hua MengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MS16</u>
<u>20/1</u>	<u>LIS \$6800/- (Red \$11048-24, 61%)</u>
<u>20/1</u>	<u>Sent Preli to Insurance</u>
	MV:
	PV:
	Nett:

RECEIVED 20 JAN 2020

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 20/1/20 Typist

Report Format:

Lump Sum I.B.I. \$ 6800/-Days Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

240

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2019		03 Oct 2019 16:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:		ANTON RUSLI, ID: 572804131		
Main Claimant:		PEH CHEE LEONG, ID: S7917420C		
Vehicle Reg. No.:		SLJ9877H	Date of Loss:	02/10/2019 00:00 - :59 [33 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:		TP / 607380	Policy/Cover Note No.:	28883756QMX (Comprehensive) Coverage: 24/02/2019 - 23/02/2020
Vehicle Reg. No. (Insured):		SJT7222G	Policy No. (Claimant):	
			Excess:	
Repairer:		Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519		
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/10/2019]		
Adj Asp. Remarks:		on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Jing Yee @ 6746 5519.		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 20 Jan 2020

Preliminary Advice

Insured Vehicle No	: SJT7222G	Accident Date	: 02/10/2019
TP Vehicle No	: SLJ9877H	Assignment Date	: 03/10/2019
Make	: MAZDA 5	Est. Duration of Repair	: 6.00
Date of Inspection	: 03/10/2019		
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,848.24
Revised Amount	:S\$	6,800.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,800.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MSME19130718 / SNE Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 02/10/2019 17:53
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2019 17:53
Date Of Accident	02/10/2019 07:20
Exact Location Of Accident	FILTER LANE OF LOWER DELTA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ9877H
Insured/Policyholder	
Name Of Registered Owner	PEH CHEE LEONG
NRIC No	S7917420C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81803479
Alternative Phone No	OFFICE-81803479

Vehicle Particulars

Manufacturer	MAZDA
Model	5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00009154-01
Cover Note Number	

Driver

Name of Driver	PEH CHEE LEONG
NRIC No	S7917420C
Date Of Birth	17/05/1979
Occupation	OUTDOOR
Date Of Driving Pass	22/04/2005
Driving Experience	14 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81803479
Fax Number	
Contact Number	OFFICE-81803479
Email Address	NOEMAIL

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PEH CHEE LEONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLJ9877H

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan #2 Pg. 1

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary along Filter lane of Lower Delta Road on the
 03-10-2019 @ 0730 hours. I was waiting for main road to be
 clear before I can filter out. Suddenly, I heard a bang sound and
 felt an impact from my rear. Vehicle B was collided onto rear
 portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder):

Reporting Centre Personnel's Signature
 Name:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	420C
Vehicle Details	
Vehicle No.:	SLJ9877H
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP6EAT SUNROOF
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	PE10421204
Chassis No.:	JM6CW1071G0124958
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$19,597.00
Original Registration Date:	30 Dec 2016
First Registration Date:	30 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$19,597.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2026
PARF Rebate Amount:	\$14,697.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,109.00
COE Rebate Amount:	\$35,611.00
Total Rebate Amount:	\$50,308.00

The information contained herein is correct as at 10 Jan 2020

OK

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JMB6CW10716 012 4558

PEH CHEE LEONG

BLK 269B PUNGGOL FIELD

#15-191

S 822269

TP MS16

None

Date

:08.10.2019

Vehicle No

:SLJ 9877 H

Make/Model

:MAZDA 5

Accident date

:02.10.2019

No	DESCRIPTION	Qty	Amount (\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 69.9 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1886.5 <i>1637</i>
3	Rear tailgate hinges @ \$ 44.40	2	\$ 88.8 ✓
4	Rear tailgate shock absorber @ \$ 203.50 <i>2nd new</i>	2	\$ 407 X
5	Rear tailgate upper lock <i>Damaged</i>	1	\$ 273.9 ✓
6	Rear tailgate lower lock <i>new</i>	1	\$ 61.8 X
7	Rear tailgate reflector @ \$ 471.80 <i>new</i>	2	\$ 943.6 X
8	Rear tailgate centre emblem	1	\$ 50.8 ✓
9	Rear tailgate Mazda emblem <i>new</i>	1	\$ 52.1 ✓
10	Rear tailgate S emblem	1	\$ 41.8 ✓
11	Rear tailgate SkyActiv emblem	1	\$ 52.2 ✓
12	Rear tailgate handle <i>new</i>	1	\$ 142.8 X
13	Rear tailgate weather strip <i>cut</i>	1	\$ 204.5 ✓
14	Rear tailgate inner board <i>cracked</i>	1	\$ 420 ✓
15	Rear tailgate inner handle <i>new</i>	1	\$ 85 X
16	Rear tailgate camera <i>new</i>	1	\$ 800 X
17	Rear number plate <i>Dented</i>	1	\$ 50 30 (SN)
18	Rear number plate holder <i>Replaced</i>	1	\$ 50 30 (SN)
19	Rear number plate lamp @ \$ 66.60 <i>new</i>	2	\$ 133.2 X
20	Rear lamp @ \$ 693.90 <i>cracked</i>	2	\$ 1387.8 <i>971.20</i>
21	Rear end panel <i>Dented</i>	1	\$ 594 ✓
22	Rear end panel inner top garnish <i>Reformed</i>	1	\$ 168 ✓
23	Rear bumper <i>Replaced</i>	1	\$ 1107.7 ✓
24	Rear bumper side holder @ \$ 54.90 <i>new</i>	2	\$ 109.8 ✓
25	Rear bumper top Mazda 5 plate <i>Best</i>	1	\$ 250 ✓
26	Rear bumper side reflector @ \$ 60.90 <i>new</i>	2	\$ 121.8 X
27	Rear bumper reinforcement <i>Best</i>	1	\$ 294.8 ✓
28	Rear bumper bracket @ \$ 54.80 <i>new</i>	2	\$ 109.6 X
29	Rear bumper clips (1 set) <i>new</i>	1	\$ 60 30
30	Rear fender inner garnish @ \$ 556.40 <i>new</i>	2	\$ 1112.8 X
31	Rear fender inner shield @ \$ 49.50 <i>new</i>	2	\$ 99 X

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2019		03 Oct 2019 16:34 Edit Adj Rpt	S\$6,800.00 Edit Estimates	S\$6,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: ANTON RUSLI , ID: S72804131									
Main Claimant: PEH CHEE LEONG , ID: S7917420C									
Vehicle Reg. No.: SLJ9877H		Date of Loss: 02/10/2019 00:00 - :59 [33 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 607380		Policy/Cover Note No.: 28883756QMX (Comprehensive) Coverage: 24/02/2019 - 23/02/2020							
Vehicle Reg. No. (Insured): SJT7222G		Policy No. (Claimant):							
		Excess:							
Repairer: Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/11/2019]									
Adj Asg. Remarks: on WP: Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Jing Yee @ 6746 5519.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ9877H (607380)
[SJT7222G]
TP
PEH CHEE LEONG
Oct 2 2019 12:00AM
[ANTON RUSLI]
Hua Meng Spray Painting Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/01/20 13:55	Adjuster Immediate Advice	 Load HTML	☒
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/01/20 10:41	General View	 Load JPG	☒
2	20/01/20 10:41	General View	 Load JPG	☒
3	20/01/20 10:41	General View	 Load JPG	☒
4	20/01/20 10:41	General View	 Load JPG	☒
5	20/01/20 10:41	General View	 Load JPG	☒
6	20/01/20 10:41	General View	 Load JPG	☒
7	20/01/20 10:41	General View	 Load JPG	☒
8	20/01/20 10:41	General View	 Load JPG	☒
9	20/01/20 10:41	General View	 Load JPG	☒
10	20/01/20 10:41	General View	 Load JPG	☒
11	20/01/20 10:41	General View	 Load JPG	☒
12	20/01/20 10:41	General View	 Load JPG	☒
13	20/01/20 10:41	General View	 Load JPG	☒
14	20/01/20 10:41	General View	 Load JPG	☒
15	20/01/20 10:41	General View	 Load JPG	☒
16	20/01/20 10:41	General View	 Load JPG	☒
17	20/01/20 10:41	General View	 Load JPG	☒
18	20/01/20 10:41	General View	 Load JPG	☒
19	20/01/20 10:41	General View	 Load JPG	☒
20	20/01/20 10:41	General View	 Load JPG	☒
21	20/01/20 10:41	General View	 Load JPG	☒
22	20/01/20 10:41	General View	 Load JPG	☒
23	20/01/20 10:41	General View	 Load JPG	☒
24	20/01/20 10:41	General View	 Load JPG	☒
25	20/01/20 10:41	General View	 Load JPG	☒
26	20/01/20 10:41	General View	 Load JPG	☒
27	20/01/20 10:41	General View	 Load JPG	☒
28	20/01/20 10:41	General View	 Load JPG	☒
29	20/01/20 10:41	General View	 Load JPG	☒
30	20/01/20 10:41	General View	 Load JPG	☒
31	20/01/20 10:41	General View	 Load JPG	☒
32	20/01/20 10:41	General View	 Load JPG	☒
33	20/01/20 10:41	General View	 Load JPG	☒
34	20/01/20 10:41	General View	 Load JPG	☒
35	20/01/20 10:41	General View	 Load JPG	☒
36	20/01/20 10:41	General View	 Load JPG	☒
37	20/01/20 10:41	General View	 Load JPG	☒
38	20/01/20 10:41	General View	 Load JPG	☒
39	20/01/20 10:41	General View	 Load JPG	☒
40	20/01/20 10:42	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
42	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
43	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
44	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
45	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
46	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
47	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
48	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
49	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
50	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
51	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
52	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
53	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
54	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
55	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
56	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
57	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
58	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
59	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
60	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
61	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
62	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
63	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
64	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
65	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
66	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
67	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
68	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
69	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
70	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
71	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
72	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
73	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
74	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
75	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
76	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
77	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
78	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
79	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
80	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
81	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
82	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
83	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
84	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
85	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
86	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
87	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
88	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
89	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
90	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
91	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
92	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
93	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
94	20/01/20 10:42	Reinspection Photo	 Load JPG	☒
95	20/01/20 10:42	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	20/01/20 10:42	Reinspection Photo		Load JPG	☒
97	20/01/20 10:42	Reinspection Photo		Load JPG	☒
98	20/01/20 10:42	Reinspection Photo		Load JPG	☒
99	20/01/20 10:42	Reinspection Photo		Load JPG	☒
100	20/01/20 10:42	Reinspection Photo		Load JPG	☒
101	20/01/20 10:42	Reinspection Photo		Load JPG	☒
102	20/01/20 10:42	Reinspection Photo		Load JPG	☒
103	20/01/20 10:42	Reinspection Photo		Load JPG	☒
104	20/01/20 10:42	Reinspection Photo		Load JPG	☒
105	20/01/20 10:42	Reinspection Photo		Load JPG	☒
106	20/01/20 10:42	Reinspection Photo		Load JPG	☒
107	20/01/20 10:42	Reinspection Photo		Load JPG	☒
108	20/01/20 10:42	Reinspection Photo		Load JPG	☒
109	20/01/20 10:42	Reinspection Photo		Load JPG	☒
110	20/01/20 10:42	Reinspection Photo		Load JPG	☒
111	20/01/20 10:42	Reinspection Photo		Load JPG	☒
112	20/01/20 10:42	Reinspection Photo		Load JPG	☒
113	20/01/20 10:42	Reinspection Photo		Load JPG	☒
114	20/01/20 10:42	Reinspection Photo		Load JPG	☒
115	20/01/20 10:42	Reinspection Photo		Load JPG	☒
116	20/01/20 10:42	Reinspection Photo		Load JPG	☒
117	20/01/20 10:42	Reinspection Photo		Load JPG	☒
118	20/01/20 10:42	Reinspection Photo		Load JPG	☒
119	20/01/20 10:42	Reinspection Photo		Load JPG	☒
120	20/01/20 10:42	Reinspection Photo		Load JPG	☒
121	20/01/20 10:42	Reinspection Photo		Load JPG	☒
122	20/01/20 10:42	Reinspection Photo		Load JPG	☒
123	20/01/20 10:42	Reinspection Photo		Load JPG	☒
124	20/01/20 10:42	Reinspection Photo		Load JPG	☒
125	20/01/20 10:42	Reinspection Photo		Load JPG	☒
126	20/01/20 10:42	Reinspection Photo		Load JPG	☒
127	20/01/20 10:42	Reinspection Photo		Load JPG	☒
128	20/01/20 10:42	Reinspection Photo		Load JPG	☒
129	20/01/20 10:42	Reinspection Photo		Load JPG	☒
130	20/01/20 10:42	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/10/19 09:33	PR1		Load PDF	
2	03/10/19 09:46	Agree on SJE		Load PDF	
3	11/10/19 12:46	Status of Driving Licence		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017473/AGYF3Q2

Date: 23/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28883756QMX

Claimant Vehicle No : SLJ9877H

Insured Vehicle No : SJT7222G

Date of Loss: 02/10/2019

Nature of Claim: TP

Claim No: 607380

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ9877H

Make & Model: MAZDA 5, 2.0 5 DR WAGON (A)

Engine No: PE10421204

Reg. Date: 30/12/2016 (Man. Year: 2016)

Chassis No: JM6CW1071G0124958

Colour: White

Odometer: 62931 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,848.24	6,037.60	6,810.64	53.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,450.00	2,800.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,098.24	8,487.60	9,610.64	53.10
Approved Total (Overridden) (\$\$)		6,800.00		
Nett Amount (\$\$)	18,098.24	6,800.00	11,298.24	62.43

INSPECTION

Date of Assignment: 03/10/2019

Date Inspected: 03/10/2019 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Jan 2020)	
Parts:	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ9877H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	69.90 FL	*69.90 FL
2	1		*REAR TAILGATE	Dented	1,886.50 FL	*1,637.00 FL
3	2		*REAR TAILGATE HINGES	Not Necessary	88.80 FL	*- FL
4	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	407.00 FL	*- FL
5	1		*REAR TAILGATE UPPER LOCK	Damaged	273.90 FL	*273.90 FL
6	1		*REAR TAILGATE LOWER LOCK	Not Necessary	61.80 FL	*- FL
7	2		*REAR TAILGATE REFLECTOR	Not Necessary	943.60 FL	*- FL
8	1		*REAR TAILGATE CENTRE EMBLEM	Necessary	50.80 FL	*50.80 FL
9	1		*REAR TAILGATE MAZDA EMBLEM	Necessary	52.10 FL	*52.10 FL
10	1		*REAR TAILGATE 5 EMBLEM	Necessary	41.80 FL	*41.80 FL
11	1		*REAR TAILGATE SKYACTIV EMBLEM	Necessary	52.20 FL	*52.20 FL
12	1		*REAR TAILGATE HANDLE	Not Necessary	142.80 FL	*- FL
13	1		*REAR TAILGATE WEATHERSTRIP	Cut	204.50 FL	*204.50 FL
14	1		*REAR TAILGATE INNER BOARD	Cracked	420.00 FL	*420.00 FL
15	1		*REAR TAILGATE INNER HANDLE	Not Necessary	85.00 FL	*- FL
16	1		*REAR TAILGATE CAMERA	Not Necessary	800.00 FL	*- FL
17	1		*REAR NUMBER PLATE	Dented	40.00 FS	*30.00 FS
18	1		*REAR NUMBER PLATE HOLDER	Deformed	40.00 FS	*30.00 FS
19	2		*REAR NUMBER PLATE LAMP	Not Necessary	133.20 FL	*- FL
20	2		*REAR LAMP	Cracked	1,387.80 FL	*971.20 FL
21	1		*REAR END PANEL	Dented	594.00 FL	*594.00 FL
22	1		*REAR END PANEL INNER TOP GARNISH	Deformed	168.00 FL	*168.00 FL
23	1		*REAR BUMPER	Deformed	1,107.70 FL	*1,107.70 FL
24	2		*REAR BUMPER SIDE HOLDER	Necessary	109.80 FL	*109.80 FL
25	1		*REAR BUMPER TOP MAZDA 5 PLATE	Bent	250.00 FL	*250.00 FL
26	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	121.80 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT	Bent	294.80 FL	*294.80 FL
28	2		*REAR BUMPER BRACKET	Not Necessary	109.60 FL	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	66.00 FL	*30.00 FL
30	2		*REAR FENDER INNER GARNISH	Not Necessary	1,112.80 FL	*- FL
31	2		*REAR FENDER INNER SHIELD	Not Necessary	99.00 FL	*- FL
32	1		*REAR SPARE TYRE WELL	Repair	1,314.50 FL	*- FL
33	1		*REAR SPARE TYRE TOP BOARD	Deformed	407.00 FL	*407.00 FL
34	2		*REAR SPARE TYRE WELL INSULATION	Not Necessary	770.00 FL	*- FL
35	1		*REAR SPARE TYRE TOOL GARNISH	Deformed	404.80 FL	*404.80 FL
36	1		*REAR EXHAUST PIPE	Repair	1,278.50 FL	*- FL
37	1		*REAR EXHAUST PIPE CHROME	Bent	82.50 FL	*82.50 FL
38	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.30 FL	*- FL
39	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	418.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,935.80 7,482.00
 - List Item Discount on L Items 20.00/20.00% (\$\$) 3,087.56 1,444.40

Total Parts (\$\$) 12,848.24 6,037.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
2	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
3	REMOVE & REINSTALL REAR WINDSCREEN	New	200.00	120.00
4	REMOVE & REINSTALL EXHAUST PIPE	New	200.00	80.00
5	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	80.00
6	REMOVE & REINSTALL SENSOR	New	200.00	60.00
7	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	2,000.00	900.00
8	RESPRAY PAINTING	New	1,800.00	900.00
9	TUFF KOTE	New	150.00	60.00
10	REMOVE AND REINSTALL REAR CAMERA	New	100.00	60.00
11	REMOVE AND REINSTALL UPHOLSTERY	New	150.00	80.00
Gross Labour Cost (\$\$)			5,250.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >