

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4441J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LAMP ASSY,FOG,LH	SERVICEABLE	920.00	-
1	FRONT BUMPER COVER	CRACKED	499.90	499.90
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
2	FRONT BUMPER SIDE RETAINER @\$77.00	CRACKED (1 PC ONLY)	154.00	77.00
1	UNIT ASSY,HEADLAMP,LH (LED)	GRAZED	3,455.00	3,455.00
1	FRONT WHEEL RIM (LH)	SERVICEABLE	1,555.10	-
1	FRONT FENDER (LH)	BUCKLED	945.30	945.30
1	EMBLEM FENDER (LH)	NECESSARY	53.50	53.50
	LESS 25% DISCOUNT		-1,901.20	-1,263.18
			5,703.60	3,789.52
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	320.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	20.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,420.00	770.00
	GRAND TOTAL		7,123.60	4,559.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,650.00

Report Ref No. NS/INC19017480/K1tf3e2


KALVIN ANG WEI KUN

Automotive Assessor / Investigator


K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.