Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017505/UBA3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SJM1061E Insured Vehicle No: SMC8799G

Date of Loss: 30/09/2019 Nature of Claim: TP Claim No: 0624728768SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM1061E

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A) Engine No: 4A910123004

Reg. Date: 22/12/2008 (Man. Year: 2008) Chassis No: JMYSRCY2A9U003326

Colour: Black Odometer: 204823 km

Engine Capacity: 1499 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm
Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,641.60	980.10	661.50	40.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	700.00	500.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,841.60	1,680.10	1,161.50	40.87
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	2,841.60	1,150.00	1,691.60	59.53
+ GST 7.00/7.00% (S\$)	198.91	80.50	118.41	59.53
Nett Amount (S\$)	3,040.51	1,230.50	1,810.01	59.53
Global Sum Settleme		0.00		

INSPECTION

Date of Assignment: 04/10/2019

Date Inspected: 04/10/2019 Inspected At: Hock Wah Motor Workshop Pte Ltd

(Tampines)

Blk 900B, Tampines Street 93,, Tampines Industrial Park A, #01-204

Singapore 528840

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Dented/Deformed	831.00 FL	*831.00 FL
2	2		*RR BUMPER SIDE RETAINER LH/RH	Not Necessary	36.00 FL	*- FL
3	2		*RR BUMPER BRACKET LH/RH	Not Necessary	36.00 FL	*- FL
4	10		*RR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
5	1		*RR END PANEL	Repair	508.00 FL	*- FL
6	1		*RR END PANEL TOP GARNISH	Not Necessary	155.00 FL	*- FL
7	1		*REAR BUMPER BEAM	Bent	228.00 FL	*228.00 FL
8	1		*RR BOOTLID (NPA)	Repair	0.00 FS	*-FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	1,824.00	1,089.00
- List Item Discount on L Items 10.00/10.00% (S\$)				182.40	108.90	
				Total Parts (S\$)	1,641.60	980.10
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	New	600.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	400.00
	Gross Labour Cost (S\$)		1,200.00	700.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >