Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017506/UGA3Q2

Date: 05/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant FBF849M

Insured Vehicle No: SHC3383P Vehicle No:

Date of Loss: 19/09/2019 Nature of Claim: TP Claim No: MCT19090457

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBF849M Reg No:

Make & Model: SYM EXCEL II 150 A, 150cc (A) Engine No: VMVS5BD000455 Reg. Date: 25/01/2011 (Man. Year: 2010) Chassis No: RLGHA15DMAD000455

29911 km Colour: White Odometer:

Engine Capacity: 150 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-12 Rear Tyre Size: 120/70-12 Front Left Side: Rear Left Side: Nylon 6 mm Nylon 6 mm Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,477.00	1,788.30	688.70	27.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	515.00	745.00	59.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,737.00	2,303.30	1,433.70	38.36
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,737.00	1,800.00	1,937.00	51.83
+ GST 7.00/7.00% (S\$)	261.59	126.00	135.59	51.83
Nett Amount (S\$)	3,998.59	1,926.00	2,072.59	51.83
+ Loss of Use (5.0 x S\$	20.00/day) (S\$)	100.00		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	tt Liability (S\$)	2,033.45		

INSPECTION

Date of Assignment: 04/10/2019

Date Inspected: 04/10/2019 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4 Singapore 539410

Estimated Period of Repair: 5.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Apr 2020)

Parts: N/A SYM EXCEL II 150 A 150cc (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBF849M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER HANDLE	Scratched	15.00 F	*15.00 FL
2	19		*BALL BEARING	Necessary	133.00 F	*133.00 FL
3	1		*BALL STEEL (26 PCS)	Necessary	52.00 F	*52.00 FL
4	1		*BEARING STEERING CONE UPPER	Necessary	8.00 F	*8.00 FL
5	1		*BRACKET UNDER FORK	Bent / Twisted	179.00 F	*179.00 FL
6	1		*COWLING FRONT	Cut	121.00 F	*121.00 FL
7	1		*DUST SEAL	Torn	5.00 F	*5.00 FL
8	4		*FLANGE BOLT 8X50	Necessary	20.00 F	*20.00 FL
9	1		*FORK FRONT LH ASSY	Twisted	252.00 F	*252.00 FL
10	1		*FORK FRONT RH ASSY	Twisted	258.00 F	*258.00 FL
11	1		*FRONT COVER EMBLEM	Necessary	52.00 F	*52.00 FL
12	1		*FRONT UNDER SPOILER	Cracked	159.00 F	*159.00 FL
13	1		*FRONT WHEEL AXLE	Bent	10.00 F	*10.00 FL
14	1		*HEADLAMP ASSY	Cracked	449.00 F	*449.00 FL
15	1		*LEVER BRAKE RH	Cracked	27.00 F	*27.00 FL
16	1		*RACE BALL	Necessary	11.00 F	*11.00 FL
17	1		*RACE BALL	Necessary	11.00 F	*11.00 FL
18	1		*RACE BOTTOM CONE	Necessary	10.00 F	*10.00 FL
19	1		*REAR BODY COVER RH	Cracked	90.00 F	*90.00 FL
20	1		*SEAL DUST WASHER	Necessary	5.00 F	*5.00 FL
21	1		*SIDE COVER LOWER LH	Cut	42.00 F	*42.00 FL
22	1		*SIDE COVER LOWER RH	Cracked	42.00 F	*42.00 FL
23	12		*TAPPING SCREW 5X16	Necessary	36.00 F	*36.00 FL
24	1		*ALIGNMENT BODY	Not Necessary	490.00 F	*- FL
F=Fra	anchise	part. L=ListIte	emDisc.			
				Sub Total (S\$)	2,477.00	1,987.00
	- List Item Discount on L Items 0.00/10.00% (S\$)					198.70

Report was unsubmitted during this print-out.

Total Parts (S\$)

2,477.00

1,788.30

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUATED	New	1,176.00	450.00
2	SPRAY PAINT FRONT MUDGUARD	New	49.00	30.00
3	TRANSPORT CHARGES	New	35.00	35.00
	Gross Labour Cost (S\$)		1,260.00	515.00
	Report was unsubmitted durin	a this print-out.		

< END OF ESTIMATES >