

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19017511/UEA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100257338

Claimant
Vehicle No : YN2040B **Insured Vehicle No :** GBC1096C

Date of Loss: 01/07/2019 Nature of Claim: TP Claim No: 9908465758SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN2040B		
Make & Model:	HINO FD8JPKA, 7.7 D (M)	Engine No:	J08EUC11601
Reg. Date:	27/01/2011 (Man. Year: 2010)	Chassis No:	FD8JPK12162
Colour:	Blue	Odometer:	247136 km
Engine Capacity:	7684 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	8.25 R16	Rear Tyre Size:	8.25 R16 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	627.80	0.00	627.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	700.00	650.00	48.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,977.80	700.00	1,277.80	64.61
+ Loss of Use (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,452.00		

INSPECTION

Date of Assignment: 04/10/2019

Date Inspected: 04/10/2019 Inspected At:

Liu's Brother Auto Engineering
Workshop (kaki Bukit) (HQ)
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay
@ Kaki Bt Singapore 417883, Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR VIEW MIRROR (Scratched)	Not Consistent With The Impact	421.50 F	*- FL
2	1		*FRONT DOOR SIGNAL LAMP (Scratched)	Not Consistent With The Impact	206.30 F	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$\$)	627.80 0.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 0.00
					Total Parts (\$\$)	627.80 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	0.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS }	New	500.00	700.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED }	New	800.00	0.00
Gross Labour Cost (\$\$)			1,350.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >