



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS3/AWA19017531/Qqf3s2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 17-01-2020



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	YN 2539E	Veh. Inspected	GBB 5566S
Policy No.	AVCPSB0083481902	Coverage (\$)	0.00
Claim No.	NSV1900493/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	31/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE MANUAL	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTFHT02P000044575	Colour	SILVER
Odometer	395685	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	VANMAX	5 mm
L/H Front Tyre	195 R15C	VANMAX	5 mm
R/H Rear Tyre	195 R15C	VANMAX	5 mm
L/H Rear Tyre	195 R15C	VANMAX	5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	02/10/2019	Inspection Date	03/01/2020
Survey held at	13 KAKI BUKIT ROAD 4 #01-20		
Repairer	CARSMITH PRIVATE LIMITED		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------