

Our Ref: TP/17032-01/MY/2017

7 July 2017

Mohamed Saharuddin Bin Gani Blk 310B Anchorvale Road #04-11 Singapore 542310

Dear Sir

INSPECTION AND ASSESSMENT OF A DAMAGED VEHICLE FBK 3958 K ACCIDENT ON 14 NOV 2016

We thank you for your instruction on 17 Jan 2017, we have inspected the vehicle at RS Bikes Centre, No.1 Kaki Bukit Ave 6, #02-45 AutoBay@Kaki Bukit, Singapore 417883.

VEHICLE PARTICULAR

: FBK 3958 K

: Green Colour

Registration No.

: Kawasaki ZZR 1400

Speedo Reading

Make/Model

Original Regn. Date : 4 Aug 2015

Rim

: Sport

PARF Eligibility

: Yes

Engine Capacity Chassis Number : 1441cc

: JKBZXT40EFA016563

Engine Number

: ZXT40EE016871

VEHICLE CONDITION

General Condition

: In order

Body Work

: In order

Steering

: In order

Foot Brake Hand Brake : In order : In order

TYRE CONDITION

Front Tyre

: 7 mm

: 120/70 R17 Made by Size

: Metzeler

Rear Tyre

: 7 mm

Size

: 190/55 R17 Made by

: Metzeler

DESCRIPTION OF DAMAGES

The vehicle sustained a severe impact damages on the rear and front portion, resulting front fork twisted, handle bar bent, lamps cracked, wheel, radiator bent, chassis frame badly twisted and cracked and etc.

For detail of the damages, kindly refer to the thirteen (13) copies of photographs attached herein.

VEHICLE VALUE

We have checked the vehicle pre-accident average market value, as at the time of accident is about \$\$45,622.50 (Forty Five Thousand Six Hundred Twenty Two And Cents Fifty Only). COE rebate is about \$\$5206.00 (Five Thousand Two Hundred and Six Only).

Therefore, market value of S\$45622.50 less S\$5206.00 balance liability will be about S\$40,416.50 (Forty Thousand Four Hundred Sixteen and Cents Fifty Only).

COST OF REPAIR

There is no estimate submitted by the repairer. Due to the damages sustain, in our opinion, it is not economical to repair the damage vehicle and is to be treated as Total Loss.

IMPORTANT

As instructed we have not authorize the repair. Please note that this report rendered by us herein is solely on our independent opinion, which is base on the available documents and inspection of the vehicle.


WITHOUT PREJUDICE, we trust this report will be of assistance to you in dealing with this matter.


If you have any query or discrepancy of this report, kindly inform us within two (2) weeks, or the report will be treated as correct.

Qualified Appraiser


Disclaimer

The rate and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rate and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.





(0



(6

