

7/10 - 11/30
Video footage to LKK
admission
K1000

威利摩

WEI LEE MOTOR W

BLOCK 9 SIN MING INDUSTRIAL ESTATI
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemo
Business Regn No: 269436/00J

05, OCT 2019
China Taiping Insurance (S) PL
105 Cecil Street #18-00
The Octagon
S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: YK45275
Accident involving vehicle no: SKU2916D/YK45275
DOA: 02/10/2019 AT Marine Parade slip road twds ECP-Still Rd South

Dear officer incharge
Re: estimate cost of repair for vehicle no: SKU2916D
To supply—

Description	Qty		
Front bumper	1		
Bumper retainer	1		
Front fender	1		
Fender VVTI emblem	1		
Fender cowling	1	Sm	163.40 X
Cowling clip		m	42.00 X
Bumper clip		m	38.00 ✓
Bonnet	1	R	1,028.10 X
Headlamp w HID	1	Br	2,804.00 ✓
Headlamp top chrome	1	Red	137.70 ✓
Bumper foglamp	1	Sm	248.20 ✓
Foglamp cover	1	Sm	112.90 X
Parts			6,011.35
Parts less 25%			1,502.83
			4,508.52

To check/rectify headlamp wiring, check /focus headlamp
To remove damaged parts and attachments.
Repair/reshape dented areas
Replace/align above parts into position.
To spray paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

0•c
0•c
458•+
89•2+
761•45+
38•4+
38•+ ✓
2,804•+
137•7=
4,326•75*
4,326•75×
75•%
3,245•06*
0•c
20•+
500•+
600•=
1,120•00*
0•c
3,245•06+
1,120•=
8/11 4,365•06*
80.00 2cl
900.00 50cl
1,100.00 60cl

6,588.52