



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2003871  
INV Date 13/05/2020  
Reference CC6/CTI19017569/Kka3q2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SKU 2916D  
Insured Veh. YK 4527S  
Claim No. SNM19D204674  
Policy No. DMCVSN3077851800  
Accident Date 02/10/2019  
Inspection Date 07/10/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

CHINA TAIPING INSURANCE (S) PTE LTD	Ref : CC6/CTI19017569/Kka3q2
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909	Date : 13-05-2020
	Code : CTI



### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b> YK 4527S	<b>Veh. Inspected</b> SKU 2916D
<b>Policy No.</b> DMCVSN3077851800	<b>Coverage (\$)</b> 0.00
<b>Claim No.</b> SNM19D204674	<b>Excess (\$)</b> 0.00
<b>Assign From</b>	<b>Assign Date</b> 07/10/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b> TOYOTA ALTIS (A)	<b>c.c</b> 1598
<b>Engine No.</b> HIDDEN	<b>Year of Reg.</b> 2015
<b>Chassis No.</b> MR053REH104537558	<b>Colour</b> METALLIC BROWN
<b>Odometer</b> 80514	<b>Steering</b> IN ORDER
<b>Brakes</b> IN ORDER	<b>Modification</b> STANDARD ALLOY RIM
<b>General</b> GOOD	

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/55 R16	YOKOHAMA	7 mm
<b>L/H Front Tyre</b>	205/55 R16	YOKOHAMA	7 mm
<b>R/H Rear Tyre</b>	205/55 R16	YOKOHAMA	7 mm
<b>L/H Rear Tyre</b>	205/55 R16	YOKOHAMA	7 mm

### 4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
--	---------------------------------------------------------------------------------

### 5. General Information

<b>Accident Date</b> 02/10/2019	<b>Inspection Date</b> 07/10/2019
<b>Survey held at</b> WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.	

### 5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	----------------------------------------------------------------------------------------------------------------------------------------

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2916D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRACKED	458.00	458.00
1	BUMPER RETAINER	DISTORTED	89.20	89.20
1	FRONT FENDER	BENT	761.45	761.45
1	FENDER VVTI EMBLEM	NECESSARY	38.40	38.40
1	FENDER COWLING	SERVICEABLE	163.40	-
1	COWLING CLIP	NOT NECESSARY	42.00	-
1	BUMPER CLIP	NECESSARY	38.00	38.00
1	BONNET	TO REPAIR SEE LABOUR	1,028.10	-
1	HEADLAMP W HID	BROKEN	2,804.00	2,804.00
1	HEADLAMP TOP CHROME	DENTED	137.70	137.70
1	BUMPER FOGLAMP	SERVICEABLE	248.20	-
1	FOGLAMP COVER	SERVICEABLE	112.90	-
	LESS 25% DISCOUNT		-1,480.34	-1,081.69
			4,441.01	3,245.06
<b><u>LABOUR</u></b>				
	TO CHECK /RECTIFY HEADLAMP WIRING CHECK /FOCUS HEADLAMP.		80.00	20.00
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR /RESHAPE DENTED AREAS REPLACE /ALIGN ABOVE PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF BONNET . TO SPRAY PAINT.		900.00	500.00
			1,100.00	600.00
			2,080.00	1,120.00
<b>GRAND TOTAL</b>			<b>6,521.01</b>	<b>4,365.06</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,365.06</b>

Report Ref No. CC6/CT119017569/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payco Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKU 2916D

INSPECTION






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION  
MODEL GR17H-GEYGRZ  
ENGINE 1598 ml  
FRAME NO. M05335H104537568  
CLUB BIN PLAT 09149  
413 LAO1 Z55  
ISSUED KSTIS -09A JUN 15  
P.L.T. TOYOTA MOTOR THAILAND CO., LTD. MADE IN THAILAND



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKU 2916D

RE-INSPECTION

