



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18019596/R1vf3s2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 20-11-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 4769P	Veh. Inspected	YP 7769P	
Policy No.	D18MTHCVE000238	Coverage (\$)	0.00	
Claim No.	CMTD1803793	Excess (\$)	0.00	
Assign From	AGNES CHAN SHU HUI	Assign Date	05/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HINO GH8JRMA	c.c	7684	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GH8JRM10386	Colour	WHITE	
Odometer	110153	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	10.00 R20	GOODYTYRE	7 mm	
L/H Front Tyre	10.00 R20	GOODYTYRE	7 mm	
R/H Rear Tyre	10.00 R20 (D)	GOODYTYRE	7/7 mm	
L/H Rear Tyre	10.00 R20 (D)	GOODYTYRE	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2018	Inspection Date	29/10/2018	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		