Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017597/T1ES3Q2

**Date:** 09/07/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: SKU9893P Insured Vehicle No: SMM7140K

Date of Loss: 01/10/2019 Nature of Claim: TP Claim No: 3483932069SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKU9893P

 Make & Model:
 VOLVO V40, 2.0 T2 CROSS COUNTRY (A)
 Engine No:
 D4162T3307691

 Reg. Date:
 26/08/2015 (Man. Year: 2015)
 Chassis No:
 YV1MV845BF2251543

Colour: Grey Odometer: 55287 km

Engine Capacity: 1560 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,866.00	657.00	2,209.00	77.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	850.00	820.00	49.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,536.00	1,507.00	3,029.00	66.78
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	4,536.00	1,200.00	3,336.00	73.54
+ GST 7.00/7.00% (S\$)	317.52	84.00	233.52	73.54
Nett Amount (S\$)	4,853.52	1,284.00	3,569.52	73.54
+ Car Rental (5.0 x S\$10	500.00			
+ Doc/S	29.00			
Ne	1,813.00			
Global Sum S	1,800.00			

**INSPECTION** 

Date of Assignment: 07/10/2019

Date Inspected: 07/10/2019 Inspected At: Wah Hong Motors & Credit Pte Ltd

(HQ)

38 Toh Guan Road East, #01-57,

Enterprise Hub Singapore 608581 Adjuster Report Page 2 of 4

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	960.00 FL	*- FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	40.00 FL	*- FL
3	1		*FRONT BUMPER UNDERCOVER	Not Necessary	360.00 FL	*- FL
4	1		*FRONT INNERSHIELD RH	Not Necessary	190.00 FL	*- FL
5	1		*FRONT FENDER RH	Bent	730.00 FL	*730.00 FL
6	1		*HEADLAMP RH	Not Necessary	860.00 FL	*- FL
7	1		*REAR BUMPER CLIPS	Not Necessary	40.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	3,180.00	730.00
	- List Item Discount on L Items 10.00/10.00% (S\$)			314.00	73.00	
				Total Parts (S\$)_	2,866.00	657.00
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	800.00	400.00				
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	600.00	400.00				
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	120.00	30.00				
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	20.00				
	Gross Labour	r Cost (S\$)	1,670.00	850.00				
	Report was unsubmitted durin	g this print-out.						

< END OF ESTIMATES >